



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest November 24, 2014

RECALL Subject : TPMS may not Locate Sensors

Report Receipt Date: OCT 03, 2014

NHTSA Campaign Number: 14V618000

Component(s): TIRES

Potential Number of Units Affected: 28,037

Vehicle Make	Model	Model Year(s)
• LAND ROVER	LR4	2013-2014
• LAND ROVER	RANGE ROVER	2014
• LAND ROVER	RANGE ROVER SPORT	2014

Manufacturer: Jaguar Land Rover North America, LLC

SUMMARY:

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain model year 2014 Range Rover and Range Rover Sport and 2013-2014 LR4 vehicles manufactured September 16, 2013, to June 30, 2014. In the affected vehicles, the Tire Pressure Monitoring System (TPMS) may fail to learn the locations of the individual sensors while the vehicle is being driven. As a result, the low tire pressure warning light will illuminate, despite the the tire pressures being within specification. Should one of the tires subsequently lose air pressure, the driver would not be notified of the change in air pressure.

CONSEQUENCE:

If the TPMS light illuminates because the sensors cannot be located, it could mask an actual low tire pressure condition, possibly resulting in tire failure, increasing the risk of a crash.

REMEDY:

Land Rover will notify owners, and dealers will update the Body Control Module (BCM) software, free of charge. The recall began on November 6, 2014.

RECALL Subject : Inconsistent Passenger Airbag Deployment/FMVSS 208

Report Receipt Date: OCT 06, 2014
NHTSA Campaign Number: 14V624000
Component(s): AIR BAGS
Potential Number of Units Affected: 1,022

Vehicle Make	Model	Model Year(s)
• CADILLAC	ESCALADE	2015
• CADILLAC	ESCALADE ESV	2015

Manufacturer: General Motors LLC

SUMMARY:

General Motors LLC (GM) is recalling certain model year 2015 Cadillac Escalade and Escalade ESV vehicles. The passenger side instrument panel top cover on the affected vehicles may have been manufactured using an incorrect spacer fabric, causing a reduction of adhesion between the spacer fabric and the vinyl show surface. This reduced adhesion may result in inconsistent passenger air bag deployment. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard No. 208, "Occupant Crash Protection."

CONSEQUENCE:

Inconsistent air bag deployment increases the risk of personal injury in the event of a crash necessitating air deployment.

REMEDY:

GM will notify owners, and dealers will replace the instrument panel top cover, free of charge. The manufacturer has not yet provided a notification schedule.

RECALL Subject : Loss of Brake Assist/Vacuum Pump Lubrication

Report Receipt Date: OCT 07, 2014
NHTSA Campaign Number: 14V627000
Component(s): SERVICE BRAKES, HYDRAULIC
Potential Number of Units Affected: 8,988

Vehicle Make	Model	Model Year(s)
• BMW	320I	2012-2014
• BMW	328I	2012-2014
• BMW	428I	2014
• BMW	528I	2012-2013
• BMW	X1	2013-2014
• BMW	X3	2013-2014
• BMW	Z4	2012-2014

Manufacturer: BMW of North America, LLC

SUMMARY:

BMW of North America LLC (BMW) is recalling certain model year 2014 BMW 328i xDrive Sports Wagon, 2012-2014 BMW 320i Sedan, 328i Sedan, 320i xDrive Sedan, 328i xDrive Sedan, 2012-2013 BMW 528i Sedan, 528i xDrive Sedan, 2013-2014 BMW X1 sDrive28i, X1 xDrive28i Sports Activity Vehicle, 2013-2014 BMW X3 xDrive28i Sports Activity Vehicle, 2012-2014 BMW Z4 sDrive28i Roadster, and 2014 BMW 428i Coupe, and 428i xDrive Coupe. Due to insufficient lubrication, the vacuum pump that supplies brake power assistance may fail. Note: This recall is an expansion of recall 13V-454.

CONSEQUENCE:

A failure of the brake vacuum pump results in a reduction in braking power that could increase the risk of a crash.

REMEDY:

BMW will notify owners, and dealers will install a locking ring in the camshaft to retain the camshaft seal disk in the proper location, free of charge. The recall is expected to begin in late November 2014.

RECALL Subject : Fuel Leak at Fuel Pressure Sensor/Fuel Pipe

Report Receipt Date: OCT 15, 2014

NHTSA Campaign Number: 14V647000

Component(s): FUEL SYSTEM, GASOLINE

Potential Number of Units Affected: 422,509

Vehicle Make	Model	Model Year(s)
• LEXUS	GS 350	2007-2011
• LEXUS	GS 450H	2007-2011
• LEXUS	GS300	2006
• LEXUS	GS460	2008-2011
• LEXUS	IS 250	2006-2010
• LEXUS	IS 250C	2010
• LEXUS	IS 350	2006-2011
• LEXUS	IS 350C	2010
• LEXUS	IS F	2008-2010
• LEXUS	LS460	2007-2010
• LEXUS	LS460L	2007-2010
• LEXUS	LS600H	2010
• LEXUS	LS600HL	2008-2010

Manufacturer: Toyota Motor Engineering & Manufacturing

SUMMARY:

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain model year 2007-2010 Lexus LS vehicles manufactured May 9, 2006, to July 20, 2010, 2006-2011 Lexus GS vehicles manufactured January 6, 2005, to September 10, 2010, and 2006-2011 Lexus IS vehicles manufactured August 30, 2005, to September 10, 2010. Due to anti-corrosion plating remnants, fuel may leak from where the fuel pressure sensor is attached to the fuel delivery pipe.

CONSEQUENCE:

A fuel leak in the presence of an ignition source increases the risk of a fire.

REMEDY:

Toyota will notify owners, and dealers will clean and reseal the fuel pressure sensor mounting area, free of charge. The recall is expected to begin in December 2014.