

NHTSA Recalls of Interest May 27, 2019

Steering Wheel may Damage Air Bag Wiring

NHTSA Campaign Number: 19V383000

Manufacturer Honda (American Honda Motor Co.)

Components STEERING, AIR BAGS, COMMUNICATIONS

Potential Number of Units Affected 118,598

Summary

Honda (American Honda Motor Co.) is recalling certain 2019 CR-V vehicles. The metal core of the steering wheel may have burrs which can damage the harnesses routed within, potentially disabling the driver's air bag or causing it to deploy without warning.

Remedy

Honda will notify owners, and dealers will install a protective cover on the steering wheel core and replace clockspring and the harnesses within, free of charge. The recall is expected to begin July 8, 2019. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is R4S.

Vehicle

MAKE MODEL YEAR

HONDA CR-V 2019

Improperly Installed Passenger Air Bag Inflator

NHTSA Campaign Number: 19V378000

Manufacturer Honda (American Honda Motor Co.)

Components AIR BAGS

Potential Number of Units Affected 19,086

Summary

Honda (American Honda Motor Co.) is recalling certain 2009-2014 Acura TSX, 2011-2013 TSX Sport Wagon, and 2010-2012 ZDX and 2008-2012 Honda Accord, 2010-2011 Accord Crosstour, 2006-2011 Civic, Civic Hybrid and Civic NGV, 2012-2014 Crosstour, 2007-2011 CR-V, 2009-2013 Fit, 2010-2013 Insight, and 2009-2015 Pilot vehicles. The front passenger air bag inflator may have been installed incorrectly during replacement.

Remedy

Honda will notify owners, and dealers will inspect the inflator installation and, if necessary, replace the passenger frontal air bag module assembly, free of charge. The recall is expected to begin June 28, 2019. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are M4O, P4R, T4O, and W4P.

Vehicles

MAKE	MODEL	YEAR
ACURA	TSX	2009-2014
ACURA	TSX SPORTSWAGON	2011-2013
ACURA	ZDX	2010-2012
HONDA	ACCORD	2008-2012
HONDA	ACCORD CROSSTOUR	2010-2011
HONDA	CIVIC	2006-2011
HONDA	CIVIC GX	2006-2011
HONDA	CIVIC HYBRID	2006-2011
HONDA	CR-V	2007-2011
HONDA	CROSSTOUR	2012-2014
HONDA	FIT	2009-2013
HONDA	INSIGHT	2010-2013
HONDA	PILOT	2009-2015

Incorrectly Wired Seat Belt Harness Connector

NHTSA Campaign Number: 19V326000

Manufacturer Jaguar Land Rover North America, LLC

Components ELECTRICAL SYSTEM, SEAT BELTS, AIR BAGS

Potential Number of Units Affected 7,060

Summary

Jaguar Land Rover North America, LLC (Jaguar Land Rover) is recalling certain 2014-2015 Jaguar F-TYPE vehicles previously remedied under Recall 14V-714. The seatbelt harness connector which connects the Seatbelt Tension Sensor (STS) to the Occupant Classification Sensor Control Module (OCSCM) may not have been correctly wired. As a result, the Restraint Control Module (RCM) may not accurately detect if an adult or child is occupying the seat.

Remedy

Jaguar will notify owners, and dealers will inspect the seat belt assembly and repair the seatbelt tension sensor harness as necessary, free of charge. The recall is expected to begin June 21, 2019. Owners may contact Jaguar

Vehicle

MAKE MODEL YEAR

JAGUAR F-TYPE 2014-2015

Air Bags May Not Deploy Properly

NHTSA Campaign Number: 19V319000

Manufacturer Toyota Motor Engineering & Manufacturing

Components ELECTRICAL SYSTEM, AIR BAGS

Potential Number of Units Affected 43,221

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2015-2017 Yaris vehicles. The wire harnesses for the side air bag sensors located within the front doors may crack and corrode, possibly causing the non-deployment or improper deployment of the front seat side air bags and the curtain shield air bags.

Remedy

Toyota will notify owners, and dealers will replace the wire harness assembly in the front doors, as necessary, free of charge. The recall is expected to begin June 10, 2019. Owners may contact Toyota customer service at 1-888-270-9371. Toyota's number for this recall is K1F/K0F.

Vehicle

MAKE MODEL YEAR

TOYOTA YARIS 2015-2017

Door Spot Welds Affecting Air Bag Deployment

NHTSA Campaign Number: 19V318000

Manufacturer Toyota Motor Engineering & Manufacturing

Components AIR BAGS

Potential Number of Units Affected 274

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2019 Sienna vehicles. The passenger front door may have incorrect welds inside, possibly affecting the air bag sensor readings for the passenger side front seat and curtain shield air bags.

Remedy

Toyota will notify owners, and dealers will replace the passenger side front door sub assembly with a new one, free of charge. The recall is expected to begin June 10, 2019. Owners may contact Toyota customer service at 1-888-270-9371. Toyota's number for this recall is K1G/K0G.

Vehicle

MAKE MODEL YEAR

TOYOTA SIENNA 2019

Driver's Door May Open During Side Impact Crash

NHTSA Campaign Number: 19V311000

Manufacturer Hyundai Motor America

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 12,438

Summary

Hyundai Motor America (Hyundai) is recalling certain 2019 Veloster vehicles. In certain side impact crashes, the driver's door latch housing and locking cable can become damaged, allowing the driver's side door to open.

Remedy

Hyundai will notify owners, and dealers will replace the driver's side door latch assembly and lower channel, free of charge. The recall is expected to begin June 14, 2019. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 183.

Vehicle

MAKE MODEL YEAR

HYUNDAI VELOSTER 2019

A/C Control Unit May Short Circuit and Cause Fire

NHTSA Campaign Number: 19V322000

Manufacturer Porsche Cars North America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 33,206

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2010-2016 Panamera 4S and Panamera S, 2011-2016 Panamera, Panamera 4 and Panamera Turbo, 2012-2016 Panamera Turbo S and Panamera S E-Hybrid, 2013-2016 Panamera GTS, 2013 Panamera Platinum Edition and Panamera 4 Platinum Edition, 2014-2016 Panamera 4S Executive, Panamera Turbo Executive and Panamera Turbo S Executive, 2015 Panamera Diesel and 2016 Panamera 4 Edition, Panamera Edition and Panamera Turbo S Exclusive Series vehicles. Water may enter the A/C blower control unit, causing an electrical short circuit.

Remedy

Porsche will notify owners, and dealers will add a relay harness to the A/C blower control unit and reseal it to prevent water from leaking in, free of charge. The recall is expected to begin June 23, 2019. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AKA7. Note: Porsche recommends that owners park their vehicle outdoors until the recall remedy has been performed.

Vehicles

MAKE	MAKE MODEL		YEAR	
PORSCHE	PANAMERA		2011-2016	
PORSCHE	PANAMERA	4	2011-2016	
PORSCHE	PANAMERA	4S	2010-2016	
PORSCHE	PANAMERA	GTS	2013-2016	
PORSCHE	PANAMERA	S	2010-2016	
PORSCHE	PANAMERA	S E-HYBRID	2012-2016	
PORSCHE	PANAMERA	TURBO	2011-2016	
PORSCHE	PANAMERA	TURBO S	2012-2016	

Loss of Power Steering Assist Due to Corrosion

NHTSA Campaign Number: 19V290000

Manufacturer Daimler Vans USA, LLC

Components STEERING

Potential Number of Units Affected 9.471

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2016-2017 Metris vehicles sold, or ever registered in Connecticut, Delaware, Illinois, Indiana, Iowa, Kentucky, Maine, Maryland, Massachusetts, Michigan, Minnesota, Missouri, New Hampshire, New Jersey, New York, Ohio, Pennsylvania, Rhode Island, Vermont, Virginia, Washington DC, West Virginia and Wisconsin. The aluminum bolts that attach the power steering gear assist motor to the gear housing may corrode and fracture causing a reduction or complete loss of power steering assist.

Remedy

DVUSA will notify owners, and dealers will replace the aluminum bolts with steels bolts, free of charge. The recall is expected to begin May 27, 2019. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS2SCHRALU.

Vehicle

MAKE MODEL YEAR

MERCEDES BENZ METRIS 2016-2017