



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

April 17, 2023

Insufficiently Welded Second-Row Seat Frame

An improperly welded second-row seat frame may not adequately secure occupants during sudden braking or a crash, increasing the risk of injury.

NHTSA Campaign Number: 23V252000

Manufacturer Jaguar Land Rover North America, LLC

Components SEATS

Potential Number of Units Affected 500

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2022-2023 Land Rover Range Rover vehicles equipped with seven seats. The second-row seat frame may have been insufficiently welded.

Remedy

Dealers will inspect and replace the second-row seat frame, as necessary, free of charge. Owner notification letters are expected to be mailed June 2, 2023. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N783.

Vehicle

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2022-2023

Lock Tab Missing from Head Restraint/FMVSS 202

A head restraint without a locking tab may not properly restrain an occupant during a crash, increasing the risk of injury.

NHTSA Campaign Number: 23V253000

Manufacturer BMW of North America, LLC

Components SEATS

Potential Number of Units Affected 235

Summary

BMW of North America, LLC (BMW) is recalling certain 2023 X5 sDrive40i, X5 xDrive40i, X5 M50i, X5 M and X5 xDrive45e vehicles. The head restraints for the second-row outboard seats may have been improperly manufactured without locking tabs in the guide sleeves. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 202, "Head Restraints."

Remedy

Dealers will inspect and replace the second-row outboard seat head restraint guide sleeves, as necessary, free of charge. Owner notification letters are expected to be mailed May 29, 2023. Owners may contact BMW customer service at 1-800-525-7417.

Vehicle

MAKE	MODEL	YEAR
BMW	X5	2023

Adaptive Cruise Control May Cause Sudden Braking

Overly aggressive braking can result in the rear axle skidding, the brakes locking up, and/or a loss of vehicle control, increasing the risk of a crash.

NHTSA Campaign Number: 23V255000

Manufacturer Volvo Trucks North America

Components EQUIPMENT ADAPTIVE/MOBILITY, FORWARD COLLISION AVOIDANCE

Potential Number of Units Affected 236

Summary

Volvo Trucks North America (Volvo Trucks) is recalling certain 2020-2023 VNR Electric vehicles equipped with Adaptive Cruise Control (ACC). When the adaptive cruise control braking activates under light load conditions, it can trigger an aggressive braking response.

Remedy

Dealers will secure wiring and remove radar antennas and brackets from the vehicle. The anti-lock braking system will be reprogrammed to disable adaptive cruise control. Owner notification letters are expected to be mailed June 2, 2023. Owners may contact Volvo Trucks' customer service at 1-800-528-6586. Volvo Trucks' number for this recall is RVXX2303.

Vehicle

MAKE	MODEL	YEAR
VOLVO	VNR	2020-202

Loss of Steering from Missing Tie Rod Fastener

A detached steering arm can result in a sudden loss of steering control, increasing the risk of a crash.

NHTSA Campaign Number: 23V259000

Manufacturer Daimler Trucks North America, LLC

Components STEERING

Potential Number of Units Affected 48

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2023-2024 Thomas Built SAF-T-LINER C2, SAF-T-LINER Jouley, 2023 SAF-T-LINER EFX Chassis, HDX Chassis, and SAF-T-LINER MVP-EF school buses. The tie rod may be missing a fastener, allowing the steer arm to detach.

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed June 4, 2023. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL970.

Vehicles

MAKE	MODEL	YEAR
THOMAS BUILT BUSES	HDX	2023
THOMAS BUILT BUSES	SAF-T-LINER C2	2023-2024
THOMAS BUILT BUSES	SAF-T-LINER C2 JOLEY	2023-2024

MAKE	MODEL	YEAR
THOMAS BUILT BUSES	SAF-T-LINER EFX	2023
THOMAS BUILT BUSES	SAF-T-LINER MVP-EF	2023

Loss of Steering from Missing Tie Rod Fastener

A detached steering arm can result in a sudden loss of steering control, increasing the risk of a crash.

NHTSA Campaign Number: 23V238000

Manufacturer Daimler Trucks North America, LLC

Components STEERING

Potential Number of Units Affected 306

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2022 FCCC MT45G, S2C 106, 2022-2023 FCCC MT50E, MT55, S2RV Chassis, 2023 Freightliner 108 SD, 114 SD, Cascadia, M2 106, FCCC XCM Chassis, XCR Chassis, XCS Chassis, Thomas Built Bus SAF-T-LINER C2, and Western Star 4700, 47X, 4900, 49X commercial buses. The tie rod may be missing a fastener, allowing the steer arm to detach.

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed June 4, 2023. Owner notification letters were mailed June 6, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL970.

Vehicles

MAKE	MODEL	YEAR
FCCC	MT45G	2022
FCCC	MT50E	2022-2023
FCCC	MT55	2022-2023

MAKE	MODEL	YEAR
FCCC	S2C	2022
FCCC	S2RV	2022-2023
FCCC	XCM	2023
FCCC	XCR	2023
FCCC	XCS	2023
FREIGHTLINER	108SD	2023
FREIGHTLINER	114SD	2023
FREIGHTLINER	CASCADIA	2023
FREIGHTLINER	M2	2023
THOMAS BUILT BUSES	SAF-T-LINER C2	2023
WESTERN STAR	4700	2023
WESTERN STAR	47X	2023
WESTERN STAR	4900	2023
WESTERN STAR	49X	2023

ABS Module May Fail

An ABS system that fails increases the risk of a crash.

NHTSA Campaign Number: 23V243000

Manufacturer New Flyer of America, Inc.

Components SERVICE BRAKES, AIR

Potential Number of Units Affected 30

Summary

New Flyer of America, Inc. (New Flyer) is recalling certain 2023 XD60 and XDE60 60' articulated transit buses. The anti-lock brake system (ABS) module may lose power during hard braking, causing the ABS system to fail.

Remedy

New Flyer will update the ABS software and correct the wiring, free of charge. Owner notification letters are expected to be mailed May 1, 2023. Owners may contact New Flyer customer service at 1-204-224-6706.

Vehicles

MAKE	MODEL	YEAR
NEW FLYER	XD60	2023
NEW FLYER	XDE60	2023

Rearview Image May Not Display/FMVSS 111

A rearview image that does not display while in reverse decreases the driver's visibility, increasing the risk of injury or crash.

NHTSA Campaign Number: 23V244000

Manufacturer Tesla, Inc.

Components BACK OVER PREVENTION

Potential Number of Units Affected 38

Summary

Tesla, Inc. (Tesla) is recalling certain 2023 Model X vehicles equipped with a full self-driving computer 4.0 and running software release version 2023.2.200. Weak camera signal strength may prevent the rearview image from displaying. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Tesla has released an over-the-air (OTA) software update, free of charge. All affected vehicles have been remedied. Owners may contact Tesla customer service at 1-877-798-3752.

Vehicle

MAKE	MODEL	YEAR
TESLA	MODEL X	2023

Parking Brake Valve Module May Cause Rollaway

A parking brake that is not engaged as expected when the driver releases the brakes may allow the vehicle to rollaway, increasing the risk of crash.

NHTSA Campaign Number: 23V249000

Manufacturer Nikola Corporation

Components PARKING BRAKE

Potential Number of Units Affected 364

Summary

Nikola Corporation (Nikola) is recalling certain 2022-2024 TRE BEV trucks. The electronic parking brake valve module (PVM) may fail to move into the park position when the parking brake is activated.

Remedy

Dealers will replace the PVM, free of charge. Owner notification letters are expected to be mailed May 1, 2023. Owners may contact Nikola customer service at 1-630-808-4531. Nikola's number for this recall is 23VDC0301.

Vehicle

MAKE	MODEL	YEAR
NIKOLA	TRE BEV	2022-2024

Damaged Tire Bead May Cause Loss of Air Pressure

A damaged tire may experience a sudden loss of air pressure, increasing the risk of a crash.

NHTSA Campaign Number: 23V258000

Manufacturer Subaru of America, Inc.

Components TIRES

Potential Number of Units Affected 4,409

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2023 Ascent vehicles equipped with 20-inch wheels. The internal tire bead may have been damaged during the wheel mounting process.

Remedy

Dealers will replace all four tires, free of charge. Owner notification letters are expected to be mailed June 6, 2023. Owners may contact Subaru's customer service at 1-844-373-6614. Subaru's number for this recall is WRH-23.

Vehicle

MAKE	MODEL	YEAR
SUBARU	ASCENT	2023

Rear HVAC Electrical Circuit May Overheat

An overheated electrical circuit increases the risk of a fire.

NHTSA Campaign Number: 23V247000

Manufacturer General Motors, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 149,028

Summary

General Motors, LLC (GM) is recalling certain 2003-2023 Chevrolet Express Cutaway and GMC Savana Cutaway incomplete vehicles equipped with wiring for an optional rear heating, ventilation, and air-conditioning (HVAC) system. When the HVAC blower motor circuit is left unused with exposed connectors and wiring, the circuit can corrode and overheat.

Remedy

Dealers will properly seal the rear HVAC blower motor circuits at the left side B-pillar, free of charge. Owner notification letters are expected to be mailed May 22, 2023. Owners may contact Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-800-462-8782. GMC's number for this recall is N222386050.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	EXPRESS CUTAWAY VAN	2003-2023
GMC	SAVANA	2003-2023

HVAC Blower Motor Circuit May Overheat

An overheated electrical circuit can increase the risk of a fire.

NHTSA Campaign Number: 23V248000

Manufacturer Navistar, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 44,887

Summary

Navistar, Inc. (Navistar) is recalling certain 2016-2020 International DuraStar, WorkStar, 2017-2018 International TranStar, 2018 International ProStar, 2020 International HV, MV, and 2018 IC Bus HC Commercial buses. The heating, ventilation, and air-conditioning (HVAC) blower motor circuit may have an insufficient wiring terminal that can overheat.

Remedy

Dealers will replace the HVAC blower motor load circuit wiring terminal, free of charge. Owner notification letters are expected to be mailed June 5, 2023. Owners may contact Navistar's customer service at 1-800-448-7825. Navistar's number for this recall is 23510.

Vehicles

MAKE	MODEL	YEAR
IC BUS	HC	2018
INTERNATIONAL	DURASTAR	2016-2020
INTERNATIONAL	HV	2020
INTERNATIONAL	MV	2020

MAKE	MODEL	YEAR
INTERNATIONAL	PROSTAR	2018
INTERNATIONAL	TRANSTAR	2017-2018
INTERNATIONAL	WORKSTAR	2016-2020

Incorrect Rear Taillights Installed/FMVSS 108

Taillights and brake lights that do not illuminate correctly can reduce vehicle visibility or cause confusion for other drivers, increasing the risk of a crash.

NHTSA Campaign Number: 23V251000

Manufacturer Jaguar Land Rover North America, LLC

Components EXTERIOR LIGHTING

Potential Number of Units Affected 5

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2023 Land Rover Range Rover Sport vehicles. The vehicles are equipped with incorrect rear taillights that do not illuminate correctly. In addition, the brake lights may not illuminate correctly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Dealers will inspect and replace the rear taillights, as necessary, free of charge. Owner notification letters are expected to be mailed June 2, 2023. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N782.

Vehicle

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER SPORT	2023
