



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

April 24, 2023

Second-Row Seat Belts May Malfunction

A pinched seat belt may not function properly, increasing the risk of injury during a crash.

NHTSA Campaign Number: 23V260000

Manufacturer BMW of North America, LLC

Components SEAT BELTS

Potential Number of Units Affected 1,465

Summary

BMW of North America, LLC (BMW) is recalling certain 2023 X1 xDrive28i, X1 M35i vehicles. On the second-row outboard seats, the seat belts may have been pinched by an interior trim panel during vehicle assembly.

Remedy

Dealers will inspect and adjust the interior trim panel, as necessary, free of charge. Owner notification letters are expected to be mailed June 2, 2023. Owners may contact BMW customer service at 1-800-525-7417.

Vehicle

MAKE

MODEL

YEAR

BMW

X1

2023

Missing Air Bag Sensors

Air bags that do not deploy as intended increase the risk of injury in a crash.

NHTSA Campaign Number: 23V264000

Manufacturer Chrysler (FCA US, LLC)

Components AIR BAGS

Potential Number of Units Affected 37

Summary

Chrysler (FCA US, LLC) is recalling certain 2022 Ram 1500 vehicles. The B-pillar impact sensors may be missing, which can result in delayed air bag deployment or non-deployment.

Remedy

Dealers will inspect and, if necessary, install the B-pillar impact sensors, free of charge. Owner notification letters are expected to be mailed June 2, 2023. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 33A.

Vehicle

MAKE	MODEL	YEAR
RAM	1500	2022

Incorrect PCM Software May Cause Engine Stall

An engine stall can increase the risk of a crash.

NHTSA Campaign Number: 23V265000

Manufacturer Chrysler (FCA US, LLC)

Components POWER TRAIN

Potential Number of Units Affected 131,700

Summary

Chrysler (FCA US, LLC) is recalling certain 2021 Ram 1500 vehicles equipped with 5.7L eTorque engines. The powertrain control module software may cause an incorrect fuel mixture condition in the engine, and result in an engine stall.

Remedy

Dealers will update the Powertrain Control Module calibration software, free of charge. Owner notification letters are expected to be mailed June 2, 2023. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 37A.

Vehicle

MAKE	MODEL	YEAR
RAM	1500	2021

Corrosion on Remote Control Circuit Board

A winch that operates unintentionally increases the risk of injury.

NHTSA Campaign Number: 23V267000

Manufacturer Field Van, Inc

Components ELECTRICAL SYSTEM, EQUIPMENT

Potential Number of Units Affected 20

Summary

Field Van, Inc (Field Van) is recalling certain 2019-2022 Sprinter vehicles, equipped with a Warn Winch and a wireless handheld remote. Water may enter the handheld remote control for the winch and cause circuit board corrosion, which can allow the winch to operate unintentionally.

Remedy

Field Van will work with Warn Industries, Inc. to provide owners instructions on how to inspect the remote for corrosion and disable the wireless function by removing the battery pack from the remote. If corrosion or water intrusion is found when removing the battery pack owners should stop using the remote and contact WARN customer service for a replacement remote, free of charge. Once new parts are available, WARN will make a replacement water resistant remote available, free of charge. Owner notification letters are expected to be mailed May 12, 2023. Owners may contact Field Van customer service at 1-559-233-8267.

Vehicle

MAKE	MODEL	YEAR
FIELD VAN	SPRINTER	2019-2022

Brake Pressure Switch May Short and Cause Fire

An electrical short in the brake pressure switch can overheat the circuit and increase the risk of a fire while driving or parked.

NHTSA Campaign Number: 23V266000

Manufacturer General Motors, LLC

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 40,428

Summary

General Motors, LLC (GM) is recalling certain 2019-2023 Chevrolet 4500HD, 5500HD, and 6500HD Medium-Duty trucks. The brake pressure sensor assembly may leak brake fluid into the brake pressure switch and cause an electrical short-circuit.

Remedy

Owners are advised to park outside and away from structures until the recall repair is complete. Dealers will replace the master cylinder pressure sensor and inspect the wire harness, replacing it, if necessary, free of charge. Interim letters notifying owners of the safety risk are expected to be mailed May 29, 2023. Second letters will be mailed once the remedy is available. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N222375270.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	4500HD	2019-2023
CHEVROLET	5500HD	2019-2023
CHEVROLET	6500HD	2019-2023

Driver's Powered Seat May Not Be Secure

An unsecured seat with broken welds may not properly restrain an occupant during a crash, increasing the risk of injury.

NHTSA Campaign Number: 23V268000

Manufacturer Nissan North America, Inc.

Components SEATS

Potential Number of Units Affected 12,400

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2023 Rogue, Pathfinder, and Infiniti QX60 vehicles. The driver's powered seat may not be fully secured to the seat frame, causing the seat frame welds to detach from the rear inboard seat bracket.

Remedy

Dealers will inspect the driver's seat rail clearance, and if necessary, replace the driver's seat cushion frame, free of charge. Owner notification letters are expected to be mailed June 10, 2023. Owners may contact Nissan's customer service at 1-800-867-7669. Nissan's number for this recall is PC966, PC967.

Vehicles

MAKE	MODEL	YEAR
INFINITI	QX60	2023
NISSAN	PATHFINDER	2023
NISSAN	ROGUE	2023

Tires May Have Tear in Inner Bead

A rapid loss of tire pressure while driving can lead to a loss of vehicle control, increasing the risk of a crash.

NHTSA Campaign Number: 23V273000

Manufacturer Nissan North America, Inc.

Components TIRES

Potential Number of Units Affected 4,249

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2023 Titan and Frontier vehicles. The tires may have a tear in the inner bead which can cause a rapid loss of tire pressure.

Remedy

Dealers will replace all four road tires, or inspect and replace the spare tire assembly, as necessary, free of charge. Owner notification letters are expected to be mailed June 10, 2023. Owners may contact Nissan's customer service at 1-800-867-7669. Nissan's number for this recall is PC973 and PC974.

Vehicles

MAKE	MODEL	YEAR
NISSAN	FRONTIER	2023

MAKE	MODEL	YEAR
NISSAN	TITAN	2023

Damaged ABS Hydraulic Control Unit

Reduced braking ability can increase the distance required to stop the vehicle, increasing the risk of a crash.

NHTSA Campaign Number: 23V275000

Manufacturer Mazda North American Operations

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 2,410

Summary

Mazda North American Operations (Mazda) is recalling certain 2022-2023 CX-30 and 2023 CX-50 vehicles. The anti-lock brake system (ABS) Hydraulic Control Unit (HCU) may be damaged, which can result in reduced braking ability.

Remedy

Dealers will inspect and replace the ABS HCU, as necessary, free of charge. Owner notification letters are expected to be mailed June 17, 2023. Owners may contact Mazda customer service at 1-800-222-5500 Option 6. Mazda's number for this recall is 5823D.

Vehicles

MAKE	MODEL	YEAR
MAZDA	CX-30	2022-2023

MAZDA	CX-50	2023
-------	-------	------
