



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

June 5, 2023

### **ABS Light May Not Stay Illuminated/FMVSS 121**

An ABS indicator light that fails to remain illuminated will not alert the driver of an ABS malfunction, which could increase the risk of a crash.

**NHTSA Campaign Number:** 23V370000

**Manufacturer** Navistar, Inc.

**Components** SERVICE BRAKES, AIR

**Potential Number of Units Affected** 91,288

#### **Summary**

Navistar, Inc. (Navistar) is recalling certain 2021-2024 International HV, HX, LoneStar, LT, MV, eMV, and RH trucks, and IC Bus CE, 2021-2023 IC Bus RE, and 2022-2023 IC Bus TC Commercial Buses. The anti-lock brake system (ABS) indicator light does not remain illuminated when a malfunction exists, and when the vehicle's ignition switch is on, and the vehicle is in motion. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 121, "Air Brake Systems."

#### **Remedy**

Dealers will update the software, free of charge. Owner notification letters are expected to be mailed July 24, 2023. Owners may contact Navistar's customer service at 1-800-448-7825. Navistar's number for this recall is 23515.

#### **Vehicles**

---

MAKE	MODEL	YEAR
IC BUS	CE	2021-2024

---

MAKE	MODEL	YEAR
IC BUS	RE	2021-2023
IC BUS	TC	2022-2023
INTERNATIONAL	EMV	2021-2024
INTERNATIONAL	HV	2021-2024
INTERNATIONAL	HX	2021-2024
INTERNATIONAL	LONESTAR	2021-2024
INTERNATIONAL	LT	2021-2024
INTERNATIONAL	MV	2021-2024
INTERNATIONAL	RH	2021-2024

## ABS Light May Not Stay Illuminated/FMVSS 121

An ABS indicator light that fails to remain illuminated will not alert the driver of an ABS malfunction, which could increase the risk of a crash.

**NHTSA Campaign Number:** 23V371000

**Manufacturer** Navistar, Inc.

**Components** SERVICE BRAKES, AIR

**Potential Number of Units Affected** 19,376

### Summary

Navistar, Inc. (Navistar) is recalling certain 2021-2024 IC Bus RE, 2022-2024 IC Bus CE, and IC Bus EV school buses. The anti-lock brake system (ABS) indicator light does not remain illuminated when a malfunction

exists, and when the vehicle's ignition switch is on, and the vehicle is in motion. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 121, "Air Brake Systems."

## Remedy

Dealers will update the software, free of charge. Owner notification letters are expected to be mailed July 24, 2023. Owners may contact Navistar's customer service at 1-800-448-7825. Navistar's number for this recall is 23516.

## Vehicles

---

MAKE	MODEL	YEAR
IC BUS	CE	2022-2024
IC BUS	EV	2022-2024
IC BUS	RE	2021-2024

---

## Steering Wheel May Disconnect from Steering Column

A loose fastener may allow the steering wheel to disconnect from the steering column, which can cause a loss of steering control and increase the risk of a crash.

**NHTSA Campaign Number:** 23V385000

**Manufacturer** Tesla, Inc.

**Components** STEERING

**Potential Number of Units Affected** 137

## Summary

Tesla, Inc. (Tesla) is recalling certain 2022-2023 Model Y vehicles. The steering wheel fastener may be loose.

## Remedy

Tesla Service will inspect and replace the fastener as necessary, free of charge. Owner notification letters are expected to be mailed July 28, 2023. Tesla's number for this recall is SB-23-32-001.

## Vehicle

---

MAKE	MODEL	YEAR
TESLA	MODEL Y	2022-2023

---

## Improperly Secured Seat Belt Fasteners

Loose seat belt mounting fasteners may not properly restrain an occupant during a crash, increasing the risk of injury.

**NHTSA Campaign Number:** 23V372000

**Manufacturer** Autocar, LLC

**Components** SEAT BELTS

**Potential Number of Units Affected** 373

### Summary

Autocar, LLC (Autocar) is recalling certain 2020-2023 Autocar DC (Legend) trucks. The seat belt mounting fasteners may be improperly secured.

### Remedy

Dealers will inspect, secure, or replace the seat belt mounting fasteners, as necessary, free of charge. Owner notification letters are expected to be mailed July 21, 2023. Owners may contact Autocar's customer service at 1-888-218-3611. Autocar's number for this recall is DC-2302.

### Vehicle

MAKE	MODEL	YEAR
AUTOCAR	LEGEND	2020-2023

## Loose Seat Belt Attachment/FMVSS 210

A loose seat belt attachment may not properly restrain the occupant in the event of a crash, increasing the risk of injury.

**NHTSA Campaign Number:** 23V365000

**Manufacturer** Winnebago Industries, Inc.

**Components** SEAT BELTS

**Potential Number of Units Affected** 1,328

### Summary

Winnebago Industries, Inc. (Winnebago) is recalling certain 2020-2023 Winnebago Shell, 2021-2023 Winnebago Inspire, 2022-2023 Winnebago Vista, Adventurer, Forza, Journey and Itasca Sunstar motorhomes. The seat belt attachment may have been improperly tightened. As such these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) 210, "Seat Belt Assembly Anchorages."

### Remedy

Dealers will inspect and tighten the seat belt attachment fasteners, as necessary, free of charge. Owner notification letters are expected to be mailed June 16, 2023. Owners may contact Winnebago at 1-800-537-1885. Winnebago's number for this recall is 175.

## Vehicles

MAKE	MODEL	YEAR
ITASCA	SUNSTAR	2022-2023
WINNEBAGO	ADVENTURER	2022-2023
WINNEBAGO	FORZA	2022-2023
WINNEBAGO	INSPIRE	2021-2023
WINNEBAGO	JOURNEY	2022-2023
WINNEBAGO	SHELL	2020-2023
WINNEBAGO	VISTA	2022-2023

## Improperly Secured Rear Seat Belt Fastener

A loose rear seat belt anchor fastener may not properly restrain an occupant in the event of a crash, increasing the risk of injury.

**NHTSA Campaign Number:** 23V374000

**Manufacturer** Nissan North America, Inc.

**Components** SEAT BELTS

**Potential Number of Units Affected** 71

### Summary

Nissan North America, Inc. (Nissan) is recalling certain 2023 Nissan Rogue vehicles. The fastener in the rear seat belt anchor attachment points may not have been tightened properly and can loosen over time.

### Remedy

Dealers will inspect and tighten the rear seat belt anchor bolts. Additionally, dealers will apply warning labels to the seat belt attachment points to indicate the bolt size and torque value required for any future seat belt

repair. Repairs will be performed free of charge. Owner notification letters are expected to be mailed July 14, 2023. Owners may contact Nissan's customer service at 1-800-867-7669. Nissan's number for this recall is PC978, PC979.

## Vehicle

---

MAKE	MODEL	YEAR
NISSAN	ROGUE	2023

---

## Right-Side Door May Not Latch Properly

An incorrectly assembled door latch may allow the door to open unexpectedly during operation, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V373000

**Manufacturer** Autocar, LLC

**Components** LATCHES/LOCKS/LINKAGES

**Potential Number of Units Affected** 557

### Summary

Autocar, LLC (Autocar) is recalling certain 2021-2023 Autocar Xpeditor (ACX) trucks. The right-side stand-up door latch may be assembled incorrectly.

### Remedy

Dealers will inspect and reassemble the door latch, as necessary, free of charge. Owner notification letters are expected to be mailed July 21, 2023. Owners may contact Autocar's customer service at 1-888-218-3611. Autocar's number for this recall is ACX-2306.

## Vehicle

---

MAKE	MODEL	YEAR
AUTOCAR	XPEDITOR	2021-2023

---

## Engine Compartment Fire While Parked or Driving

An engine compartment fire while parked or driving can increase the risk of injury.

**NHTSA Campaign Number:** 23V378000

**Manufacturer** Ford Motor Company

**Components** ENGINE

## Potential Number of Units Affected 142,734

### Summary

Ford Motor Company (Ford) is recalling certain 2015-2019 Lincoln MKC vehicles. The battery monitor sensor may short-circuit and overheat, causing a fire in the engine compartment while parked or driving.

### Remedy

Owners are advised to park outside and away from structures until the recall repair is complete. Dealers will add an in-line fuse to the battery monitor sensor power circuit, free of charge. Owner notification letters are expected to be mailed June 26, 2026. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 23S28.

### Vehicle

---

MAKE	MODEL	YEAR
LINCOLN	MKC	2015-2019

---

## High-Voltage Battery May Overheat

The high-voltage battery overheating increases the risk of a fire.

**NHTSA Campaign Number:** 23V369000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 6,367

### Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2019-2024 Jaguar I-PACE vehicles. The high-voltage battery may overheat.

### Remedy

The battery energy control module software will be updated by a dealer, or through an over-the-air (OTA) update. In addition, battery modules will be replaced as necessary. Repairs will be performed free of charge. Owner notification letters are expected to be mailed July 21, 2023. Owners may contact Jaguar's customer service at 1-800-452-4827. Jaguar's number for this recall is H441.

### Vehicle

---

MAKE	MODEL	YEAR
JAGUAR	I-PACE	2019-2024

---

# High-Voltage Battery May Overheat

The high-voltage battery overheating increases the risk of a fire.

**NHTSA Campaign Number:** 23V361000

**Manufacturer** Polestar Automotive USA, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 66

## Summary

Polestar Automotive USA, Inc. (Polestar) is recalling certain 2020-2021 Polestar 1 vehicles. Defective high-voltage battery cells may cause the battery to overheat when fully charged.

## Remedy

Dealers will replace the high-voltage battery pack and restore the electric driving range as necessary, free of charge. Owner notification letters are expected to be mailed July 16, 2023. Owners may contact Polestar customer service at 1-800-806-2504. Polestar's number for this recall is R102316. Note: This recall supersedes Recall 22V-926 (R10216). Any vehicle that received the interim repair under Recall 22V-926 (R10202) will still need to have the remedy for 23V-361 (R10216) performed.

## Vehicle

---

MAKE	MODEL	YEAR
POLESTAR	POLESTAR 1	2020-2021

---