



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

January 27, 2025

### Side Curtain Air Bag Inflators May Rupture

An inflator rupture may result in sharp metal fragments striking occupants, resulting in injury.

**NHTSA Campaign Number:** 25V010000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** AIR BAGS

**Potential Number of Units Affected** 6,066

#### Summary

Chrysler (FCA US, LLC) is recalling certain 2016-2019 Ram 3500, Ram 1500, 2016-2020 Ram 2500, and 2016 Ram 3500 Cab Chassis vehicles. The right and left side curtain air bag inflators may rupture due to a manufacturing defect.

#### Remedy

Dealers will replace one or both side curtain air bags, as necessary, free of charge. Owner notification letters are expected to be mailed February 13, 2025. Owners may contact FCA customer service at 1-800-853-1403. FCA's numbers for this recall are 05C, 09C, and 10C.

#### Vehicles

---

MAKE	MODEL	YEAR
RAM	1500	2016-2019

---

---

MAKE	MODEL	YEAR
RAM	2500	2016-2020
RAM	3500	2016-2019
RAM	3500 CAB CHASSIS	2016

---

## Loss of Drive Power from Damaged PTU

A loss of drive power can increase the risk of a crash. A loss of park function can cause an unintended vehicle rollaway, which can increase the risk of a crash or injury.

**NHTSA Campaign Number:** 25V011000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** POWER TRAIN

**Potential Number of Units Affected** 63,082

### Summary

Chrysler (FCA US, LLC) is recalling certain 2017-2019 Jeep Cherokee vehicles. The power transfer unit (PTU) may become damaged and disengage the transmission and differential, resulting in a loss of drive power and/or loss of park function.

### Remedy

The remedy is under development. Owner notification letters are expected to be mailed February 13, 2025. Owners may contact FCA customer service at 1-800-853-1403. FCA's number for this recall is 01C.

### Vehicle

---

MAKE	MODEL	YEAR
JEEP	CHEROKEE	2017-2019

---

## Adaptive Cruise Control May Not Activate Brakes

A vehicle that does not automatically brake as expected increases the risk of a crash.

**NHTSA Campaign Number:** 25V012000

**Manufacturer** General Motors, LLC

**Components** SERVICE BRAKES, HYDRAULIC, FORWARD COLLISION AVOIDANCE

**Potential Number of Units Affected** 2,890

**Summary**

General Motors, LLC (GM) is recalling certain 2025 Chevrolet Equinox EV all-wheel drive electric vehicles. The adaptive cruise control may fail to engage the brakes as expected, due to incorrect brake module software.

**Remedy**

Dealers will update the software calibration in the brake system control module, free of charge. Owner notification letters are expected to be mailed March 3, 2025. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N242481530.

**Vehicle**

---

MAKE	MODEL	YEAR
CHEVROLET	EQUINOX EV	2025

---

**Loss of Drive Power from Battery Failure**

**NHTSA Campaign Number:** 25V019000

**Manufacturer** Ford Motor Company

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 272,817

**Summary**

Ford Motor Company (Ford) is recalling certain 2021-2023 Bronco Sport and 2022-2023 Maverick vehicles. The 12-volt battery may experience degradation and suddenly fail.

**Remedy**

Dealers will inspect and if necessary, replace the 12-volt battery, free of charge. Owner notification letters are expected to be mailed February 3, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S02. Vehicles in this recall were previously repaired under 24V-267 and will need to have the new remedy completed.

**Vehicles**

---

MAKE	MODEL	YEAR
FORD	BRONCO SPORT	2021-2023
FORD	MAVERICK	2022-2023

---

## Rearview Camera Image May Not Display

A rearview camera that does not display an image can reduce the driver's rear view, increasing the risk of a crash.

**NHTSA Campaign Number:** 25V017000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** BACK OVER PREVENTION, ELECTRICAL SYSTEM

**Potential Number of Units Affected** 5,329

### Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2019-2020 Jaguar XE vehicles. Due to wiring damage in the trunk, the rearview camera image may not appear on the display.

### Remedy

Dealers will inspect and repair, or replace the rearview camera wiring harness, as necessary, free of charge. Owner notification letters are expected to be mailed March 14, 2025. Owners may contact Jaguar's customer service at 1-800-452-4827. Jaguar's number for this recall is H535. This recall replaces and expands previous recall number 23V-501. Vehicles already repaired under recall 23V-501 will need to have the new remedy completed.

### Vehicle

---

MAKE	MODEL	YEAR
JAGUAR	XE	2019-2020

---

## Rearview Camera Image May Not Display/FMVSS 111

A rearview camera that does not display an image can reduce the driver's rear view, increasing the risk of a crash.

**NHTSA Campaign Number:** 25V016000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** BACK OVER PREVENTION, EQUIPMENT

**Potential Number of Units Affected** 28,370

### Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2023 Discovery Sport, 2023-2024 Defender, and 2023 Range Rover Evoque vehicles. The touchscreen in the center console may go blank at vehicle startup, resulting in the rearview camera image not displaying as intended. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility."

## Remedy

Dealers will update the touchscreen software, free of charge. Owner notification letters are expected to be mailed March 14, 2025. Owners may contact Land Rover's customer service at 1-800-637-6837. Land Rover's number for this recall is N972.

## Vehicles

MAKE	MODEL	YEAR
LAND ROVER	DEFENDER	2023-2024
LAND ROVER	DISCOVERY SPORT	2023
LAND ROVER	RANGE ROVER EVOQUE	2023

## Seat Belt Assembly Bolt Improperly Tightened

An improperly secured seat belt assembly may not restrain an occupant as intended, increasing the risk of injury in a crash.

**NHTSA Campaign Number:** 25V015000

**Manufacturer** General Motors, LLC

**Components** SEAT BELTS, SEATS

**Potential Number of Units Affected** 5

### Summary

General Motors, LLC (GM) is recalling certain 2024 Chevrolet Silverado EV and 2024-2025 GMC Sierra EV pickup trucks. The bolt that secures the rear center seat belt assembly to the seat structure may not have been properly tightened.

### Remedy

GM will tighten the bolt that attaches the center seat belt assembly to the rear seat structure, free of charge. All affected vehicles are still in dealer inventory and, therefore, no owner letters will be mailed. Owners may contact GM customer service at 1-888-988-7267, or Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N242489901.

## Vehicles

MAKE	MODEL	YEAR
CHEVROLET	SILVERADO EV	2024

---

MAKE	MODEL	YEAR
GMC	SIERRA EV	2024-2025

---

## Throttle Pedal Assembly May Stick

A pedal that sticks increases the risk of a crash.

**NHTSA Campaign Number:** 25V014000

**Manufacturer** PACCAR Incorporated

**Components** VEHICLE SPEED CONTROL

**Potential Number of Units Affected** 1,110

### Summary

PACCAR Incorporated (PACCAR) is recalling certain 2023-2024 Peterbilt 535, 536, 537, 548, 2023-2024 Kenworth T280, T380, T480, and 2024 Kenworth T180 trucks. The throttle pedal assembly may contain an oversized magnet carrier, slowing the responsiveness or causing the pedal to stick.

### Remedy

Dealers will inspect and replace the throttle pedal as necessary, free of charge. Owner notification letters are expected to be mailed March 17, 2025. Owners may contact Peterbilt's customer service at 1-940-591-4220 and Kenworth's customer service at 1-425-828-5888. PACCAR's numbers for this recall are 25PBA and 25KWA.

### Vehicles

---

MAKE	MODEL	YEAR
KENWORTH	T180	2024
KENWORTH	T280	2023-2024
KENWORTH	T380	2023-2024
KENWORTH	T480	2023-2024
PETERBILT	535	2023-2024

---

MAKE	MODEL	YEAR
PETERBILT	536	2023-2024
PETERBILT	537	2023-2024
PETERBILT	548	2023-2024

## Improper Air Bag Deployment from Damaged Wiring

Air bags and seat belts that deploy improperly or an air bag deploying unintentionally can increase the risk of injury in a crash.

**NHTSA Campaign Number:** 25V024000

**Manufacturer** Kia America, Inc.

**Components** SEATS, ELECTRICAL SYSTEM

**Potential Number of Units Affected** 80,255

### Summary

Kia America, Inc. (Kia) is recalling certain 2023-2025 Niro EV, Plug-in Hybrid (PHEV), and Hybrid vehicles. The floor wiring assembly beneath the front passenger seat may become damaged, which can prevent the front air bags and seat belts from deploying properly or cause an unintended side curtain air bag deployment.

### Remedy

Dealers will inspect, replace and reroute the floor wiring assembly, as necessary, free of charge. In addition, dealers will install wiring covers. Owner notification letters are expected to be mailed March 14, 2025. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC332.

### Vehicles

MAKE	MODEL	YEAR
KIA	NIRO	2023-2025
KIA	NIRO EV	2023-2025

---

MAKE	MODEL	YEAR
KIA	NIRO PHEV	2023-2025

---

## Rear Shock Absorber Reservoir May Detach

An external reservoir that detaches from a vehicle can create a road hazard, increasing the risk of a crash.

**NHTSA Campaign Number:** 25V025000

**Manufacturer** Ford Motor Company

**Components** SUSPENSION

**Potential Number of Units Affected** 149,449

### Summary

Ford Motor Company (Ford) is recalling certain 2021-2024 Bronco vehicles. The rear shock absorbers may corrode and fail, resulting in detachment of the external reservoir.

### Remedy

The remedy is currently under development. Interim letters notifying owners of the safety risk are expected to be mailed February 3, 2025. A second notice will be sent once the remedy is available. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S01.

### Vehicle

---

MAKE	MODEL	YEAR
FORD	BRONCO	2021-2024

---

## Insufficient Air Volume in Brake System/FMVSS 121

Insufficient air volume can reduce braking performance and increase the risk of a crash.

**NHTSA Campaign Number:** 25V026000

**Manufacturer** Mack Trucks, Inc.

**Components** SERVICE BRAKES, AIR

**Potential Number of Units Affected** 21



## Summary

Mack Trucks, Inc. (Mack) is recalling certain 2024-2025 Pinnacle (PI/PN) trucks. The air tanks have an insufficient volume of air for the brake system. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 121, "Air Brake Systems."

## Remedy

Dealers will install the correct volume air tanks, free of charge. Owner notification letters are expected to be mailed March 17, 2025. Owners may contact Mack's customer service at 1-800-866-1177. Mack's number for this recall is SC0473.

## Vehicle

---

MAKE	MODEL	YEAR
MACK	PINNACLE (PI/PN)	2024-2025

---

## Fuel Pump May Fail

Fuel pump failure can cause an engine stall, increasing the risk of a crash.

**NHTSA Campaign Number:** 25V028000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 858

## Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2018 Camry, 2019 Lexus NX300, and 2019 RX350L vehicles. The low-pressure fuel pump inside the fuel tank may fail.

## Remedy

Dealers will replace the fuel pump assembly, free of charge. Owner notification letters are expected to be mailed March 9, 2025. Owners may contact Toyota's customer service at 1-800-331-4331. Toyota's numbers for this recall are 25TA01 and 25LA01.

## Vehicles

---

MAKE	MODEL	YEAR
LEXUS	NX	2019
LEXUS	RX	2019

---

---

MAKE

MODEL

YEAR

TOYOTA

CAMRY

2018

---