



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

February 24, 2025

Rearview Camera Image May Not Display/FMVSS 111

A rearview camera image that does not display decreases the driver's visibility, increasing the risk of a crash.

NHTSA Campaign Number: 25V098000

Manufacturer Maserati North America, Inc.

Components BACK OVER PREVENTION

Potential Number of Units Affected 27,354

Summary

Maserati North America, Inc. (Maserati) is recalling certain 2023-2024 Grecale, 2023-2025 MC20 Cielo, 2024 Granturismo, GranCabrio, 2021-2024 Levante, Ghibli, Quattroporte, and 2022-2025 MC 20 vehicles. The radio software may prevent the rearview image from displaying. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility."

Remedy

The radio software will be updated over-the-air (OTA) or by a dealer, free of charge. Owner notification letters are expected to be mailed March 21, 2025. Owners may contact Maserati customer service at 877-696-2737. Maserati's number for this recall is 740.

Vehicles

MAKE	MODEL	YEAR
MASERATI	GHIBLI	2021-2024

MAKE	MODEL	YEAR
MASERATI	GRANCABRIO	2024
MASERATI	GRANTURISMO	2024
MASERATI	GRECALE	2023-2024
MASERATI	LEVANTE	2021-2024
MASERATI	MC20	2022-2025
MASERATI	MC20 CIELO	2023-2025
MASERATI	QUATTROPORTE	2021-2024

Rearview Camera Image May Not Display/FMVSS 111

A rearview camera that does not display an image can reduce the driver's rear view, increasing the risk of a crash.

NHTSA Campaign Number: 25V082000

Manufacturer Volkswagen Group of America, Inc.

Components BACK OVER PREVENTION

Potential Number of Units Affected 29,569

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2022-2024 Tiguan, 2023 Arteon, and 2024-2025 Audi Q3 vehicles. An error may occur in the camera control unit at vehicle startup, resulting in the rearview camera image not displaying as intended. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Dealers will update the camera control unit software, free of charge. Owner notification letters are expected to be mailed April 11, 2025. Owners may contact Volkswagen customer service at 1-800-893-5298 or Audi customer service at 1-800-253-2834. Volkswagen's numbers for this recall are (Volkswagen) 91NY and (Audi) 90AV.

Vehicles

MAKE	MODEL	YEAR
AUDI	Q3	2024-2025
VOLKSWAGEN	ARTEON	2023
VOLKSWAGEN	TIGUAN	2022-2024

Rearview Camera Image May Not Display/FMVSS 111

A rearview image that does not display reduces the driver's visibility, increasing the risk of a crash.

NHTSA Campaign Number: 25V083000

Manufacturer Chrysler (FCA US, LLC)

Components EQUIPMENT, BACK OVER PREVENTION

Potential Number of Units Affected 133

Summary

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Grand Cherokee and 2021-2022 Jeep Grand Cherokee L vehicles. The center stack upper display (DCSD) contains a transistor that may overheat and prevent the rearview camera image from displaying. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility."

Remedy

Dealers replaced the DCSD, free of charge. All affected vehicles have been repaired. Owner notification letters are expected to be mailed March 13, 2025. Owners may contact Chrysler customer service at 800-853-1403. Chrysler's number for this recall is 11C.

Vehicles

MAKE	MODEL	YEAR
JEEP	GRAND CHEROKEE	2022
JEEP	GRAND CHEROKEE L	2021-2022

Right-Side Knee Air Bag May Deploy Improperly

An improperly folded air bag may not deploy as intended, increasing the risk of injury in a crash.

NHTSA Campaign Number: 25V088000

Manufacturer Jaguar Land Rover North America, LLC

Components AIR BAGS

Potential Number of Units Affected 1,473

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2020 Range Rover Evoque vehicles. The cover for the right-side lower knee air bag may come loose, allowing the air bag cushion to unfold.

Remedy

Dealers will replace the right-side lower knee air bag module, free of charge. Owner notification letters are expected to be mailed April 11, 2025. Owners may contact Land Rover's customer service at 800-637-6837. Land Rover's number for this recall is N978.

Vehicle

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER EVOQUE	2020

Left-Side Knee Air Bag May Deploy Improperly

An improperly folded air bag may not deploy as intended, increasing the risk of injury in a crash.

NHTSA Campaign Number: 25V089000

Manufacturer Jaguar Land Rover North America, LLC

Components AIR BAGS

Potential Number of Units Affected 1,270

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2020 Range Rover Evoque vehicles. The cover for the left-side lower knee air bag may come loose, allowing the air bag cushion to unfold.

Remedy

Dealers will replace the left-side lower knee air bag module, free of charge. Owner notification letters are expected to be mailed April 11, 2025. Owners may contact Land Rover's customer service at 800-637-6837. Land Rover's number for this recall is N979. This recall expands and replaces previous NHTSA recall 21V-168.

Vehicle

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER EVOQUE	2020

Loose Third-Row Seatback Bolts/FMVSS 202

An improperly tightened seatback may not adequately restrain the occupant during a crash, increasing their risk of injury.

NHTSA Campaign Number: 25V086000

Manufacturer Toyota Motor Engineering & Manufacturing

Components SEATS

Potential Number of Units Affected 167,802

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2021-2025 Sienna Hybrid vehicles. The bolts for the seatbacks on the third-row seat assemblies may not be tightened properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) numbers 202, "Head Restraints," 207, "Seating Systems," and 225, "Child Restraint Anchorage Systems."

Remedy

Dealers will tighten the seat assembly bolts, free of charge. Owner notification letters are expected to be mailed March 31, 2025. Owners may contact Toyota's customer service at 1-800-331-4331. Toyota's number for this recall is 25TA05.

Vehicle

MAKE	MODEL	YEAR
TOYOTA	SIENNA HYBRID	2021-2025

Improperly Secured Seat Belt Buckle Anchor Bolts

A loose seat belt or seat belt buckle may not properly restrain an occupant during a crash, increasing the risk of injury.

NHTSA Campaign Number: 25V093000

Manufacturer Ford Motor Company

Components SEAT BELTS

Potential Number of Units Affected 240,510

Summary

Ford Motor Company (Ford) is recalling certain 2020-2021 Explorer and Aviator vehicles. The seat belt buckle anchor bolts at one or more seating positions may be improperly secured. Additionally, vehicles may have an improperly secured seat belt retractor anchor bolt and/or seat belt anchor bolt at the second-row center seating position, if equipped.

Remedy

Dealers will inspect seat belt buckle anchor bolts in all seating positions. Additionally, dealers will inspect the seat belt retractor anchor bolt and seat belt anchor bolt at the second-row center seating position, if equipped. If loose anchor bolts are found, the affected seat components will be replaced. Repairs will be performed free of charge. Owner notification letters are expected to be mailed March 31, 2025. Owners may contact Ford customer service at 866-436-7332. Ford's number for this recall is 25S09.

Vehicles

MAKE	MODEL	YEAR
FORD	EXPLORER	2020-2021
LINCOLN	AVIATOR	2020-2021

Loss of Power Steering Assist

Software Update Repairs Recall

A loss of power steering assist can require greater steering effort, especially at low speeds, increasing the risk of a crash.

NHTSA Campaign Number: 25V092000

Manufacturer Tesla, Inc.

Components STEERING

Potential Number of Units Affected 376,241

Summary

Tesla, Inc. (Tesla) is recalling certain 2023 Model 3 and Model Y vehicles operating software prior to 2023.38.4. The printed circuit board for the electronic power steering assist may experience an overstress condition, causing a loss of power steering assist when the vehicle reaches a stop and then accelerates again.

Remedy

Tesla has released an over-the-air (OTA) software update, free of charge. Owner notification letters are expected to be mailed March 25, 2025. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-25-00-004.

Vehicles

MAKE	MODEL	YEAR
TESLA	MODEL 3	2023
TESLA	MODEL Y	2023

High-Voltage Battery May Overheat and Cause Fire

A high-voltage battery that overheats increases the risk of a fire.

NHTSA Campaign Number: 25V080000

Manufacturer Volkswagen Group of America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 2,616

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2023 Audi Q5 PHEV vehicles. The high-voltage battery may overheat.

Remedy

Dealers will install advanced diagnostic software as the final remedy, anticipated to be available in the second quarter of 2025. Volkswagen will monitor available online vehicle data and contact owners as necessary, to advise them not to charge the vehicle until the battery can be replaced. For vehicles in which online data is unavailable, owners are advised not to charge their batteries until the final remedy becomes available. Repairs will be performed free of charge. Interim letters notifying owners of the safety risk are expected to be mailed April 11, 2025. A second notice will be sent once the final remedy is available. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 93AA. This recall expands previous NHTSA recall number 24V-898.

Vehicle

MAKE	MODEL	YEAR
AUDI	Q5	2023

Loss of Drive Power

A loss of drive power increases the risk of a crash. In addition, drivetrain failure can result in a vehicle rollaway if the parking brake is not applied, increasing the risk of a crash or injury.

NHTSA Campaign Number: 25V090000

Manufacturer Daimler Vans USA, LLC

Components PARKING BRAKE, POWER TRAIN

Potential Number of Units Affected 689

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2024 Mercedes-Benz eSprinter vehicles. The welds on the helical gear within the rear axle drivetrain may fail, causing a loss of drive power.

Remedy

Dealers will replace the rear axle electric drivetrain, free of charge. Owner notification letters are expected to be mailed April 11, 2025. Owners may contact DVUSA customer service at 877-762-8267. DVUSA's number for this recall is V3ESCHWEI.

Vehicle

MAKE	MODEL	YEAR
MERCEDES-BENZ	ESPRINTER	2024

Tail Lights May Fail

Rear tail lights that fail to illuminate can reduce the vehicle's visibility to other drivers, increasing the risk of a crash.

NHTSA Campaign Number: 25V095000

Manufacturer Ford Motor Company

Components EXTERIOR LIGHTING, ELECTRICAL SYSTEM

Potential Number of Units Affected 2,711

Summary

Ford Motor Company (Ford) is recalling certain 2022-2024 Maverick vehicles previously repaired incorrectly under recall number 24V-293. The body control module (BCM) may inadvertently deactivate one or both rear tail lights.

Remedy

Dealers will update the body control module software, free of charge. Owner notification letters are expected to be mailed March 31, 2025. Owners may contact Ford customer service at 866-436-7332. Ford's number for this recall is 25S07.

Vehicle

MAKE	MODEL	YEAR
FORD	MAVERICK	2022-2024

Headlight Low Beams May Fail/FMVSS 108

Headlight failure can reduce visibility, increasing the risk of a crash.

NHTSA Campaign Number: 25V085000

Manufacturer Rivian Automotive, LLC

Components EXTERIOR LIGHTING

Potential Number of Units Affected 17,260

Summary

Rivian Automotive, LLC (Rivian) is recalling certain 2025 R1S and R1T vehicles. The headlight low beams may fail to illuminate when starting the vehicle in cold weather. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Rivian will replace the headlight control modules, free of charge. Owner notification letters are expected to be mailed March 28, 2025. Owners may contact Rivian customer service at 1-888-748-4261. Rivian's number for this recall is FSAM-1612.

Vehicles

MAKE	MODEL	YEAR
RIVIAN	R1S	2025
RIVIAN	R1T	2025

Loss of Drive Power from Transmission Failure

A sudden loss of drive power can increase the risk of a crash.

NHTSA Campaign Number: 25V081000

Manufacturer Volkswagen Group of America, Inc.

Components POWER TRAIN

Potential Number of Units Affected 19

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2025 Atlas and Atlas Cross Sport vehicles. The transmission may have been manufactured incorrectly, which can result in a loss of drive power.

Remedy

Dealers will replace the transmission, free of charge. Owner notification letters are expected to be mailed April 11, 2025. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 38CX.

Vehicles

MAKE	MODEL	YEAR
VOLKSWAGEN	ATLAS	2025
VOLKSWAGEN	ATLAS CROSS SPORT	2025
