



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

April 7, 2025

Loss of Control from Loose Brake Caliper Bracket

Reduced steering control, a brake fluid leak, and loss of front brake function increase the risk of a crash.

NHTSA Campaign Number: 25V191000

Manufacturer Chrysler (FCA US, LLC)

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 8

Summary

Chrysler (FCA US, LLC) is recalling certain 2025 Chrysler Pacifica Plug-In Hybrid Electric (PHEV) vehicles. The bolts securing the front brake caliper bracket may not be tightened properly, which can result in reduced steering control, a brake fluid leak, and a loss of front brake function.

Remedy

Dealers will inspect and replace the front brake caliper brackets and bolts, as necessary, free of charge. Owner notification letters are expected to be mailed April 24, 2025. Owners may contact FCA customer service at 1-800-853-1403. FCA's number for this recall is 27C.

Vehicle

MAKE	MODEL	YEAR
CHRYSLER	PACIFICA PLUG-IN HYBRID	2025

Steering Damper May Fail

An unexpected increase in steering effort can result in a loss of control, increasing the risk of a crash.

NHTSA Campaign Number: 25V194000

Manufacturer BMW of North America, LLC

Components STEERING

Potential Number of Units Affected 51

Summary

BMW of North America, LLC (BMW) is recalling certain 2024-2025 M 1000 XR, and M 1000 R motorcycles. The steering damper may have a loose valve pin within the housing, which can cause an unexpected increase in steering effort.

Remedy

Dealers will replace the steering damper, free of charge. Owner notification letters are expected to be mailed May 19, 2025. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	M 1000 R	2024-2025
BMW	M 1000 XR	2024-2025

Seat Belt May Fail to Retract or Extend

Seat belts that do not retract or extend can fail to restrain an occupant as intended, increasing the risk of injury in a crash.

NHTSA Campaign Number: 25V197000

Manufacturer Ford Motor Company

Components SEAT BELTS

Potential Number of Units Affected 105,322

Summary

Ford Motor Company (Ford) is recalling certain 2018-2020 Expedition and Lincoln Navigator vehicles. The seat belt pretensioner in the driver and/or front passenger seat may inadvertently lock the seat belt, which will not allow the belt to retract or extend.

Remedy

Dealers will inspect the seat belt retractor date codes and replace the seat belt retractors as necessary, free of charge. Owner notification letters are expected to be mailed April 14, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S31. Some vehicles in this recall that were previously inspected under recall 24V-099 and did not have parts replaced will need to have this new recall remedy completed.

Vehicles

MAKE	MODEL	YEAR
FORD	EXPEDITION	2018-2020
LINCOLN	NAVIGATOR	2018-2020

Incorrect Fuse May Cause a Loss of Drive Power

A sudden loss of drive power increases the risk of a crash.

NHTSA Campaign Number: 25V199000

Manufacturer Ford Motor Company

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 47

Summary

Ford Motor Company (Ford) is recalling certain 2025 F-150 full hybrid electric (FHEV) vehicles. The high voltage battery junction box may contain an incorrect fuse, which can fail and result in a sudden loss of drive power.

Remedy

Dealers will replace the incorrect 60-amp fuse with a 150-amp fuse, free of charge. Owner notification letters are expected to be mailed April 14, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S29.

Vehicle

MAKE	MODEL	YEAR
FORD	F-150 HYBRID	2025

Tires Manufactured Incorrectly/FMVSS 119

Incorrect belt orientation may cause the tires to fail and increase the risk of a crash.

NHTSA Campaign Number: 25V200000

Manufacturer Great Dane Trailers

Components TIRES

Potential Number of Units Affected 16

Summary

Great Dane Trailers (Great Dane) is recalling certain 2025-2026 Champion Dry Van trailers equipped with Bridgestone R123 Ecopia tires, size 295/75R22.5. The tires may have been manufactured incorrectly with one of the three stabilizer ply belts applied in the wrong orientation. As such, these vehicles fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) number 119, "New pneumatic tires - other than passenger cars."

Remedy

Bridgestone (BATO) dealers will replace the tires, free of charge. Owner notification letters are expected to be mailed May 27, 2025. Owners may contact BATO customer service at 1-800-847-3272 or Great Dane customer service at 1-877-369-3493.

Tire

BRAND	TIRE LINE/SIZE	PRODUCTION DATES
BRIDGESTONE	R123 ECOPIA/295/75R22.5	

High Voltage Batteries May Short Circuit

A short circuit increases the risk of a fire. In addition, the battery contactors may open suddenly and cause a loss of drive power, increasing the risk of a crash.

NHTSA Campaign Number: 25V203000

Manufacturer Gillig, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 15

Summary

Gillig, LLC (Gillig) is recalling certain 2023-2024 Low Floor transit buses. The high voltage batteries may have loose hardware that can fall inside the battery pack and create a short circuit.

Remedy

Gillig will replace the batteries, free of charge. Owner notification letters are expected to be mailed April 30, 2025. Owners may contact Gillig customer service at 1-800-735-1500.

Vehicle

MAKE	MODEL	YEAR
GILLIG	LOW FLOOR	2023-2024

High Voltage Battery May Short Circuit

Liquid intrusion into a battery pack can cause a loss of electrical isolation or short circuit, increasing the risk of a fire or shock hazard. In addition, the detection of a battery fault can cause a loss of drive power, increasing the risk of a crash.

NHTSA Campaign Number: 25V204000

Manufacturer Bollinger Motors, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 17

Summary

Bollinger Motors, Inc. (Bollinger Motors) is recalling certain 2025 B4 trucks. The high voltage battery pack may be improperly sealed and allow liquid to enter the battery.

Remedy

Bollinger Motors will work with Our Next Energy to inspect and repair the battery packs as necessary, free of charge. Owners can contact Bollinger Motors at 586-785-7351.

Vehicle

MAKE	MODEL	YEAR
BOLLINGER MOTORS	B4	2025

Starter-Generator Electrical Connection May Fail

A loose starter-generator connection can result in an engine stall, increasing the risk of a crash. In addition, the wiring may overheat, increasing the risk of a fire.

NHTSA Campaign Number: 25V202000

Manufacturer BMW of North America, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 4,397

Summary

BMW of North America, LLC (BMW) is recalling certain 2025 330i, 330i xDrive, 530i, 530i xDrive, 4 Series Coupe (430i, 430i xDrive), 4 Series Convertible (430i, 430i xDrive), 4 Series Gran Coupe (430i, 430i xDrive) and X3 30 xDrive vehicles. The electrical connection between the starter-generator and battery may come loose.

Remedy

Dealers will inspect and replace the starter-generator and positive battery cable as necessary, free of charge. Owner notification letters are expected to be mailed May 23, 2025. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	330I	2025
BMW	330I XDRIVE	2025
BMW	430I	2025
BMW	430I XDRIVE	2025
BMW	530I	2025
BMW	530I XDRIVE	2025
BMW	X3	2025

Seats May Detach During a Crash/FMVSS 207 and 210

An insufficiently retained seat can detach during a crash, increasing the risk of injury.

NHTSA Campaign Number: 25V190000

Manufacturer Corp. Micro Bird, Inc.

Components SEATS

Potential Number of Units Affected 26

Summary

Corp. Micro Bird, Inc. (Micro Bird) is recalling certain 2012, 2015-2019, and 2024 G5 school buses equipped with Type 2 seat belts. The seat reinforcement supports may not have been installed. As such, these vehicles fail to comply with Federal Motor Vehicle Safety Standard numbers 207, "Seating Systems" and 210, "Seat Belt Assembly Anchorages."

Remedy

Dealers will install reinforcement supports, free of charge. Owner notification letters are expected to be mailed May 12, 2024. Owners may contact Micro Bird customer service at 1-819-477-2012. Micro Bird's number for this recall is 25-113-FUS.

Vehicle

MAKE	MODEL	YEAR
MICRO BIRD	G5	2012, 2015-2019, 2024
