



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

March 24, 2025

Loss of Power Steering Assist

A loss of power steering assist can require greater steering effort, especially at low speeds, increasing the risk of a crash.

NHTSA Campaign Number: 25V175000

Manufacturer General Motors, LLC

Components STEERING

Potential Number of Units Affected 934

Summary

General Motors LLC (GM) is recalling certain 2016-2018 Cadillac CTS, 2017-2018 Cadillac ATS, Chevrolet Camaro, and Chevrolet Corvette vehicles. The electric power steering (EPS) assist may fail.

Remedy

Dealers will replace the power steering gear assembly, free of charge. Owner notification letters are expected to be mailed May 5, 2025. Owners may contact Cadillac customer service at 1-800-333-4223 or Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N252497020.

Vehicles

MAKE	MODEL	YEAR
CADILLAC	ATS	2017-2018

MAKE	MODEL	YEAR
CADILLAC	CTS	2016-2018
CHEVROLET	CAMARO	2017-2018
CHEVROLET	CORVETTE	2017-2018

Loss of Rear Brake Function from Brake Fluid Leak

A loss of rear brake function increases the risk of a crash.

NHTSA Campaign Number: 25V154000

Manufacturer BMW of North America, LLC

Components SERVICE BRAKES, HYDRAULIC, ELECTRONIC STABILITY CONTROL (ESC)

Potential Number of Units Affected 192

Summary

BMW of North America, LLC (BMW) is recalling certain 2025 X3 30 xDrive and X3 M50 xDrive vehicles. The rear brake hoses may leak, causing a loss of rear brake function, and a loss of the Antilock Brake System (ABS) and the Dynamic Stability Control (DSC) system.

Remedy

Dealers will replace the rear brake hoses, free of charge. Owner notification letters are expected to be mailed May 2, 2025. Owners may contact BMW customer service at 800-525-7417.

Vehicle

MAKE	MODEL	YEAR
BMW	X3	2025

Unexpected Vehicle Movement

Unexpected vehicle movement increases the risk of a crash.

NHTSA Campaign Number: 25V164000

Manufacturer Ford Motor Company

Components POWER TRAIN

Potential Number of Units Affected 269

Summary

Ford Motor Company (Ford) is recalling certain 2024-2025 F-150, Bronco, 2024 Ranger, 2025 Mustang, Explorer, and Aviator vehicles. The transmission valve body may have been machined incorrectly, which can cause reverse gear failure, or unexpected forward movement in reverse or neutral gear.

Remedy

Dealers will replace the transmission main control valve body, free of charge. Owner notification letters are expected to be mailed May 5, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S19.

Vehicles

MAKE	MODEL	YEAR
FORD	BRONCO	2024-2025
FORD	EXPLORER	2025
FORD	F-150	2024-2025
FORD	MUSTANG	2025
FORD	RANGER	2024
LINCOLN	AVIATOR	2025

Front Windows May Fail to Reverse Direction

A window that does not automatically reverse when an obstruction is encountered increases the risk of injury.

NHTSA Campaign Number: 25V157000

Manufacturer Ford Motor Company

Components VISIBILITY

Potential Number of Units Affected 9

Summary

Ford Motor Company (Ford) is recalling certain 2023 Super Duty F-250 and F-350 vehicles previously repaired incorrectly under recall number 23V-507. The driver and front passenger windows may fail to detect an obstacle while closing and not reverse direction as intended.

Remedy

Dealers will update the software, free of charge. Owner notification letters are expected to be mailed April 24, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S25.

Vehicles

MAKE	MODEL	YEAR
FORD	F-250 SD	2023
FORD	F-350 SD	2023

Transmission May Shift into Neutral While Driving

An unexpected shift into neutral will cause a loss of drive power and increase the risk of a crash.

NHTSA Campaign Number: 25V169000

Manufacturer Ford Motor Company

Components POWER TRAIN

Potential Number of Units Affected 567

Summary

Ford Motor Company (Ford) is recalling certain 2021 F-150 vehicles previously repaired incorrectly under recall number 22V-188. The Diagnostic Trouble Code (DTC) for low transmission fluid pressure may falsely activate and cause the transmission to unexpectedly shift into neutral.

Remedy

Dealers will update the Powertrain Control Module (PCM) software, free of charge. Owner notification letters are expected to be mailed April 24, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S24.

Vehicle

MAKE	MODEL	YEAR
FORD	F-150	2021

Steering Column Shifter May Detach

A detached shifter will prevent the driver from shifting into park, which can result in a vehicle rollaway and increase the risk of a crash.

NHTSA Campaign Number: 25V163000

Manufacturer Ford Motor Company

Components POWER TRAIN

Potential Number of Units Affected 11,745

Summary

Ford Motor Company (Ford) is recalling certain 2025 Super Duty F-250, F-350, and F-450 vehicles. The steering column shifter may have been improperly welded and detach from the steering column.

Remedy

Dealers will inspect the steering column serial numbers and replace the steering column as necessary, free of charge. Owner notification letters are expected to be mailed April 24, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S20.

Vehicles

MAKE	MODEL	YEAR
FORD	F-250 SD	2025
FORD	F-350 SD	2025
FORD	F-450 SD	2025

Blank or Distorted Rearview Camera Image

A rearview camera that displays a blank or distorted image can reduce the driver's view of what is behind the vehicle, increasing the risk of a crash.

NHTSA Campaign Number: 25V160000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 2,290

Summary

Ford Motor Company (Ford) is recalling certain 2021-2022 Edge vehicles previously repaired incorrectly under recall number 22V-151. A software error may cause the rearview camera to display a blank or distorted image when the vehicle is in reverse.

Remedy

Dealers will update the rearview camera software, free of charge. Owner notification letters are expected to be mailed April 24, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S28.

Vehicle

MAKE	MODEL	YEAR
FORD	EDGE	2021-2022

Rearview Camera Image May Not Display

Loss of the rearview camera image can reduce the driver's rear visibility, increasing the risk of a crash.

NHTSA Campaign Number: 25V159000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 49,399

Summary

Ford Motor Company (Ford) is recalling certain 2020-2023 Explorer, Lincoln Aviator, and 2020-2022 Lincoln Corsair vehicles previously repaired incorrectly under recall number 23V-342. The video output may fail, preventing the rearview camera image from displaying.

Remedy

Dealers will update the Image Processing Module software, free of charge. Owner notification letters are expected to be mailed April 24, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S27.

Vehicles

MAKE	MODEL	YEAR
FORD	EXPLORER	2020-2023

MAKE	MODEL	YEAR
LINCOLN	AVIATOR	2020-2023
LINCOLN	CORSAIR	2020-2022

Loss of Drive Power from Undetected Low Battery

An undetected low battery charge can result in a loss of electrical accessories such as hazard lights, or cause a loss of drive power, increasing the risk of a crash.

NHTSA Campaign Number: 25V158000

Manufacturer Ford Motor Company

Components POWER TRAIN, ELECTRICAL SYSTEM

Potential Number of Units Affected 12,833

Summary

Ford Motor Company (Ford) is recalling certain 2021-2024 Bronco Sport and 2022-2023 Maverick vehicles previously repaired incorrectly under recall number 24V-267. The body and power train control modules may fail to detect a change in the 12-volt battery state of charge.

Remedy

Dealers will recalibrate the body control module and power train control module, free of charge. Owner notification letters are expected to be mailed April 24, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S26.

Vehicles

MAKE	MODEL	YEAR
FORD	BRONCO SPORT	2021-2024
FORD	MAVERICK	2022-2023

Exterior Trim Panel Can Detach While Driving

A detached panel can become a road hazard, increasing the risk of a crash.

NHTSA Campaign Number: 25V170000

Manufacturer Tesla, Inc.

Components STRUCTURE

Potential Number of Units Affected 46,096

Summary

Tesla, Inc. (Tesla) is recalling certain 2024-2025 Cybertruck vehicles. The cant rail, a stainless-steel exterior trim panel, can delaminate and detach from the vehicle.

Remedy

Tesla service will replace the cant rail assembly, free of charge. Owner notification letters are expected to be mailed May 19, 2025. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-25-10-001.

Vehicle

MAKE	MODEL	YEAR
TESLA	CYBERTRUCK	2024-2025
