



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

June 9, 2025

D-ring Bolts for Seat Belt Anchorage Assemblies may be Improperly Installed

An improperly secured seat belt may not restrain an occupant as intended, increasing the risk of injury during a crash.

NHTSA Campaign Number: 25V370000

Manufacturer Rivian Automotive, LLC

Components SEAT BELTS

Potential Number of Units Affected 536

Summary

Rivian Automotive, LLC (Rivian) is recalling certain 2022-2025 R1T and R1S vehicles. The D-ring bolts for one or both front seat belt anchorage assemblies may not have been properly installed.

Remedy

Rivian will inspect and properly secure the seat belt anchorage assemblies as necessary, free of charge. Owner notification letters are expected to be mailed July 16, 2025. Owners may contact Rivian customer service at 1-888-748-4261. Rivian's number for this recall is FSAM-1681.

Vehicles

MAKE	MODEL	YEAR
RIVIAN	R1S	2022-2025

MAKE	MODEL	YEAR
RIVIAN	R1T	2022-2025

Traction Control Indicator Light May Not Illuminate/FMVSS 126

An indicator light that does not illuminate may fail to warn the driver of a TCS or DSC system issue, increasing the risk of a crash.

NHTSA Campaign Number: 25V336000

Manufacturer Mazda North American Operations

Components TRACTION CONTROL SYSTEM, ELECTRONIC STABILITY CONTROL (ESC)

Potential Number of Units Affected 12,244

Summary

Mazda North American Operations (Mazda) is recalling certain 2024-2025 Mazda MX-5 vehicles. The Traction Control System (TCS) and Dynamic Stability Control (DSC) indicator light may fail to illuminate as intended due to a software error. As such, these vehicles fail to conform to Federal Motor Vehicle Safety Standard number 126, "Electronic Stability Control Systems."

Remedy

Dealers will replace the DSC unit, free of charge. Owner notification letters are expected to be mailed July 21, 2025. Owners may contact Mazda customer service at 1-800-222-5500 Option 6. Mazda's number for this recall is 7425E.

Vehicle

MAKE	MODEL	YEAR
MAZDA	MX-5	2024-2025

Panoramic and Center Display Failure/FMVSS 111

A blank instrument display can result in a loss of critical safety information, such as the speedometer and warning lights, increasing the risk of a crash. In addition, a missing rearview camera display image can reduce visibility of what is behind the vehicle, increasing the risk of a crash.

NHTSA Campaign Number: 25V337000

Manufacturer Ford Motor Company

Components ELECTRICAL SYSTEM, EQUIPMENT

Potential Number of Units Affected 30,679

Summary

Ford Motor Company (Ford) is recalling certain 2024 Nautilus vehicles. The multimedia module software may cause the panoramic and center displays to reboot, resulting in a blank screen. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) numbers 111, "Rear Visibility," and 102, "Transmission shift lever sequence, starter interlock, and transmission braking effect," as well as FMVSS numbers 126, 108, 135, 138, 208, 101, and 305.

Remedy

The multimedia module system software will be updated by a dealer, or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed June 16, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25C21.

Vehicle

MAKE	MODEL	YEAR
LINCOLN	NAUTILUS	2024

Pre-Collision Assist Features May Not Function

Inoperative pre-collision assist features that fail to perform as expected can increase the risk of a crash or injury.

NHTSA Campaign Number: 25V346000

Manufacturer Ford Motor Company

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 426

Summary

Ford Motor Company (Ford) is recalling certain 2020 Expedition and Navigator vehicles that were repaired incorrectly under recall 20V262. The Pre-Collision Assist features, such as forward collision warning and automatic emergency braking, are not functional due to a software error.

Remedy

Dealers will update the body control module software, free of charge. Owner notification letters are expected to be mailed June 9, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S56.

Vehicles

MAKE	MODEL	YEAR
FORD	EXPEDITION	2020
LINCOLN	NAVIGATOR	2020

Windshield Wipers Nozzles May be Blocked/FMVSS 104

The inability to clean the windshield reduces the driver’s visibility and increases the risk of a crash.

NHTSA Campaign Number: 25V359000

Manufacturer Tesla, Inc.

Components VISIBILITY

Potential Number of Units Affected 172

Summary

Tesla, Inc. (Tesla) is recalling certain 2026 Model Y vehicles. The hose connector may block the windshield washer nozzles, preventing washer fluid from reaching the windshield. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 104, "Windshield Wiping and Washing Systems."

Remedy

Tesla service will inspect and replace the wiper arm elbow connector as necessary, free of charge. Owner notification letters are expected to be mailed July 28, 2025. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-25-20-001.

Vehicle

MAKE	MODEL	YEAR
TESLA	MODEL Y	2026

Air Bags May Not Deploy in a Crash

Air bags that do not deploy in the event of a crash increase the risk of injury.

NHTSA Campaign Number: 25V357000

Manufacturer Mazda North American Operations

Components AIR BAGS

Potential Number of Units Affected 171,412

Summary

Mazda North American Operations is recalling certain 2024-2025 Mazda3 and CX30 vehicles. The Sophisticated Air Bag Sensor (SAS) units may set an error code and deactivate the air bags, due to a low battery condition.

Remedy

Dealers will reprogram the SAS unit with improved software or replace the unit, free of charge. Owner notification letters are expected to be mailed July 28, 2025. Mazda's number for this recall is 7525E.

Vehicles

MAKE	MODEL	YEAR
MAZDA	CX-30	2024-2025
MAZDA	MAZDA3	2024-2025

Incorrect Pedestrian Warning Sound/FMVSS 141

A vehicle that makes an incorrect sound may fail to alert pedestrians of a reversing vehicle, increasing the risk of crash.

NHTSA Campaign Number: 25V366000

Manufacturer Mercedes-Benz USA, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 94

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2022-2025 S-Class, EQE SUV, EQE, EQS SUV and EQS vehicles. Please see the recall report for a complete list of models. Software in the Acoustic Vehicle Alerting System (AVAS) may cause an incorrect external pedestrian warning sound while reversing. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 141, "Minimum Sound Requirements for Hybrid Electric Vehicles."

Remedy

Dealers will update the AVAS software, free of charge. Owner notification letters are expected to be mailed August 1, 2025. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG EQE 53 4MATIC	2025
MERCEDES-BENZ	EQE 350+	2023-2024
MERCEDES-BENZ	EQE 500 4MATIC	2023-2024
MERCEDES-BENZ	EQE SUV 350 4MATIC	2023-2025
MERCEDES-BENZ	EQE SUV 350+	2023-2025
MERCEDES-BENZ	EQE SUV 500 4MATIC	2023-2025
MERCEDES-BENZ	EQS 450 4MATIC	2023-2024
MERCEDES-BENZ	EQS 450+	2022-2024
MERCEDES-BENZ	EQS 580 4MATIC	2022-2023
MERCEDES-BENZ	EQS SUV 450 4MATIC	2023-2025
MERCEDES-BENZ	EQS SUV 450+	2023-2025
MERCEDES-BENZ	EQS SUV 580 4MATIC	2023-2025
MERCEDES-BENZ	S 580 E 4MATIC	2025
MERCEDES-MAYBACH	EQS SUV 680 4MATIC	2024-2025

Video Display May Go Blank While Driving

A blank video display can result in a loss of critical safety information, such as the speedometer, warning lights, and rearview camera image, increasing the risk of a crash.

NHTSA Campaign Number: 25V356000

Manufacturer General Motors, LLC

Components EQUIPMENT, ELECTRICAL SYSTEM

Potential Number of Units Affected 41,376

Summary

General Motors, LLC (GM) is recalling certain 2023 – 2024 model year Cadillac Lyriq vehicles. The driver video display may go blank while driving.

Remedy

The video display control module software will be updated by a dealer, or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed July 14, 2025. Owners may contact Cadillac customer service at 1-800-333-4223. GM's number for this recall is N252500680.

Vehicle

MAKE	MODEL	YEAR
CADILLAC	LYRIQ	2023-2024

Parking Lights May Flicker/FMVSS 108

Parking lights that fail to illuminate properly can reduce visibility, increasing the risk of a crash.

NHTSA Campaign Number: 25V351000

Manufacturer Kia America, Inc.

Components EXTERIOR LIGHTING

Potential Number of Units Affected 82,281

Summary

Kia America, Inc. (Kia) is recalling certain 2025 K5 vehicles. A software error in the Power-net Domain Controller (PDC) may cause the parking lights to flicker. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

The PDC software will be updated by a dealer or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed June 24, 2025. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC341.

Vehicle

MAKE	MODEL	YEAR
KIA	K5	2025

High Voltage Battery May Short Circuit

Battery failure can cause a loss of drive power, increasing the risk of a crash. Battery failure can also increase the risk of a fire.

NHTSA Campaign Number: 25V349000

Manufacturer Ford Motor Company

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 8

Summary

Ford Motor Company (Ford) is recalling certain 2020-2021 Lincoln Aviator vehicles equipped with 3.0L PHEV engines that were repaired incorrectly under recall 23V626. A manufacturing defect in one or more of the high voltage battery cells may result in an internal short circuit and battery failure.

Remedy

Dealers will update the Battery Energy Control Module software, free of charge. Owner notification letters are expected to be mailed June 23, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S58.

Vehicle

MAKE	MODEL	YEAR
LINCOLN	AVIATOR	2020-2021

Reverse Lights May Not Function

Inoperative reverse lights may fail to alert others that the vehicle is reversing, increasing the risk of a crash.

NHTSA Campaign Number: 25V348000

Manufacturer Ford Motor Company

Components EXTERIOR LIGHTING

Potential Number of Units Affected 10

Summary

Ford Motor Company (Ford) is recalling certain 2021 F-150 vehicles equipped with the Onboard Scales feature that were repaired incorrectly under recall 24V443. An over-the-air software update to the body control module (BCM) may have disabled both reverse lights.

Remedy

Dealers will update the body control module software, free of charge. Owner notification letters are expected to be mailed on June 9, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S57.

Vehicle

MAKE	MODEL	YEAR
FORD	F-150	2021

Driver and Passenger Door Trim May Detach

Door trim that detaches while driving can create a road hazard, increasing the risk of a crash.

NHTSA Campaign Number: 25V347000

Manufacturer Ford Motor Company

Components STRUCTURE

Potential Number of Units Affected 492,145

Summary

Ford Motor Company (Ford) is recalling certain 2016-2017 Explorer vehicles. The driver and front passenger B-Pillar door trim may detach while driving.

Remedy

The remedy is currently under development. Owner notification letters notifying owners of the safety risk are expected to be mailed June 9, 2025. A second letter will be sent once the remedy is available. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S53.

Vehicle

MAKE	MODEL	YEAR
FORD	EXPLORER	2016-2017

Engine Failure May Cause Fire

An engine compartment fire increases the risk of injury.

NHTSA Campaign Number: 25V345000

Manufacturer Ford Motor Company

Components ENGINE

Potential Number of Units Affected 1,797

Summary

Ford Motor Company (Ford) is recalling certain 2020-2023 Escape, 2021-2023 Corsair, and 2022-2023 Maverick vehicles equipped with 2.5L HEV or PHEV engines that were repaired incorrectly under recall 23V380. In the event of an engine failure, engine oil and fuel vapor may be released into the engine compartment and accumulate near ignition sources such as hot engine or exhaust components, possibly resulting in an engine compartment fire.

Remedy

Owners are advised to park and shut off the engine as quickly as possible if they hear unexpected engine noises, notice a reduction in vehicle power, or see smoke. Dealers will update the powertrain control module software, free of charge. Owner notification letters are expected to be mailed June 23, 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S54.

Vehicles

MAKE	MODEL	YEAR
FORD	ESCAPE	2020-2023
FORD	MAVERICK	2022-2023
LINCOLN	CORSAIR	2021-2023

Engine Failure

A damaged engine can result in engine failure and a stall, increasing the risk of a crash.

NHTSA Campaign Number: 25V344000

Manufacturer Ford Motor Company

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 154

Summary

Ford Motor Company (Ford) is recalling certain 2025 Transit, F-150, and Explorer vehicles. The connecting rod and rod bearing components may have manufacturing defects that can lead to engine damage and engine failure.

Remedy

The remedy is under development. Owner notification letters notifying owners of the safety risk are expected to be mailed June 9, 2025. Second letters will be sent once the remedy is available. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S55.

Vehicles

MAKE	MODEL	YEAR
FORD	EXPLORER	2025
FORD	F-150	2025

Block Heater May Overheat and Cause Fire

An overheated engine block heater can increase the risk of a fire.

NHTSA Campaign Number: 25V343000

Manufacturer Ford Motor Company

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 6,781

Summary

Ford Motor Company (Ford) is recalling certain 2024-2025 Lincoln Nautilus, 2023-2025 Escape, 2023 Lincoln Corsair, 2025 Lincoln Corsair, Maverick, and Bronco Sport vehicles equipped with a 1.5L or 2.0L MPC engine and an engine block heater. The engine block heater may overheat when the vehicle is parked with the block heater plugged in.

Remedy

Dealers will replace the engine block heater element and inspect the electrical cord, replacing it if necessary, free of charge. Owner notification letters notifying owners of the safety risk are expected to be mailed June 6, 2025. Second letters will be mailed once the remedy is available, anticipated for 4th quarter 2025. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 25S52.

Vehicles

MAKE	MODEL	YEAR
FORD	BRONCO SPORT	2025
FORD	ESCAPE	2023-2025
FORD	MAVERICK	2025
LINCOLN	CORSAIR	2023, 2025
LINCOLN	NAUTILUS	2024-2025

TPMS Light May Not Illuminate/FMVSS 138

Low tire pressure can lead to poor vehicle handling and a loss of vehicle control, increasing the risk of a crash.

NHTSA Campaign Number: 25V340000

Manufacturer Ford Motor Company

Components TIRES

Potential Number of Units Affected 192

Summary

Ford Motor Company (Ford) is recalling certain 2022 F-150 Lightning BEV vehicles equipped with 20" or 22" all season tires that were repaired incorrectly under recall 22V-453. The tire pressure monitoring system (TPMS) light may not illuminate as intended, failing to warn the driver of low tire pressure. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 138, "Tire Pressure Monitoring Systems."

Remedy

Dealers will update the body control module (BCM) software, free of charge. Owner notification letters are expected to be mailed June 23, 2025. Owners may contact Ford customer service at 1-866-436-7332.

Vehicle

MAKE	MODEL	YEAR
FORD	F-150 LIGHTNING BEV	2022

