



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest February 9, 2015

RECALL Subject : Unintended Side Curtain Air Bag Deployment

Report Receipt Date: JAN 28, 2015

NHTSA Campaign Number: 15V041000

Component(s): AIR BAGS

Potential Number of Units Affected: 167,749

Vehicle Make	Model	Model Year(s)
• JEEP	CHEROKEE	2014-2015

Manufacturer: Chrysler (FCA US LLC)

SUMMARY:

Chrysler is recalling certain model year 2014-2015 Jeep Cherokee vehicles manufactured January 1, 2013, to November 19, 2014. The affected vehicles may experience unintended side curtain and seat air bag deployment during vehicle operation.

CONSEQUENCE:

If the air bags deploy unexpectedly during vehicle operation, it can increase the risk of personal injury and increase the risk of a crash.

REMEDY:

Chrysler will notify owners, and dealers will re-flash the occupant restraint control module software, free of charge. The recall is expected to begin on March 26, 2015.

RECALL Subject : Front Brake Hose(s) may Rupture

Report Receipt Date: JAN 27, 2015

NHTSA Campaign Number: 15V039000

Component(s): SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected: 74,648

Vehicle Make	Model	Model Year(s)
• LAND ROVER	RANGE ROVER	2006-2012

Manufacturer: Jaguar Land Rover North America, LLC

SUMMARY:

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain model year 2006-2012 Land Rover Range Rover vehicles manufactured April 15, 2005, to September 4, 2012. One or both of the flexible front brake hoses may rupture causing loss of brake fluid.

CONSEQUENCE:

If one or both of the flexible brake hoses fails, the vehicle may require a longer distance to stop, increasing the risk of a crash.

REMEDY:

Land Rover will notify owners, and dealers will replace the left and right front brake hoses, free of charge. The recall is expected to begin March 13, 2015.

RECALL Subject : Parking Lamps may Turn Off/FMVSS 108

Report Receipt Date: JAN 27, 2015
NHTSA Campaign Number: 15V038000
Component(s): EXTERIOR LIGHTING
Potential Number of Units Affected: 4,787

Vehicle Make	Model	Model Year(s)
• JAGUAR	XK	2012-2015

Manufacturer: Jaguar Land Rover North America, LLC

SUMMARY:

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain model year 2012-2015 Jaguar XK vehicles manufactured March 4, 2011, to March 20, 2014. In the affected vehicles, the front side lamps (parking lamps) may turn off after approximately 5 minutes. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 108, "Lamps, Reflective Devices, and Associated Equipment."

CONSEQUENCE:

If the parking lamps turn off, the vehicle will have reduced conspicuity, increasing the risk of a crash.

REMEDY:

Jaguar will notify owners, and dealers will update software that controls the front side lamps, free of charge. The recall is expected to begin March 13, 2015.

RECALL Subject : Tire Tread Cracking/FMVSS 110

Report Receipt Date: JAN 28, 2015
NHTSA Campaign Number: 15V044000
Component(s): TIRES
Potential Number of Units Affected: 5,876

Vehicle Make	Model	Model Year(s)
• BUICK	ENCLAVE	2015
• CHEVROLET	TRAVERSE	2015
• GMC	ACADIA	2015

Manufacturer: General Motors LLC

SUMMARY:

General Motors LLC (GM) is recalling certain model year 2015 Buick Enclave vehicles manufactured December 9, 2014, to January 14, 2015, 2015 Chevrolet Traverse vehicles manufactured December 9, 2014, to January 20, 2015, and 2015 GMC Acadia vehicles manufactured December 9, 2014, to January 16, 2015, and all equipped with Goodyear P255/65R18 Fortera HL tires. These vehicles are equipped with tires that may experience tread cracking. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) No. 110, "Tire Selection and Rims and Motor Home/Recreation Vehicle Trailer Load Carrying Capacity Information for Motor Vehicles with a GVWR of 4,536 kilograms (10,000 pounds) or Less."

CONSEQUENCE:

If the tire treads crack, a loss of tire pressure and possible tire failure may result, increasing the risk of a crash.

REMEDY:

GM will notify owners, and dealers will replace the tires that were manufactured within a specific date range, free of charge. This manufacturer has not yet provided a notification schedule. Owners may contact GM customer service at 1-800-521-7300 (Buick), 1-800-222-1020 (Chevrolet), or 1-800-462-8782 (GMC). GM's number for this recall is 15025/15067. Note: This recall is for Goodyear P255/65R18 Fortera HL tires installed as original equipment. For tires that were purchased as replacement equipment, see recall 15T-002.