



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest January 6, 2014

**RECALL Subject : Side Air Bag Connectors may Disconnect**

**Report Receipt Date:** DEC 02, 2013  
**NHTSA Campaign Number:** 13V607000  
**Component(s):** AIR BAGS  
**Potential Number of Units Affected:** 3,912

Vehicle	MakeModel	Model Year(s)
• LAND ROVER	RANGE ROVER	2013-2014

**Manufacturer:** Jaguar Land Rover North America, LLC

**SUMMARY:**

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain model year 2013-2014 Range Rover vehicles. In the affected vehicles, due to insufficient clearance, the Supplemental Restraint System (SRS) connector located in the driver and front passenger side seat of the vehicle may become disconnected.

**CONSEQUENCE:**

If the connector becomes disconnected, the driver and/or passenger seat side air bag may not function. In the event of a crash necessitating side air bag deployment, the seat occupant is at an increased risk of injury.

**REMEDY:**

Land Rover will notify owners, and dealers will modify the area around the connector to prevent it from becoming disconnected, free of charge. The recall is expected to begin on January 17, 2014.