

## NHTSA Recalls of Interest

# June 13, 2016

## **<u>RECALL Subject : Improperly Tightened Seat Belt Retractor Screws</u></u>**

**Report Receipt Date:** MAY 17, 2016 **NHTSA Campaign Number:** 16V312000 **Component(s):** SEAT BELTS **Potential Number of Units Affected:** 5,245

| Vehicle Make | Model | Model Year(s) |
|--------------|-------|---------------|
| • KIA        | FORTE | 2013          |

Manufacturer: Kia Motors America

### SUMMARY:

Kia Motors America (Kia) is recalling certain model year 2013 Forte vehicles manufactured September 10, 2012, to October 31, 2012. The screws that hold the front seatbelt retractor retaining plates may not have been properly tightened, and as a result, the seatbelt retractor retaining plates may break in a crash.

### **CONSEQUENCE:**

If a retaining plate breaks during a crash, pieces of the plate could strike the occupants, increasing risk of injury.

### **REMEDY:**

Kia will notify owners, and dealers will inspect and replace both front seatbelt assemblies, as necessary, free of charge. The recall is expected to begin June 30, 2016.

### **<u>RECALL Subject : Secondary Hood Latch may Disengage</u>**

Report Receipt Date: MAY 24, 2016 NHTSA Campaign Number: 16V348000 Component(s): LATCHES/LOCKS/LINKAGES Potential Number of Units Affected: 81,000 and 219,800

|   | Vehicle Make | Model  | Model Year(s) |
|---|--------------|--------|---------------|
| • | HYUNDAI      | TUCSON | 2016          |
| ٠ | KIA          | SEDONA | 2006-2014     |

### Manufacturer: Hyundai Motor America

### SUMMARY:

Hyundai Motor Company (Hyundai) is recalling certain model year 2016 Tucson vehicles manufactured May 19, 2015 to March 14, 2016. In the affected vehicles, if the primary hood latch has been released, and the vehicle is driven, the secondary hood latch may not hold adequately secure the hood to prevent it from opening while the vehicle is in motion.

### **CONSEQUENCE:**

If the primary hood latch is inadvertently released and the secondary latch cannot secure the hood, the hood may unexpectedly open while driving, increasing the risk of a crash.

### **REMEDY:**

Hyundai and Kia will notify owners, and dealers will replace the secondary hood latch, free of charge. The recall is expected to begin July 15, 2016.