

# NHTSA Recalls of Interest

# May 29, 2017

Doors May Not Fully Latch

NHTSA Campaign Number: 17V328000

Manufacturer BMW of North America, LLC

**Components** LATCHES/LOCKS/LINKAGES

**Potential Number of Units Affected** 45,484

## Summary

BMW of North America, LLC (BMW) is recalling certain 2005-2008 745i, 745Li, 750i, 750Li, 760i, 760Li, and B7 Alpina vehicles equipped with both the Kiekert Comfort Access and Soft Close Automatic options. In these vehicles, the doors may appear to be closed and latched, but, in fact, may inadvertently open.

## Remedy

The manufacturer has not yet provided a remedy for this recall. Owners may contact BMW at 1-800-525-7417 or email BMW at CustomerRelations@bmwusa.com.

### Vehicles

## MAKE MODEL YEAR

BMW	745I	2005-2008
BMW	745LI	2005-2008
BMW	750I	2005-2008
BMW	750LI	2005-2008

BMW760I2005-2006BMW760LI2005-2008BMWB7 ALPINA2005-2008

Driver Seat Back Frame May Fail/FMVSS 202, 207

#### NHTSA Campaign Number: 17V332000

Manufacturer Ford Motor Company

**Components SEATS** 

**Potential Number of Units Affected 2,204** 

#### **Summary**

Ford Motor Company (Ford) is recalling certain 2017 Ford Explorer, F-150, F-250, F-350, F-450 and F-550 vehicles equipped with a Faurecia manual driver's seat back recliner mechanism. In the event of a crash, the seat back frame may not restrain the occupant due to having inadequate welds. As such, these vehicles may not meet the requirements of Federal Motor Vehicle Safety Standard (FMVSS) numbers 202a, "Head Restraints" and 207, "Seating Systems."

#### Remedy

Ford will notify owners, and dealers will inspect and, if necessary, replace the seat back frame, free of charge. The recall is expected to begin on June 5, 2017. Owners may contact Ford at 1-866-436-7332. Ford's number for this recall is 17C08.

### Vehicles

MAKE MODEL YEAR

FORDEXPLORER 2017FORDF-1502017FORDF-250 SD2017FORDF-350 SD2017FORDF-450 SD2017FORDF-550 SD2017