

# NHTSA Recalls of Interest June 12, 2017

Secondary Hood Latch may Bind and not Latch

NHTSA Campaign Number: 17V358000

Manufacturer Hyundai Motor America

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 437,400

## **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2013-2017 Santa Fe and Santa Fe Sport vehicles. In the affected vehicles, the secondary hood latch actuating cable may corrode and bind, causing the secondary hood latch to remain in the unlatched position when the hood is closed.

## Remedy

Hyundai will notify owners, and dealers will replace the secondary latch cable, free of charge. The recall is expected to begin June 30, 2017. Owner's may contact Hyundai customer service at 1-855-671-3059. Hyundai's number for the recall is 163.

#### **Vehicles**

#### MAKE MODEL YEAR

HYUNDAI SANTA FE 2013-2017 HYUNDAI SANTA FE SPORT 2013-2017

## Parking Brake Indicator may not Illuminate

NHTSA Campaign Number: 17V359000

Manufacturer Hyundai Motor America

Components PARKING BRAKE

**Potential Number of Units Affected 161,074** 

## **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2015-2016 Sonata and Genesis vehicles. In the affected vehicles, the SL Corporation warning light to indicate that the parking brake is applied may intermittently not illuminate in the dash due to corrosion in the switch.

# Remedy

Hyundai will notify owners, and dealers will replace the parking brake switch, free of charge. The recall is expected to begin on June 30, 2017. Owners may contact Hyundai customer service at 1-855-671-3059. Hyundai's number for this recall is 164.

## **Vehicles**

MAKE MODEL YEAR

HYUNDAI GENESIS 2015-2016 HYUNDAI SONATA 2015-2016

Ball Joint may Separate from Control Arm

NHTSA Campaign Number: 17V355000

**Manufacturer** Mazda North American Operations

**Components SUSPENSION** 

Potential Number of Units Affected 35.332

**Summary** 

Mazda North American Operations (Mazda) is recalling certain 2004 Mazda RX-8 vehicles. The Y-TEC ball joint socket on the front suspension lower control arm may crack and the ball joint may separate from the socket.

# Remedy

Mazda will notify owners, and dealers will replace the front lower control arms, free of charge. The recall is expected to begin July 30, 2017. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 1117E.

## Vehicle

MAKE MODEL YEAR

MAZDA RX-8 2004

No Warning if Front Turn Signals Fail/FMVSS 108

NHTSA Campaign Number: 17V341000

Manufacturer Jaguar Land Rover North America, LLC

**Components EXTERIOR LIGHTING** 

**Potential Number of Units Affected 18** 

## **Summary**

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2018 Jaguar F-TYPE vehicles equipped with Automotive Lighting Reutlingen Highline headlamps. If a front turn signal indicator stops working, the visual and audible turn signal reminders do not flash or chime faster as required. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, reflective devices, and associated equipment."

## Remedy

Jaguar will notify owners, and dealers will update the vehicle's software, free of charge. The recall is expected to begin on July 17, 2017. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H026.

#### Vehicle

MAKE MODEL YEAR

JAGUAR F-TYPE 2018