



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

December 25, 2017

### Inflator Component may Detach During Deployment

**NHTSA Campaign Number:** 17V784000

**Manufacturer** Kia Motors America

**Components** AIR BAGS

**Potential Number of Units Affected** 2,014

#### **Summary**

Kia Motors America (Kia) is recalling certain 2018 Kia Sorento vehicles. The Autoliv side curtain air bags on these vehicles have a component that may detach during deployment of the inflatable curtain air bag.

#### **Remedy**

Kia will notify owners, and dealers will replace the driver and passenger side curtain air bags, free of charge. The recall is expected to begin in December 2017. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC159.

#### **Vehicle**

**MAKE MODEL YEAR**

KIA SORENTO 2018

## Inflator Component may Detach During Deployment

**NHTSA Campaign Number:** 17V801000

**Manufacturer** Hyundai Motor America

**Components** AIR BAGS

**Potential Number of Units Affected** 1,201

### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2018 Santa Fe Sport vehicles. The Autoliv side curtain air bags on these vehicles have a component that may detach during deployment of the inflatable curtain air bag.

### **Remedy**

Hyundai will notify owners, and dealers will replace the driver and passenger side curtain air bags, free of charge. The recall is expected to begin February 9, 2018. Owners may contact Hyundai customer service at 1-855-671-3059. Hyundai's number for this recall is 171.

### **Vehicle**

MAKE	MODEL	YEAR
------	-------	------

HYUNDAI	SANTA FE SPORT	2018
---------	----------------	------

## Inflator Component may Detach During Deployment

**NHTSA Campaign Number:** 17V803000

**Manufacturer** Ford Motor Company

**Components** AIR BAGS

**Potential Number of Units Affected** 10,157

### **Summary**

Ford Motor Company (Ford) is recalling certain 2018 Ford Escape vehicles. The Autoliv side curtain air bags on these vehicles have a component that may detach during deployment of the inflatable curtain air bag.

## Remedy

Ford will notify owners, and dealers will replace the driver and passenger side curtain air bags, as necessary, free of charge. The recall is expected to begin January 29, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17S44.

## Vehicle

### MAKE MODEL YEAR

FORD ESCAPE 2018

## Driver Side Air Bag Inflator May Rupture

**NHTSA Campaign Number:** 17V787000

**Manufacturer** Ford Motor Company

**Components** AIR BAGS

**Potential Number of Units Affected** 361,523

## Summary

Ford Motor Company (Ford) is superseding a previous recall for certain 2004-2006 Ford Ranger trucks to implement a final repair. Upon deployment of the Takata driver side frontal air bag, excessive internal pressure may cause the inflator to rupture.

## Remedy

Ford will notify owners, and dealers will replace the driver's frontal air bag inflator with an alternate inflator, free of charge. The recall is expected to begin December 26, 2017, and will be launched in phases through the end of March 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17S42. Note: This recall supersedes recall 16V-036 which was an interim repair. Vehicles that received a replacement air bag inflator under the previous campaign need to return to a dealer to have an alternate inflator installed.

## Vehicle

### MAKE MODEL YEAR

FORD RANGER 2004-2006

## **Passenger Frontal Air Bag Inflator May Rupture**

**NHTSA Campaign Number:** 17V788000

**Manufacturer** Ford Motor Company

**Components** AIR BAGS

**Potential Number of Units Affected** 361,523

### **Summary**

Ford Motor Company (Ford) is superseding a previous recall for certain 2004-2006 Ford Ranger trucks to implement a final repair. Upon deployment of the Takata passenger side frontal air bag, excessive internal pressure may cause the inflator to rupture.

### **Remedy**

Ford will notify owners, and dealers will replace the passenger's frontal air bag inflator with an alternate inflator, free of charge. The recall is expected to begin December 26, 2017, and will be launched in phases through the end of March 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17S42. Note: This recall supersedes recall 15V322 which was an interim repair. Vehicles that received a replacement air bag inflator under the previous campaign need to return to a dealer to have an alternate inflator installed. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17S42.

### **Vehicle**

**MAKE MODEL YEAR**

FORD RANGER 2004-2006

## **Passenger Frontal Air Bag Inflator May Rupture**

**NHTSA Campaign Number:** 17V806000

**Manufacturer** Mazda North American Operations

**Components** AIR BAGS

**Potential Number of Units Affected** 19,781

## Summary

Mazda North American Operations (Mazda) is recalling certain 2004-2006 Mazda B-series trucks. Upon deployment of the Takata passenger side frontal air bag, excessive internal pressure may cause the inflator to rupture.

## Remedy

Mazda will notify owners, and dealers will replace the passenger side frontal air bag inflator with an alternate inflator, free of charge. The recall is expected to begin January 17, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 1817L. Note: This recall supersedes recall 15V-346. Vehicles that received a replacement air bag inflator under the previous campaign need to return to a dealer to have an alternate inflator installed.

## Vehicle

MAKE	MODEL	YEAR
------	-------	------

MAZDA	B-SERIES TRUCK	2004-2006
-------	----------------	-----------

## Driver Side Frontal Air Bag Inflator May Rupture

**NHTSA Campaign Number:** 17V807000

**Manufacturer** Mazda North American Operations

**Components** AIR BAGS

**Potential Number of Units Affected** 19,781

## Summary

Mazda North American Operations (Mazda) is recalling certain 2004-2006 B-Series trucks. Upon deployment of the Takata driver side frontal air bag, excessive internal pressure may cause the inflator to rupture.

## Remedy

Mazda will notify owners, and dealers will replace the driver's frontal air bag inflator with an alternate inflator, free of charge. The recall is expected to begin January 17, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 1917L. Note: This recall supersedes recall 16V-048. Vehicles that received a replacement air bag inflator under the previous campaign need to return to a dealer to have an alternate inflator installed.

**Vehicle**

MAKE	MODEL	YEAR
MAZDA	B-SERIES TRUCK	2004-2006