

NHTSA Recalls of Interest January 15, 2018

Seat Belt May Bind, Causing Slack

NHTSA Campaign Number: 17V826000

Manufacturer Mercedes-Benz USA, LLC.

Components SEAT BELTS

Potential Number of Units Affected 1,263

Summary

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain model year 2018 Mercedes-Benz AMG GT, AMG GT R, AMG GT C and AMG GT S vehicles. The seat belts may bind within the guidance loops possibly causing slack in the seat belts.

Remedy

MBUSA will notify owners, and dealers will reconfigure the seat belt guides, free of charge. Owners will be notified of the recall in January 2018 and they will receive a second letter when the parts become available, currently expected to be in February 2018. Owners may contact MBUSA customer service at 1-877-496-3691.

Vehicles

MAKE MODEL YEAR

MERCEDES BENZ AMG GT 2018 MERCEDES BENZ AMG GT C 2018 MERCEDES BENZ AMG GT R 2018 MERCEDES BENZ AMG GT S 2018

Inflator Component may Detach/FMVSS 214, 226

NHTSA Campaign Number: 17V837000

Manufacturer Nissan North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 111

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2018 Nissan Versa Note vehicles. During deployment of the side curtain air bag, a component of the air bag inflator may detach. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standards (FMVSS) number 214, "Side Impact Protection," and 226, "Ejection Mitigation."

Remedy

Nissan will notify owners, and dealers will replace the side curtain air bags, free of charge. The recall is expected to begin February 8, 2018. Owners may contact Nissan customer service at 1-800-647-7261.

Vehicle

MAKE MODEL YEAR

NISSAN VERSA NOTE 2018

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V022000

Manufacturer Ford Motor Company

Components AIR BAGS

Potential Number of Units Affected 2,700

Summary

Ford Motor Company (Ford) is recalling certain 2006 Ford Ranger trucks. Upon deployment of the passenger side frontal air bag, excessive internal pressure may cause the inflator to explode.

Remedy

Ford will notify owners, instructing them not to drive their vehicles. Dealers will replace the passenger's frontal air bag inflator with an alternate inflator, free of charge. The recall is expected to begin January 16, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18802.

Vehicle

MAKE MODEL YEAR

FORD RANGER 2006

Driver Side Air Bag Inflator May Explode

NHTSA Campaign Number: 18V023000

Manufacturer Ford Motor Company

Components AIR BAGS

Potential Number of Units Affected 2,700

Summary

Ford Motor Company (Ford) is recalling certain 2006 Ranger vehicles. Upon deployment of the driver side frontal air bag, excessive internal pressure may cause the inflator to explode.

Remedy

Ford will notify owners instructing them to not drive their vehicles, and dealers will replace the front driver side air bag inflator with an alternate inflator, free of charge. The recall is expected to begin January 16, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S02.

Vehicle

MAKE MODEL YEAR

FORD RANGER 2006