



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

February 12, 2018

Driver's Frontal Air Bag Inflator May Rupture

NHTSA Campaign Number: 18V082000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 97,440

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2009-2012 Audi Q5 and 2010-2012 Audi A5 Cabriolet and S5 Cabriolet vehicles. Upon deployment of the driver's frontal air bag, excessive internal pressure may cause the inflator to explode.

Remedy

Audi will notify owners, and dealers will replace the driver's frontal air bag inflator with an alternative inflator, free of charge. The recall is expected to begin February 13, 2018. Volkswagen's number for this recall is 69R6. Note: This recall partially supersedes recall 16V-078.

Vehicles

MAKE	MODEL	YEAR
AUDI	A5 CABRIOLET	2010-2012
AUDI	Q5	2009-2012
AUDI	S5 CABRIOLET	2010-2012

Sensor Failures May Prevent Air Bag Deployment

NHTSA Campaign Number: 18V085000

Manufacturer Toyota Motor Engineering & Manufacturing

Components AIR BAGS

Potential Number of Units Affected 48,672

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2016 Toyota Prius and Lexus RX 350, RX 350 F Sport, RX 450h F Sport and RX 450h vehicles and 2015-2016 Lexus NX 200T, NX Turbo and NX 300h vehicles. The air bag pressure sensors and/or the acceleration sensors may fail causing the side/curtain shield air bags and/or the front air bags to not deploy in the event of a crash.

Remedy

Toyota will notify owners, and dealers will replace the sensors as necessary based on their serial numbers, free of charge. The recall is expected to begin March 12, 2018. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's numbers for this recall are JLA, JOF.

Vehicles

MAKE	MODEL	YEAR
LEXUS	NX	2015-2016
LEXUS	RX350	2016
LEXUS	RX450H	2016
TOYOTA	PRIUS	2016

Brake Master Cylinder may Leak Fluid into Booster

NHTSA Campaign Number: 18V086000

Manufacturer Nissan North America, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 415

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2015-2017 Nissan Juke Nismo RS vehicles. Due to a problem within the Denso master cylinder, brake fluid may leak into the brake booster, reducing brake performance.

Remedy

Nissan will notify owners, and dealers will replace the brake master cylinder, free of charge. The recall is expected to begin March 19, 2018. Owners may contact Nissan customer service at 1-800-647-7261.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

NISSAN	JUKE	2015-2017
--------	------	-----------