



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

April 11, 2018

Loss of Power Steering Assist Due to Corrosion

NHTSA Campaign Number: 18V204000

Manufacturer Tesla, Inc.

Components STEERING

Potential Number of Units Affected 70,421

Summary

Tesla, Inc. (Tesla) is recalling certain 2012-2016 Tesla Model S vehicles equipped with Bosch steering racks. The aluminum bolts that attach the power steering gear assist motor to the gear housing may corrode and fracture causing a reduction or complete loss of power steering assist.

Remedy

Tesla will notify owners, and Tesla Service Centers will replace the steering gear mounting bolts and add a corrosion-preventative sealer, free of charge. The recall is expected to begin March 29, 2018. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-18-32-002.

Vehicle

MAKE MODEL YEAR

TESLA MODEL S 2012-2016

Missing Roll Pin Causing Loss of Park Function

NHTSA Campaign Number: 18V213000

Manufacturer Ford Motor Company

Components POWER TRAIN

Potential Number of Units Affected 142

Summary

Ford Motor Company (Ford) is recalling certain 2017-2018 Ford F-150 and 2018 Ford Expedition and Mustang and Lincoln Navigator vehicles equipped with 10-speed automatic transmissions. A roll pin may not have been installed in the transmission, potentially causing a loss of the "Park" function.

Remedy

Ford will notify owners, and dealers will inspect the transmission to make sure it has the roll pin, installing one if it is missing, free of charge. The recall is expected to begin April 16, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S09.

Vehicles

MAKE	MODEL	YEAR
FORD	EXPEDITION	2018
FORD	F-150	2017-2018
FORD	MUSTANG	2018
LINCOLN	NAVIGATOR	2018