



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

April 30, 2018

Left Rear Frame Section May Corrode

NHTSA Campaign Number: 18V231000

Manufacturer Chrysler (FCA US LLC)

Components STRUCTURE, SEATS

Potential Number of Units Affected 106

Summary

Chrysler (FCA US LLC) is recalling certain 2018 Jeep Wrangler vehicles. The rear under body ladder rail may corrode, possibly reducing the strength of the rear floor pan and causing the left rear seat mount to become loose.

Remedy

The remedy for this recall is still under development. The recall is expected to begin June 1, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U27.

Vehicle

MAKE MODEL YEAR

JEEP WRANGLER 2018

Brake Switch May Detach

NHTSA Campaign Number: 18V235000

Manufacturer Isuzu Technical Center of America, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 80

Summary

Isuzu Technical Center of America, Inc. (Isuzu) is recalling certain 2018 Isuzu NPR and 2019 Isuzu NPR-HD and NPR-XD vehicles. These vehicles have a brake switch and nylon retainer that may not have been properly secured into the steel brake pedal assembly bracket.

Remedy

Isuzu has notified owners, and dealers will inspect the seating of the retainer, and re-seat the retainer clip or replace the retainer clip, if necessary, free of charge. The recall began on April 24, 2018. Owners may contact Isuzu customer service at 1-866-441-9638. Isuzu's number for this recall is V1801.

Vehicles

MAKE MODEL YEAR

ISUZU NPR 2018

ISUZU NPR HD 2019

ISUZU NPR XD 2019