

NHTSA Recalls of Interest June 18, 2018

Seat Back Frame Joint Improperly Welded

NHTSA Campaign Number: 18V342000

Manufacturer General Motors LLC

Components SEATS

Potential Number of Units Affected 71

Summary

General Motors LLC (GM) is recalling certain 2018 Chevrolet Sonic vehicles. A joint in the Fisher Dynamics driver's seat-back frame may not be properly welded, reducing the strength of the seat-back frame.

Remedy

GM will notify owners, and dealers will replace the driver's seat-back, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is 18178.

Vehicle

MAKE MODEL YEAR

CHEVROLET SONIC 2018

Passenger's Air Bag May Deploy Improperly

NHTSA Campaign Number: 18V370000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 139,249

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2013-2018 Audi S6 and S7, 2012-2018 A7 and A6 Sedan, and 2014-2018 RS7 vehicles equipped with Lear Corporation basic seats (with or without heating). Stress or wear of the body-sensing mat within the front passenger seat may cause the Passenger Occupant Detection System (PODS) control module to malfunction.

Remedy

Volkswagen will notify owners, and dealers will install a PODS system repair kit, free of charge. The recall is expected to begin July 31, 2018. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 74D5.

Vehicles

MAKE MODEL YEAR

| AUDI | A6 | 2012-2018 |
|------|------------|-----------|
| AUDI | A7 | 2012-2018 |
| AUDI | RS7 | 2014-2018 |
| AUDI | S 6 | 2013-2018 |
| AUDI | S 7 | 2013-2018 |

Certain Child Seats May Damage Seat Belt Buckles

NHTSA Campaign Number: 18V380000

Manufacturer Volkswagen Group of America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 54,537

Summary

Volkswagen Group of America, Inc. (Volkswaen) is recalling certain 2018 Volkswagen Atlas vehicles. The owner's manuals provided with the affected vehicles do not inform the customers about the child restraint size limitation/restrictions for the second row center seating position. As a result, the center and adjacent outboard seat belt buckles on the second row can become damaged it a child seat base is installed that is wider than 12.6 inches.

Remedy

Volkswagen will notify owners, and dealers will inspect the center and left outboard seat belt buckles, and replace them if necessary, free of charge. Volkswagen will also provide an owner's manual supplement addressing child safety and child restraints. The recall is expected to begin August 3, 2018. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 69X1.

Vehicle

MAKE MODEL YEAR

VOLKSWAGEN ATLAS 2018

Fuel Gauge Reads Lower than Actual Level

NHTSA Campaign Number: 18V337000

Manufacturer Jaguar Land Rover North America, LLC

Components FUEL SYSTEM, GASOLINE, ELECTRICAL SYSTEM

Potential Number of Units Affected 1,917

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2017 Land Rover Range Rover, Range Rover Sport, and Discovery vehicles. The Lear Corporation fuel gauge on these vehicles may indicate that the fuel level is low and illuminate the warning lamp, when the fuel tank actually has more fuel. The engine management software may also cut off the engine when the vehicle has traveled approximately 17 more miles.

Remedy

Land Rover will notify owners, and dealers will install a software update to correct the fuel level reading, free of charge. The recall is expected to begin July 16, 2018. Owners may Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N206.

Vehicles

| MAKE | MODEL | YEAR |
|-----------|-------------------|----------|
| | | |
| LAND ROVE | R DISCOVERY | 2017 |
| LAND ROVE | R RANGE ROVER | 2017 |
| LAND ROVE | R RANGE ROVER SPO | ORT 2017 |