



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

June 4, 2018

Sensing Module may not Power Down Correctly

NHTSA Campaign Number: 18V340000

Manufacturer General Motors LLC

Components AIR BAGS

Potential Number of Units Affected 88,129

Summary

General Motors LLC (GM) is recalling certain 2018 GMC Terrain vehicles. The Veoneer sensing diagnostic module (SDM) that senses a crash and deploys the necessary air bags may not power down correctly when the vehicle is shut off, causing it to be inoperative when the vehicle is restarted.

Remedy

GM will notify owners, and dealers will reprogram the SDM with updated software, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact GMC customer service at 1-800-462-8782. GM's number for this recall is 18179.

Vehicle

MAKE MODEL YEAR

GMC TERRAIN 2018

Power Sliding Door may not Auto-Reverse

NHTSA Campaign Number: 18V338000

Manufacturer Kia Motors America

Components STRUCTURE, ELECTRICAL SYSTEM

Potential Number of Units Affected 106,428

Summary

Kia Motors America (Kia) is recalling certain 2015-2018 Kia Sedona vehicles equipped with a STRATTEC power sliding door (PSD). The PSD may not auto-reverse when its closing is obstructed.

Remedy

Kia will notify owners, and dealers will reprogram the PSD module software, free of charge. The recall is expected to begin June 18, 2018. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC164.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

KIA	SEDONA	2015-2018
-----	--------	-----------

Control Unit may Fail

NHTSA Campaign Number: 18V318000

Manufacturer Porsche Cars North America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 3

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2018 Porsche Macan S and Macan vehicles. These vehicles have a Conti Temic control unit that may fail and prevent safety-related functions such as driver display alerts and possibly impair drivability and post-crash functions.

Remedy

Porsche will notify owners, and dealers will replace the affected control unit, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AJ05.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

PORSCHE	MACAN	2018
---------	-------	------

PORSCHE	MACAN S	2018
---------	---------	------

D-ring Bolt on Seat Belt May Break/FMVSS 210

NHTSA Campaign Number: 18V293000

Manufacturer Navistar, Inc.

Components SEAT BELTS

Potential Number of Units Affected 18,665

Summary

Navistar, Inc. (Navistar) is recalling certain 2018-2019 International WorkStar, DuraStar, LoneStar, LT, ProStar, RH and IC Bus HC, 2018 International TranStar, 2019 International HV and MV trucks and transit buses. The front driver and passenger seat belt anchor D-ring bolt may break in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 210, "Seat Belt Assembly Anchorages."

Remedy

Navistar has notified owners, and dealers will replace the Shield D-ring bolt depending on the information found on the seat belt label, free of charge. The recall began May 23, 2018. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 18505.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

IC BUS	HC	2018-2019
--------	----	-----------

INTERNATIONAL	DURASTAR	2018-2019
---------------	----------	-----------

INTERNATIONAL	HV	2019
---------------	----	------

INTERNATIONAL	LONESTAR	2018-2019
---------------	----------	-----------

MAKE	MODEL	YEAR
INTERNATIONAL	LT	2018-2019
INTERNATIONAL	MV	2019
INTERNATIONAL	PROSTAR	2018-2019
INTERNATIONAL	RH	2018-2019
INTERNATIONAL	TRANSTAR	2018
INTERNATIONAL	WORKSTAR	2018-2019

Lower Ball Joint Separation

NHTSA Campaign Number: 18V324000

Manufacturer Volkswagen Group of America, Inc.

Components SUSPENSION

Potential Number of Units Affected 360

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Volkswagen Tiguan long wheel base (LWB) vehicles. The nut that holds the lower ball joint of the front wheel on each side of the vehicle may be loose or improperly tightened.

Remedy

Volkswagen has notified owners, and dealers will replace the nut on the lower ball joint, free of charge. The recall began May 30, 2018. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 40N4. Note: owners are advised not to drive their vehicle until the recall repair has been performed.

Vehicle

MAKE	MODEL	YEAR
VOLKSWAGEN	TIGUAN	2018