



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest September 3, 2018

Ignition Switch May Turn Off

NHTSA Campaign Number: 18V551000

Manufacturer Nissan North America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 153,047

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2017 Nissan NV200, Sentra, NV3500 Van, NV3500 Bus, NV200 Taxi, NV1500, NV2500 Van, Chevrolet City Express, 2017-2018 Frontier, Versa Note, and Versa Sedan vehicles that have a mechanical (physical) key ignition system. In these models, over time, the weight on the key ring and road conditions or some other jarring event may cause the ignition switch to move out of the run position to the accessory position, turning off the engine.

Remedy

Nissan will notify owners, and dealers will inspect the production information on the ignition switch, and replace it as necessary, free of charge. The recall is expected to begin October 19, 2018. Owners may contact Nissan customer service at 1-800-867-7669.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	CITY EXPRESS	2017
NISSAN	FRONTIER	2017-2018
NISSAN	NV1500	2017
NISSAN	NV200	2017
NISSAN	NV200 TAXI	2017
NISSAN	NV2500	2017
NISSAN	NV3500	2017
NISSAN	SENTRA	2017
NISSAN	VERSA	2017-2018
NISSAN	VERSA NOTE	2017-2018

Insufficient Coating on Rear Brake Caliper Pistons

NHTSA Campaign Number: 18V539000

Manufacturer Mercedes-Benz USA, LLC.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 9,044

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2018 Mercedes-Benz GLE350 4Matic, GLE350, GLS450 4Matic, GLS550 4matic, GLE43 AMG 4Matic, GLE63 AMG 4Matic, GLE63S AMG 4Matic, and GLS63 AMG 4Matic vehicles. The ZF rear brake caliper pistons on these vehicles may not have been correctly coated, causing gas to become temporarily released into the rear brake hydraulic circuit, reducing braking performance.

Remedy

MBUSA will notify owners, and dealers will bleed the rear axle brake system, free of charge. The recall is expected to begin in early September 2018. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2018080013.

Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	GLE350	2018
MERCEDES BENZ	GLE43	2018
MERCEDES BENZ	GLE63	2018
MERCEDES BENZ	GLE63S	2018
MERCEDES BENZ	GLS450	2018
MERCEDES BENZ	GLS550	2018
MERCEDES BENZ	GLS63	2018

Missing Rear Seat Back Lock Strikers

NHTSA Campaign Number: 18V535000

Manufacturer Volvo Car USA LLC

Components SEATS

Potential Number of Units Affected 25

Summary

Volvo Cars USA LLC (Volvo) is recalling certain 2019 Volvo XC40 vehicles. The rear seats may not have rear seat back lock strikers, allowing the seat back to move forward during certain hard braking conditions or a crash.

Remedy

Volvo will notify owners, and dealers will inspect the vehicles and install the seat back lock strikers if they are missing, free of charge. The recall is expected to begin October 15, 2018. Owners may contact Volvo customer service at 1-800-458-1552. Volvo's number for this recall is R89898.

Vehicle

MAKE	MODEL	YEAR
VOLVO	XC40	2019

Incorrect Turn Signal Flash Pattern/FMVSS 108

NHTSA Campaign Number: 18V511000

Manufacturer Gillig LLC

Components EXTERIOR LIGHTING

Potential Number of Units Affected 178

Summary

Gillig LLC (Gillig) is recalling certain 2012-2018 Gillig Low Floor vehicles. The front and rear turn signals on these vehicles may flash at different rates, potentially confusing other drivers of the vehicle's intention. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Gillig will notify the owner of the buses, and dealers will reprogram the turn signals with new software, free of charge. The recall is expected to begin in September 2018. Owners may contact Gillig customer service at 1-510-264-5073 or 1-800-735-1500.

Vehicle

MAKE MODEL YEAR

GILLIG LOW FLOOR 2012-2018