



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

October 8, 2018

Insufficient Limitation of Front Passenger Seat

NHTSA Campaign Number: 18V609000

Manufacturer Mercedes-Benz USA, LLC.

Components SEATS

Potential Number of Units Affected 22

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2018 Mercedes-Benz E63S AMG 4MATIC vehicles. The front passenger seat can be adjusted beyond its intended limit.

Remedy

MBUSA will notify owners, and dealers will inspect the adjustment range, and if needed, install a mechanical adjustment range limitation or update the seat control unit software, free of charge. The recall is expected to begin October 19, 2018. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

MERCEDES BENZ	E63S AMG	2018
---------------	----------	------

Autonomous Emergency Braking System Failure

NHTSA Campaign Number: 18V625000

Manufacturer Jaguar Land Rover North America, LLC

Components FORWARD COLLISION AVOIDANCE

Potential Number of Units Affected 86

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2018 Land Rover Range Rover, Land Rover Range Rover Sport and Land Rover Discovery vehicles. The Bosch Autonomous Emergency Braking (AEB) system may be disabled without warning the driver that the system is not functional.

Remedy

Land Rover will notify owners, and dealers will update the vehicle software, free of charge. The recall is expected to begin November 9, 2018. Owners may contact Land Rover customer service at 1-800-637-6837, Option 9. Land Rover's number for this recall is N227.

Vehicles

MAKE	MODEL	YEAR
LAND ROVER	DISCOVERY	2018
LAND ROVER	RANGE ROVER	2018
LAND ROVER	RANGE ROVER SPORT	2018

Electronic Parking Brake May Fail

NHTSA Campaign Number: 18V626000

Manufacturer Subaru of America, Inc.

Components PARKING BRAKE

Potential Number of Units Affected 27,175

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2010-2014 Subaru Legacy and Outback vehicles equipped with a manual transmission. The Continental electronic parking brake (EPB) may not engage as intended, allowing the vehicle to rollaway if the transmission is not in the proper gear when parked.

Remedy

Subaru will notify owners, and dealers will replace the EPB actuator assembly, free of charge. The recall is scheduled to begin November 7, 2018. Owners may contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is WTV-81.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

SUBARU	LEGACY	2010-2014
--------	--------	-----------

SUBARU	OUTBACK	2010-2014
--------	---------	-----------

Wire Harness Damage Causing Failure/FMVSS 108, 123

NHTSA Campaign Number: 18V630000

Manufacturer Honda (American Honda Motor Co.)

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 505

Summary

Honda (American Honda Motor Co.) is recalling certain 2018 Honda CRF250L motorcycles. The SEWS wiring harness may have been inappropriately installed, potentially resulting in damage to the wiring harness and affecting the operation of safety components such as the exterior lighting, horn, and instrument panel. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment," and 123, "Motorcycle Control Displays."

Remedy

Honda will notify owners, and dealers will inspect the wiring harness, replacing it as necessary, free of charge. The recall is expected to begin November 5, 2018. Owners may contact Honda customer service at 1-866-784-1870. Honda's number for this recall is KJ7.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

HONDA	CRF250L	2018
-------	---------	------

Steering Column may Separate

NHTSA Campaign Number: 18V656000

Manufacturer Kia Motors America

Components STEERING

Potential Number of Units Affected 97

Summary

Kia Motors America (Kia) is recalling certain 2018 Kia Sorento vehicles. The Sewon cowl crossbar that connects to the Motor Driven Power Steering (MDPS) steering column may be improperly welded, allowing the steering column to separate.

Remedy

Kia will notify owners, and dealers will replace the cowl crossbar, free of charge. The recall is expected to begin October 26, 2018. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC167.

Vehicle

MAKE MODEL YEAR

KIA SORENTO 2018

Electrical Resistance at Main Relay May Cause Fire

NHTSA Campaign Number: 18V666000

Manufacturer Kia Motors America

Components HYBRID PROPULSION SYSTEM

Potential Number of Units Affected 27,030

Summary

Kia Motors America (Kia) is recalling certain 2017-2018 Kia Niro hybrid electric vehicles. The LS IS Co. Main Relay within the Power Relay Assembly (PRA) may have inadequate connections between its contacts, causing increased electrical resistance.

Remedy

Kia will notify owners, and dealers will inspect the Power Relay Assembly (PRA) for damage. If no damage is found, the main relay will be replaced. If damage is found, the PRA will be replaced. These repairs will be performed free of charge. The recall is expected to begin November 23, 2018. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC168.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

KIA	NIRO	2017-2018
-----	------	-----------