



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

November 12, 2018

[Seat Belt May Not Restrain Occupant/FMVSS 209](#)

NHTSA Campaign Number: 18V751000

Manufacturer Porsche Cars North America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 415

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2019 Porsche Cayenne vehicles. The passenger side Joyson rear seat belt buckle may break under load, such as in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 209, "Seat Belt Assemblies."

Remedy

Porsche will notify owners, and dealers will replace the passenger rear seat belt buckle, free of charge. The recall is expected to begin December 23, 2018. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AJ09.

Vehicle

MAKE MODEL YEAR

PORSCHE CAYENNE 2019

Wiring Harness may be Damaged by Fender

NHTSA Campaign Number: 18V754000

Manufacturer Kia Motors America

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 16,011

Summary

Kia Motors America (Kia) is recalling certain 2018 Kia Stinger vehicles. The front wiring harness located in the engine and passenger compartment may get damaged from contacting a burr on the left fender body panel.

Remedy

Kia will notify owners, and dealers will inspect the wiring harness for damage. If no damage is found, a cover will be installed. If damage is found, the wiring harness will be repaired and a cover will be installed, free of charge. The recall is expected to begin December 20, 2018. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall SC170.

Vehicle

MAKE MODEL YEAR

KIA STINGER 2018

Incorrect Door Lever Prevents Door From Opening

NHTSA Campaign Number: 18V743000

Manufacturer Daimler Vans USA, LLC

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 76

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2018 Freightliner Sprinter 2500 and 3500 and Mercedes-Benz Sprinter 2500 and 3500 vehicles. The Kiekert right side door latches may have been built with incorrect components. As a result, when the doors are electronically unlocked, the right-side doors may not be able to be opened from inside or outside of the vehicle.

Remedy

DVUSA will notify owners, and dealers will inspect and replace the locks if necessary, free of charge. The recall is expected to begin December 11, 2018. Owners may contact DVUSA at 1-877-762-8267.

Vehicles

MAKE	MODEL	YEAR
FREIGHTLINER	SPRINTER 2500	2018
FREIGHTLINER	SPRINTER 3500	2018
MERCEDES BENZ	SPRINTER 2500	2018
MERCEDES BENZ	SPRINTER 3500	2018