



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

November 26, 2018

### [Air Bags may not Deploy Due to Incorrect Setting](#)

**NHTSA Campaign Number:** 18V774000

**Manufacturer** General Motors LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 12

#### **Summary**

General Motors LLC (GM) is recalling certain 2019 Buick Encore, Chevrolet Spark, Traverse, and Trax vehicles. The Sensing Diagnostic Module (SDM) on these vehicle may not have been turned off of "manufacturing mode," preventing the air bags from deploying in the event of a crash.

#### **Remedy**

GM will notify owners, and dealers will reprogram the SDM module to the correct mode, free of charge. The recall began November 6, 2018. Owners may contact Buick customer service at 1-800-521-7300 and Chevrolet customer service at 1-800-222-1020. GM's number for this recall is 18365.

#### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
BUICK	ENCORE	2019
CHEVROLET	SPARK	2019
CHEVROLET	TRAVERSE	2019
CHEVROLET	TRAX	2019

## Out of Position Door Latch may cause Door to Open

**NHTSA Campaign Number:** 18V786000

**Manufacturer** Chrysler (FCA US LLC)

**Components** LATCHES/LOCKS/LINKAGES

**Potential Number of Units Affected** 52

### **Summary**

Chrysler (FCA US LLC) is recalling certain 2018 Jeep Wrangler four-door vehicles. The right rear passenger door latch may not be in the correct location, possibly preventing the door from latching properly.

### **Remedy**

Chrysler will notify owners, and dealers will repair the right rear door latch reinforcement, free of charge. The recall is expected to begin December 28, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is UB6.

### **Vehicle**

**MAKE MODEL YEAR**

JEEP WRANGLER 2018

## Power Sliding Doors May Open While Moving

**NHTSA Campaign Number:** 18V795000

**Manufacturer** Honda (American Honda Motor Co.)

**Components** LATCHES/LOCKS/LINKAGES

**Potential Number of Units Affected** 107,774

### **Summary**

Honda (American Honda Motor Co.) is recalling certain model year 2018 and 2019 Honda Odyssey vehicles. The Gecom latch assemblies for the power sliding doors may stick and not properly latch to the door strikers.

### **Remedy**

Honda will notify owners, and dealers will replace the left and right power sliding door rear latch assemblies, free of charge. The recall is expected to begin December 20, 2018. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are Z33 and O36.

## Vehicle

**MAKE MODEL YEAR**

HONDA ODYSSEY 2018-2019

## Fuel Pressure Sensor may Leak Fuel

**NHTSA Campaign Number:** 18V807000

**Manufacturer** Ford Motor Company

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 144

### Summary

Ford Motor Company (Ford) is recalling certain 2018 Ford Explorer vehicles equipped with 2.3L or 3.5L GTDI engine. Due to an assembly error, the Plastic Omnium fuel pressure sensor may leak fuel.

### Remedy

Ford will notify owners, and dealers will replace the fuel line assembly, free of charge. The recall is expected to begin December 3, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S35.

## Vehicle

**MAKE MODEL YEAR**

FORD EXPLORER 2018