



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

### Left Hand Door May Remain Unlatched and Open

**NHTSA Campaign Number:** 19V390000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** LATCHES/LOCKS/LINKAGES

**Potential Number of Units Affected** 28,671

#### Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2016 Range Rover and Range Rover Sport vehicles. A spring in the Keyless Vehicle Latching System (KV Latch) may get stuck, causing the left hand door to remain unlatched when the door is closed.

#### Remedy

Land Rover will notify owners, and dealers will replace the left hand side door latch assembly, free of charge. Interim notices informing owners of the safety risk will be mailed July 19, 2019. Owners will receive a second notice when the remedy becomes available. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N336.

#### Vehicles

| MAKE       | MODEL             | YEAR |
|------------|-------------------|------|
| LAND ROVER | RANGE ROVER       | 2016 |
| LAND ROVER | RANGE ROVER SPORT | 2016 |

## Unintentional Rollaway Due to Detached Shift Cable

**NHTSA Campaign Number:** 19V446000

**Manufacturer** Porsche Cars North America, Inc.

**Components** POWER TRAIN

**Potential Number of Units Affected** 99,665

### **Summary**

Porsche Cars North America, Inc. (Porsche) is recalling certain 2003-2006 Cayenne S, Cayenne Turbo, 2004-2010 Cayenne, 2006 Cayenne Turbo S, 2010-2016 Panamera S, Panamera 4 S, Panamera Turbo, 2011-2016 Panamera, Panamera 4, 2012-2013 Panamera Turbo S, 2013-2016 Panamera 4 GTS, 2014-2016 Panamera 4 S Executive, Panamera Turbo Executive, Panamera Turbo S G1 II, Panamera Turbo S Executive, 2013 Panamera 4 Platinum Edition, Panamera Platinum Edition, 2016 Panamera 4 Edition, Panamera Edition, Panamera Turbo S Executive Luxury Sports vehicles.

The bushing that attaches the gear selector lever to the gearbox may degrade over time, causing the bushing to detach. This condition could allow the driver to move the shift lever to Park and remove the ignition key, while the transmission may not be in Park, with no warning message or audible chime.

### **Remedy**

Porsche will notify owners, and dealers will replace the shifter cable bushing, free of charge. Owners are instructed to use the parking brake until their vehicle is repaired. The recall is expected to begin August 11, 2019. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AKB1.

### **Vehicles**

| MAKE                     | MODEL | YEAR                 |
|--------------------------|-------|----------------------|
| PORSCHE CAYENNE          |       | 2004-2006, 2008-2010 |
| PORSCHE CAYENNE S        |       | 2003-2006            |
| PORSCHE CAYENNE TURBO    |       | 2003-2006            |
| PORSCHE CAYENNE TURBO S  |       | 2006                 |
| PORSCHE PANAMERA         |       | 2011-2016            |
| PORSCHE PANAMERA 4       |       | 2011-2016            |
| PORSCHE PANAMERA 4S      |       | 2010-2016            |
| PORSCHE PANAMERA GTS     |       | 2013-2016            |
| PORSCHE PANAMERA S       |       | 2010-2016            |
| PORSCHE PANAMERA TURBO   |       | 2010-2016            |
| PORSCHE PANAMERA TURBO S |       | 2012-2016            |