



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

July 1, 2019

Doors May Unexpectedly Open

NHTSA Campaign Number: 19V392000

Manufacturer Jaguar Land Rover North America, LLC

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 65,385

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2013-2016 Range Rover and 2014-2016 Range Rover Sport vehicles. Due to a problem with the Keyless Vehicle Latching System (KV Latch), the doors may appear to be closed but may be unlatched.

Remedy

Land Rover will notify owners, and dealers will inspect for any issues with the KV system, disabling the KV mechanisms if necessary, and update the KV Latch software, free of charge. The recall is expected to begin July 19, 2019. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N335. Note: Vehicles in this recall were previously recalled under recall number 15V-385 and need to be remedied again.

Vehicles

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2013-2016
LAND ROVER	RANGE ROVER SPORT	2014-2016

Weak Retention Force of Wiring Harness Connectors

NHTSA Campaign Number: 19V403000

Manufacturer Mazda North American Operations

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 7,854

Summary

Mazda North American Operations (Mazda) is recalling certain 2018 CX-9 vehicles. The wiring harness may disrupt electrical communications and disable the passenger frontal air bag, turn signals, and/or engine starting system.

Remedy

Mazda will notify owners, and dealers will repair the wiring harnesses, free of charge. The recall is expected to begin on or before July 29, 2019. Owners may contact Mazda customer service at 1-800-222-5500, Option 4. Mazda's number for this recall is 3419E.

Vehicle

MAKE MODEL YEAR

MAZDA CX-9 2018

Air Bag ECU May Malfunction

NHTSA Campaign Number: 19V411000

Manufacturer Ferrari North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 893

Summary

Ferrari North America, Inc. (Ferrari) is recalling certain 2018 488 Spider, 488 Pista, 2015 458 Speciale A, 2016-2018 488 GTB, 2015-2017 F12 Berlinetta, 2016 F12 tdf, and 2016-2018 California T vehicles. The air bag Electronic Control Unit (ECU) may malfunction, possibly causing the non-deployment or improper deployment of the air bags and/or seat belt pretensioners.

Remedy

Ferrari will notify owners, and dealers will replace the air bag ECU, free of charge. The recall is expected to begin August 7, 2019. Owners may contact Ferrari customer service at 1-201-816-2668. Ferrari's number for this recall is 70.

Vehicles

MAKE	MODEL	YEAR
FERRARI	458 SPECIALE A	2015
FERRARI	488 GTB	2016-2018
FERRARI	488 PISTA	2018
FERRARI	488 SPIDER	2018
FERRARI	CALIFORNIA T	2016-2018
FERRARI	F12 BERLINETTA	2015-2017
FERRARI	F12 TDF	2016

Air Bags May Not Deploy Properly

NHTSA Campaign Number: 19V461000

Manufacturer Maserati North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 739

Summary

Maserati North America, Inc. (Maserati) is recalling certain 2015-2018 Granturismo and 2016-2018 Granturismo Convertible vehicles. The air bag Electronic Control Unit (ECU) may have a defective power supply capacitor that can cause a deactivation or inadvertent deployment of the air bag.

Remedy

Maserati will notify owners, and dealers will replace the air bag ECU, free of charge. The recall is expected to begin July 30, 2019. Owners may contact Maserati customer service at 1-877-696-2737. Maserati's number for this recall is 386.

Vehicle

MAKE	MODEL	YEAR
MASERATI	GRANTURISMO	2015-2018

Passenger Air Bag May Deactivate

NHTSA Campaign Number: 19V474000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 138,896

Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2015-2016 Audi S3 Sedan, 2015-2019 A3 Sedan and A3 Cabriolet, 2016-2018 A3 e-tron, and 2017-2019 RS3 vehicles. An improper electrical contact may cause the Passenger Occupant Detection System (PODS) to falsely detect a malfunction and deactivate the passenger air bag.

Remedy

Audi will notify owners, and dealers will replace the connector and reroute the cable, free of charge. The recall is expected to begin August 18, 2019. Owners may contact Volkswagen customer service at 1-800-253-2834. Audi's number for this recall is 69Z4.

Vehicles

MAKE	MODEL	YEAR
AUDI	A3	2015-2019
AUDI	A3 ETRON	2016-2018
AUDI	RS3	2017-2019
AUDI	S3	2015-2016

Passenger Seat Improperly Manufactured

NHTSA Campaign Number: 19V415000

Manufacturer Volkswagen Group of America, Inc.

Components SEATS

Potential Number of Units Affected 66

Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2019 Audi A8 vehicles equipped with rear relaxation seats. The front passenger seat track rivet may fail and cause the spindle bracket to separate.

Remedy

Audi will notify owners, and dealers will replace the passenger seat tracks, free of charge. The recall is expected to begin August 2, 2019. Owners may contact Volkswagen customer service at 1-800-253-2834. Audi's number for this recall is 72J3.

Vehicle

MAKE MODEL YEAR

AUDI A8 2019

No Indicator For Failed Turn Signal

NHTSA Campaign Number: 19V385000

Manufacturer Volkswagen Group of America, Inc.

Components EXTERIOR LIGHTING

Potential Number of Units Affected 23,241

Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2016-2018 Audi Q3 vehicles equipped with LED headlights. An inoperable front turn signal may not illuminate an indicator, failing to alert the driver to the issue. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Audi will notify owners, and dealers will update the body control module (BCM), free of charge. The recall began June 21, 2019. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 97DK.

Vehicle

MAKE MODEL YEAR

AUDI Q3 2016-2018

Windshield Washers May Fail/FMVSS 104

NHTSA Campaign Number: 19V421000

Manufacturer Jaguar Land Rover North America, LLC

Components VISIBILITY

Potential Number of Units Affected 2,200

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2020 Range Rover Evoque vehicles. The fuse for the front and rear windshield washer system may fail and reduce driver visibility. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 104, "Windshield Wiping and Washing Systems."

Remedy

Land Rover will notify owners, and dealers will replace the fuse for the front and rear washer systems, free of charge. In addition, the Engine Junction Box lid will be replaced and an owner's manual insert will be added with the updated fuse rating information. The recall is expected to begin August 2, 2019. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N341.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

LAND ROVER	RANGE ROVER EVOQUE	2020
------------	--------------------	------