



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

July 22, 2019

### Improperly Assembled Front Passenger Seat Belt

**NHTSA Campaign Number:** 19V518000

**Manufacturer** Ford Motor Company

**Components** SEAT BELTS

**Potential Number of Units Affected** 7,579

#### **Summary**

Ford Motor Company (Ford) is recalling certain 2019 Ford Ranger vehicles with a SuperCab body style. The front passenger seat belt may have been improperly assembled.

#### **Remedy**

Ford will notify owners, and dealers will inspect and, if necessary, replace the right front seat belt assembly, free of charge. The recall is expected to begin July 29, 2019. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 19S23.

#### **Vehicle**

**MAKE MODEL YEAR**

FORD RANGER 2019

## Fuel Lines May Leak

**NHTSA Campaign Number:** 19V498000

**Manufacturer** Chrysler (FCA US LLC)

**Components** FUEL SYSTEM, DIESEL

**Potential Number of Units Affected** 498

### **Summary**

Chrysler (FCA US LLC) is recalling certain 2019 Ram 2500 and 3500 trucks, and 3500, 4500, and 5500 Cab Chassis vehicles equipped with diesel engines. The fuel lines may leak fuel into the engine compartment.

### **Remedy**

Chrysler will notify owners, and dealers will inspect the fuel lines, replacing them if necessary, free of charge. The recall is expected to begin August 16, 2019. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is V76.

### **Vehicles**

#### **MAKE MODEL YEAR**

RAM	2500	2019
RAM	3500	2019
RAM	4500	2019
RAM	5500	2019

## Alternator Harness may Short

**NHTSA Campaign Number:** 19V495000

**Manufacturer** Nissan North America, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 91,319

## Summary

Nissan North America, Inc. (Nissan) is recalling certain 2017-2019 gasoline, light duty, Titan vehicles. The alternator harness

may have been damaged during the engine installation process, possibly resulting in an electrical short.

## Remedy

Nissan will notify owners, and dealers will inspect the alternator harness for the proper routing and any damage. The harness will be clipped into the correct position or replaced as necessary, free of charge. The recall is expected to begin July 2019. Owners may contact Nissan customer service at 1-800-867-7669.

## Vehicle

**MAKE MODEL YEAR**

NISSAN TITAN 2017-2019

## [Back Up Camera Display Image may be Reversed](#)

**NHTSA Campaign Number:** 19V466000

**Manufacturer** SVO Group Inc

**Components** EQUIPMENT

**Potential Number of Units Affected** 52

## Summary

SVO Group Inc. (SVO Group) is recalling certain 2017-2018 Ford E-350 and E-450-based shuttle buses equipped with ASA Electronics Voyager monitors used to display the back-up camera image. The affected monitors may revert back to the factory default settings which may cause the camera image to be reversed.

## Remedy

SVO Group will work with ASA to notify owners, and ASA will provide a harness relay capacitor module to eliminate the image reversal, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact ASA Electronics customer service at 1-800-384-4400.

## Vehicles

**MAKE MODEL YEAR**

FORD E-350 2017-2018

FORD E-450 2017-2018

## 2nd Row Seats May Not Provide Crash Protection

**NHTSA Campaign Number:** 19V450000

**Manufacturer** Erwin Hymer Group North America, Inc.

**Components** SEATS

**Potential Number of Units Affected** 1,701

### **Summary**

Erwin Hymer Group North America, Inc. (Erwin Hymer) is recalling 2013-2019 Roadtrek E-Trek, RS Adventurous, CS Adventurous, and TS Adventurous motorhomes built on Sprinter chassis and equipped with one or two second row captain's chairs, with integrated seat belts. The seat pedestal base anchor brackets to the chassis frame may not have enough strength to prevent the seat and seat belt from moving in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 210, "Seat Belt Assembly Anchorages" and 207, "Seating Systems."

### **Remedy**

The recall began June 26, 2019. Owners may contact Erwin Hymer customer service at 1-844-464-3735. Erwin Hymer's number for this recall is 2019-01.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
ROADTREK	CS ADVENTUROUS	2013-2019
ROADTREK	E-TREK	2013-2019
ROADTREK	RS ADVENTUROUS	2013-2019
ROADTREK	TS ADVENTUROUS	2013-2016