



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

September 2, 2019

### Rear Center Headrest may Fold in a Crash

**NHTSA Campaign Number:** 19V600000

**Manufacturer** BMW of North America, LLC

**Components** SEATS

**Potential Number of Units Affected** 2

#### **Summary**

BMW of North America, LLC (BMW) is recalling one 2020 M340i and one M340i xDrive vehicle. Due to improper welding, the rear center headrest may fold in the event of a rear impact crash.

#### **Remedy**

BMW will notify owners, and dealers will replace the rear center headrest, free of charge. The recall is expected to begin October 7, 2019. Owners may contact BMW customer service at 1-800-525-7417.

#### **Vehicle**

##### **MAKE MODEL YEAR**

BMW M340I 2020

## Front Passenger Air Bag May Not Properly Inflate

**NHTSA Campaign Number:** 19V627000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** AIR BAGS

**Potential Number of Units Affected** 219,000

### **Summary**

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2003-2008 Corolla, 2005-2008 Corolla Matrix, and Pontiac Vibe vehicles equipped with a front passenger air bag assembly replaced under a prior recall. The air bag may not unfold as designed during inflation under high temperature conditions, possibly resulting in the air bag not inflating properly.

### **Remedy**

Toyota will notify their owners. Pontiac Vibe owners will be notified by GM. Dealers will replace the front passenger air bag assembly, free of charge. The recall is expected to begin September 25, 2019 for Toyota owners. Toyota owners may contact Toyota customer service at 1-888-270-9371. Toyota's numbers for this recall are K1Q and K0Q. Pontiac owners may contact GM customer service at 1-800-762-2737. GM's number for this recall is N192273760.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
PONTIAC	VIBE	2005-2008
TOYOTA	COROLLA	2003-2008
TOYOTA	COROLLA MATRIX	2005-2008

## Back-Up Camera May Not Display Image

**NHTSA Campaign Number:** 19V603000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 14,277

## Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2018 Range Rover and Range Rover Sport vehicles equipped with Continental Surround Camera Systems. The back-up camera system may fail to display the rearview image when the vehicle is in reverse.

## Remedy

Land Rover will notify owners, and dealers will reprogram the infotainment system display and camera software, free of charge. The recall is expected to begin October 14, 2019. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N367.

## Vehicles

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2018
LAND ROVER	RANGE ROVER SPORT	2018

## Incorrect Seat Belt Assemblies Installed/FMVSS 208

**NHTSA Campaign Number:** 19V594000

**Manufacturer** Kia Motors America

**Components** SEAT BELTS

**Potential Number of Units Affected** 30,168

## Summary

Kia Motors America (Kia) is recalling certain 2020 Telluride vehicles. The seat belt assemblies in the front passenger, second, and/or third row seats may not tightly secure a child restraint system in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

## Remedy

Kia will notify owners, and dealers will inspect the vehicles and replace any incorrect seat belt assemblies, free of charge. The recall is expected to begin August 30, 2019. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC181.

## Vehicle

MAKE	MODEL	YEAR
------	-------	------

KIA	TELLURIDE	2020
-----	-----------	------

## Brake Calipers May Corrode

**NHTSA Campaign Number:** 19V593000

**Manufacturer** BMW of North America, LLC

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 5,938

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2019 C 400 X, 2018-2020 G 310 GS, and 2017-2020 G 310 R scooters and motorcycles. The front and rear brake caliper pistons may corrode, possibly causing the piston to stick or drag in the caliper bore.

### **Remedy**

BMW will notify owners, and dealers will replace the front and rear brake calipers, free of charge. The recall is expected to begin October 4, 2019. Owners may contact BMW customer service at 1-800-525-7417.

### **Vehicles**

**MAKE MODEL YEAR**

BMW C 400 X 2019

BMW G310 GS 2018-2020

BMW G310R 2017-2020

## Blower Regulator Wiring May Overheat

**NHTSA Campaign Number:** 19V579000

**Manufacturer** BMW of North America, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 41,981

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2008-2012 BMW 128i, 135i, 135is Coupes and 128i, 135i Convertible vehicles. The wiring and electrical connectors in the blower-regulator wiring harness may overheat.

## Remedy

BMW will notify owners, and dealers will inspect the blower-regulator wiring harness, and replace it with a new part, free of charge. The recall is expected to begin September 27, 2019. Owners may contact BMW customer service at 1-800-525-7417. Note: This recall is an expansion of an earlier recall number 17V-676.

## Vehicles

### MAKE MODEL YEAR

BMW	128I	2008-2012
BMW	135I	2008-2012
BMW	135IS	2008-2012

## Steering Gear Tie Rod may Break

**NHTSA Campaign Number:** 19V601000

**Manufacturer** BMW of North America, LLC

**Components** STEERING

**Potential Number of Units Affected** 32

## Summary

BMW of North America, LLC (BMW) is recalling certain 2018-2019 BMW X1 sDrive28i, X1 xDrive28i, 2019 X2 xDrive28i, MINI Cooper S Convertible, Countryman, and John Cooper Works Countryman vehicles. The steering gear tie rod may have been assembled incorrectly, which may result in excessive wear of the tie rod end, eventually causing it to break.

## Remedy

BMW will notify owners, and dealers will inspect the vehicles and replace the tie rods and ball joints as necessary, free of charge. The recall is expected to begin October 7, 2019. Owners may contact BMW customer service at 1-800-525-7417 or MINI customer service at 1-866-825-1525.

## Vehicles

### MAKE MODEL YEAR

BMW	X1	2018-2019
BMW	X2	2019
MINI	COOPER	2019

