



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

September 23, 2019

### Front Brakes May Drag

**NHTSA Campaign Number:** 19V635000

**Manufacturer** Chrysler (FCA US LLC)

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 5,495

#### **Summary**

Chrysler (FCA US LLC) is recalling certain 2019 Ram 2500, 3500 and 3500 Cab Chassis trucks. The brake calipers may have been manufactured with an incorrect assembly fluid, which can cause the caliper's rubber seals to swell.

#### **Remedy**

FCA US will notify owners, and dealers will replace the front brake calipers and brake hoses and bleed the brakes, free of charge. The recall is expected to begin October 18, 2019. Owners may contact FCA US customer service at 1-800-853-1403. FCA US' number for this recall is V98.

#### **Vehicles**

##### **MAKE MODEL YEAR**

RAM	2500	2019
RAM	3500	2019

## Steering Rack Gear May Fail

**NHTSA Campaign Number:** 19V637000

**Manufacturer** Chrysler (FCA US LLC)

**Components** STEERING

**Potential Number of Units Affected** 5,294

### **Summary**

Chrysler (FCA US LLC) is recalling certain 2019-2020 Jeep Cherokee vehicles. The steering rack gear may break, possibly causing a loss of steering control.

### **Remedy**

Chrysler will notify owners, and dealers will replace the steering gear, free of charge. The recall is expected to begin October 18, 2019. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is V99.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

JEEP	CHEROKEE	2019-2020
------	----------	-----------

## Lower-Control Arm May Separate From Vehicle

**NHTSA Campaign Number:** 19V652000

**Manufacturer** General Motors LLC

**Components** SUSPENSION

**Potential Number of Units Affected** 93,693

### **Summary**

General Motors LLC (GM) is recalling certain 2015-2018 Chevrolet Trax vehicles. A joint in one or both of the front lower-control arms may have been improperly welded. An improperly welded joint may break, resulting in the partial separation of the lower-control arm from the vehicle.

**Remedy**

GM will notify owners, and dealers will inspect the left and right front lower-control arms, replacing them as necessary, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is A192261870.

**Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

CHEVROLET TRAX		2015-2018
----------------	--	-----------