



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

December 2, 2019

Insufficient Weld May Cause Seat Cushion to Shift

NHTSA Campaign Number: 19V800000

Manufacturer Daimler Vans USA, LLC

Components SEATS

Potential Number of Units Affected 3

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2019 Mercedes-Benz Sprinter and Freightliner vehicles. A seam on the height adjuster for the front seats may have been insufficiently welded.

Remedy

DVUSA will notify owners, and dealers will replace the tilt adjuster for the front seats, free of charge. The recall is expected to begin December 20, 2019. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS3SITZVER.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

FREIGHTLINER	SPRINTER 1500	2019
--------------	---------------	------

MAKE	MODEL	YEAR
FREIGHTLINER	SPRINTER 2500	2019
FREIGHTLINER	SPRINTER 3500	2019
FREIGHTLINER	SPRINTER 4500	2019
MERCEDES BENZ	SPRINTER 1500	2019
MERCEDES BENZ	SPRINTER 2500	2019
MERCEDES BENZ	SPRINTER 3500	2019
MERCEDES BENZ	SPRINTER 4500	2019

Loss of Electric Power Steering Assist

NHTSA Campaign Number: 19V801000

Manufacturer General Motors LLC

Components STEERING

Potential Number of Units Affected 476

Summary

General Motors LLC (GM) is recalling certain 2014-2016 Chevrolet SS vehicles that previously received an inspect-only remedy under recall 17V-382. Corrosion of the connector between the electric power steering module and the torque sensor connector may cause a loss of electric power steering assist.

Remedy

GM will notify owners, and dealers will replace the steering gear assembly, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Chevrolet customer service at 1-800-222-1020 or GM customer service at 1-586-596-1733. GM's number for this recall is N192265980.

Vehicle

MAKE	MODEL	YEAR
CHEVROLET	SS	2014-2016

Improperly Tightened Air Bag Fasteners

NHTSA Campaign Number: 19V806000

Manufacturer Aston Martin The Americas

Components AIR BAGS

Potential Number of Units Affected 17

Summary

Aston Martin The Americas (Aston Martin) is recalling certain 2018-2019 DB11 Coupe and Volante and 2019 Vantage and DBS Superleggera Coupe vehicles. The locking nut fasteners on the passenger air bag may not be tightened properly.

Remedy

Aston Martin will notify owners, and dealers will inspect the air bag fasteners, tightening them as necessary, free of charge. The recall is expected to begin December 18, 2019. Owners may contact Aston Martin customer service at 1-866-278-6661. Aston Martin's number for this recall is RA-01-1327.

Vehicles

MAKE	MODEL	YEAR
ASTON MARTIN	DB11	2018-2019
ASTON MARTIN	DBS SUPERLEGGERA	2019
ASTON MARTIN	VANTAGE	2019

Intermittent or Inoperative Tail Lights

NHTSA Campaign Number: 19V839000

Manufacturer Ford Motor Company

Components EXTERIOR LIGHTING

Potential Number of Units Affected 72,718

Summary

Ford Motor Company (Ford) is recalling certain 2019 Ranger trucks. The inline electrical connector terminals for the rear lights may be misaligned or not properly seated, potentially causing the rear lights to function intermittently or not at all.

Remedy

Ford will notify owners, and dealers will inspect the inline connector for loose terminals and replace the connectors, if necessary, free of charge. The recall is expected to begin January 6, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 19S43.

Vehicle**MAKE MODEL YEAR**

FORD RANGER 2019