



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

January 20, 2020

### Passenger Air Bag Inflators May Explode

**NHTSA Campaign Number:** 20V007000

**Manufacturer** Ferrari North America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 982

#### **Summary**

Ferrari North America, Inc. (Ferrari) is recalling certain 2009-2011 California and 2010-2011 458 Italia vehicles equipped with non-desiccated, passenger frontal air bag inflators containing phase stabilized ammonium nitrate (PSAN) propellant that were used as interim remedy parts for previous Takata recalls. These inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling.

#### **Remedy**

Ferrari will notify owners, and dealers will replace the front passenger air bag assembly with an alternate one, including a new non-ammonium nitrate inflator, free of charge. The recall is expected to begin March 9, 2020. Owners may contact Ferrari customer service at 1-201-816-2668. Ferrari's number for this recall is 60FL.

## Vehicles

MAKE	MODEL	YEAR
FERRARI	458 ITALIA	2010-2011
FERRARI	CALIFORNIA	2009-2011

## Frontal Passenger Air Bag Inflators May Explode

**NHTSA Campaign Number:** 20V008000

**Manufacturer** Nissan North America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 307,962

### Summary

Nissan North America, Inc. (Nissan) is recalling certain 2001-2003 Maxima, 2002-2006 Sentra, 2002-2004 Pathfinder, 2007-2011 Versa Sedan and Versa Hatchback, 2001-2004 Infiniti I30 and I35, 2002-2003 Infiniti QX4, 2003-2008 Infiniti FX35 and FX45 and 2006-2010 M35 and M45 vehicles. The vehicles are equipped with non-desiccated, frontal passenger air bag inflators containing phase stabilized ammonium nitrate (PSAN) propellant that were used as interim remedy parts for previous Takata recalls. These inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling.

### Remedy

Nissan will notify owners, and dealers will replace the front passenger air bag inflators with alternate desiccated inflators, free of charge. The recall is expected to begin February 10, 2020. Owners may contact Nissan customer service at 888-737-9511 or Infiniti customer service at 888-810-3715.

## Vehicles

MAKE	MODEL	YEAR
INFINITI	FX35	2003-2008
INFINITI	FX45	2003-2008
INFINITI	I30	2001-2004
INFINITI	I35	2001-2004
INFINITI	M35	2006-2010
INFINITI	M45	2006-2010
INFINITI	QX4	2002-2003
NISSAN	MAXIMA	2001-2003
NISSAN	PATHFINDER	2002-2004

MAKE	MODEL	YEAR
------	-------	------

NISSAN	SENTRA	2002-2006
--------	--------	-----------

NISSAN	VERSA	2007-2011
--------	-------	-----------

## Passenger Air Bag Inflators May Explode

**NHTSA Campaign Number:** 20V011000

**Manufacturer** General Motors LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 699

### **Summary**

General Motors LLC (GM) is recalling certain 2007-2008 Chevrolet Silverado 2500 and 3500 and GMC Sierra 2500 and 3500 vehicles equipped with non-desiccated, passenger frontal air bag inflators containing phase stabilized ammonium nitrate (PSAN) propellant that were used as interim remedy parts for previous Takata recalls. These inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling.

### **Remedy**

GM will notify owners, and dealers will replace the front passenger air bag inflators, free of charge. The recall is expected to begin February 24, 2020. Owners may contact Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-866-522-9559. GM's number for this recall is N192290990.

### **Vehicles**

MAKE	MODEL	YEAR
------	-------	------

CHEVROLET	SILVERADO 2500	2007-2008
-----------	----------------	-----------

CHEVROLET	SILVERADO 3500	2007-2008
-----------	----------------	-----------

GMC	SIERRA 2500	2007-2008
-----	-------------	-----------

GMC	SIERRA 3500	2007-2008
-----	-------------	-----------

## Passenger Air Bag Inflators May Explode

**NHTSA Campaign Number:** 20V016000

**Manufacturer** BMW of North America, LLC

## **Components AIR BAGS**

**Potential Number of Units Affected** 4,007

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2009-2012 X5 xDrive35d, 2008-2012 X6 xDrive35i, X6 xDrive50i and X6 M, 2007-2012 X5 30si, X5 xDrive30i, X5 xDrive35i, X5 48i, X5 xDrive48i, X5 xDrive50i and X5 M and 2010-2011 X6 ActiveHybrid vehicles equipped with non-desiccated, passenger frontal air bag inflators containing phase stabilized ammonium nitrate (PSPI-2) propellant that were used as interim remedy parts for previous Takata recalls. These inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling.

### **Remedy**

BMW will notify owners, and dealers will replace the passenger front air bag, free of charge. The recall is expected to begin March 6, 2020. Owners may contact BMW customer service at 1-800-525-7417.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
BMW	X5	2007-2012
BMW	X6	2008-2012
BMW	X6 ACTIVEHYBRID	SAC 2010-2011

## **Driver Air Bag Inflators May Explode**

**NHTSA Campaign Number:** 20V017000

**Manufacturer** BMW of North America, LLC

## **Components AIR BAGS**

**Potential Number of Units Affected** 59,965

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2008-2013 128i and 135i Convertibles, 128i, 135i, and M Coupes, 2007-2010 X3 30si and X3 xDrive30i, 2013-2015 X1 sDrive28i, X1 xDrive28i and X1 xDrive35i, 2007-2013 328i, 328i xDrive, 335i, 335is, 335i xDrive and M3 Coupes, 2006-2011 328i, 328xi, 328i xDrive, 325i, 325xi, 330i, 330xi, 335i, 335xi, 335i

xDrive and M3, 2009-2011 335D, 2006-2012 325xi, 328i, 328xi and 328i xDrive, 2010-2011 X6 ActiveHybrid, 2007-2013 328i, 335i, 335is, M3 Coupes, X5 30si, X5 xDrive30i, X5 xDrive35i, X5 48i, X5 xDrive48i, X5 xDrive50i and X5 M, 2009-2013 X5 xDrive35d and 2008-2014 X6 xDrive35i, X6 xDrive50i and X6M vehicles equipped with non-desiccated driver frontal air bag inflators containing phase stabilized ammonium nitrate

(PSAN) that were used as interim remedy parts for previous Takata recalls. These inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling.

## **Remedy**

BMW will notify owners, and dealers will replace the driver air bag. On X5 and X6 vehicles, only the inflator will be replaced. All repairs will be performed free of charge. The recall is expected to begin March 6, 2020. Owners may contact BMW customer service at 1-800-525-7417.

## **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
BMW	1 SERIES M	2008-2013
BMW	128I	2008-2013
BMW	135I	2008-2013
BMW	325I	2006-2011
BMW	325XI	2006-2012
BMW	328I	2006-2013
BMW	328XI	2006-2012
BMW	330I	2006-2011
BMW	330XI	2006-2011
BMW	335D	2009-2011
BMW	335I	2006-2013
BMW	335IS	2007-2013
BMW	335XI	2006-2011
BMW	M3	2006-2013
BMW	X1	2013-2015
BMW	X3	2007-2010
BMW	X5	2007-2013
BMW	X6	2008-2014
BMW	X6 ACTIVEHYBRID SAC	2010-2011

## **Passenger frontal Air Bag Inflators May Explode**

**NHTSA Campaign Number:** 20V018000

**Manufacturer** BMW of North America, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 292,948

## Summary

BMW of North America, LLC (BMW) is recalling certain 2000-2005 323iT, 325iT, 325xiT, 320i, 323i, 325i, 325xi, 328i, 330i and 330xi and 2000-2006 323Ci, 325Ci, 328Ci, 330Ci, M3 Coupe, 323Cic, 325Cic, 330Cic, and M3 Convertible vehicles equipped with non-desiccated frontal Takata PSAN inflators and PSPI passenger frontal air bag inflators containing phase stabilized ammonium nitrate (PSAN) propellant that were used as interim remedy parts for previous Takata recalls. These inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling.

## Remedy

BMW will notify owners, and dealers will replace the passenger's front air bag, free of charge. The recall is expected to begin March 6, 2020. Owners may contact BMW customer service at 1-800-525-7417.

## Vehicles

### MAKE MODEL YEAR

BMW	320I	2000-2005
BMW	323CI	2000-2006
BMW	323I	2000-2005
BMW	323IT	2000-2005
BMW	325CI	2000-2006
BMW	325I	2000-2005
BMW	325IT	2000-2005
BMW	325XI	2000-2005
BMW	325XIT	2000-2005
BMW	328CI	2000-2006
BMW	328I	2000-2005
BMW	330CI	2000-2006
BMW	330I	2000-2005
BMW	330XI	2000-2005
BMW	M3	2000-2006

## Fuel Pump May Fail

**NHTSA Campaign Number:** 20V012000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 695,541

## Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2018-2019 4Runner, Highlander, Camry, Land Cruiser, Sequoia, Sienna, Tacoma and Tundra, and Lexus RC 300, RC 350, GS 350, GX 460, IS 300, LC 500, LS 500, LX 570, RX 350, and 2019 Toyota Avalon and Corolla, and Lexus NX 300, ES 350, and GS 200T vehicles. The low-pressure fuel pump inside the fuel tank may fail.

## Remedy

The remedy for this recall is still under development. The recall is expected to begin March 13, 2020. Owners may contact Toyota customer service at 1-888-270-9371 or Lexus customer service at 1-800-255-3987. Toyota's numbers for this recall are 20TB02 and 20TA02 for Toyota vehicles and 20LB01 and 20LA01 for Lexus vehicles.

## Vehicles

MAKE	MODEL	YEAR
LEXUS	ES350	2019
LEXUS	GS 200T	2019
LEXUS	GS 350	2018-2019
LEXUS	GX460	2018-2019
LEXUS	IS 300	2018-2019
LEXUS	LC500	2018-2019
LEXUS	LS500	2018-2019
LEXUS	LX570	2018-2019
LEXUS	NX300	2019
LEXUS	RC 300	2018-2019
LEXUS	RC 350	2018-2019
LEXUS	RX350	2018-2019
TOYOTA	4RUNNER	2018-2019
TOYOTA	AVALON	2019
TOYOTA	CAMRY	2018-2019
TOYOTA	COROLLA	2019
TOYOTA	HIGHLANDER	2018-2019
TOYOTA	LAND CRUISER	2018-2019
TOYOTA	SEQUOIA	2018-2019
TOYOTA	SIENNA	2018-2019
TOYOTA	TACOMA	2018-2019
TOYOTA	TUNDRA	2018-2019