



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

February 10, 2020

### Delayed Camera Display/FMVSS 111

**NHTSA Campaign Number:** 20V046000

**Manufacturer** Mercedes-Benz USA, LLC.

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 22

#### **Summary**

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2019 A220 and A220 4MATIC vehicles. In certain operating conditions, the rearview camera software may cause a delay in displaying the rearview camera image. As such, these vehicles fail to comply to Federal Motor Safety Standard (FMVSS) number 111, "Rearview Mirrors."

#### **Remedy**

MBUSA will notify owners, and dealers will update the rearview camera software, free of charge. The recall is expected to begin March 27, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

#### **Vehicle**

MAKE	MODEL YEAR
------	------------

MERCEDES BENZ A220	2019
--------------------	------

## EBCM Software Error/FMVSS 126, 135

**NHTSA Campaign Number:** 20V055000

**Manufacturer** General Motors LLC

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 148,055

### **Summary**

General Motors LLC (GM) is recalling certain 2019 Chevrolet Silverado 1500 and GMC Sierra 1500 vehicles. These vehicles received updated software for the Electronic Brake Control Module (EBCM). This software has an error, and as a result, the vehicle's electronic brake assist may be disabled. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 126, "Electronic Stability Control" and 135, "Light Vehicle Brake Systems."

### **Remedy**

GM will notify owners, and dealers will reprogram the EBCM, free of charge. The recall is expected to begin February 10, 2020. Owners may contact Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-888-988-7267. GM's number for this recall is N192268091.

### **Vehicles**

MAKE	MODEL	YEAR
CHEVROLET	SILVERADO 1500	2019
GMC	SIERRA 1500	2019

## Air Bag Inflators May Underinflate Bag

**NHTSA Campaign Number:** 20V056000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 106,857

### **Summary**

Volkswagen Group of America, Inc. (VW) is recalling certain 2000-2001 TT Roadster, 2000 TT Coupe, 1999 Audi A8, 1998-2000 Audi A6, and 1999-2000 Audi A4 vehicles equipped with Non-Azide Driver air bag Inflators (NADI) that do not contain phase stabilized ammonium nitrate (PSAN) propellant. Due to a

manufacturing issue, the NADI inflators may absorb moisture, possibly causing the air bag to deploy improperly in the event of a crash.

### **Remedy**

Dealers will replace the driver frontal air bag inflator with an alternative inflator when the parts become available, free of charge. Interim owner notifications are expected to begin March 27, 2020. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 69AE.

### **Vehicles**

#### **MAKE MODEL YEAR**

AUDI	A4	1999-2000
AUDI	A6	1998-2000
AUDI	A8	1999
AUDI	TT	2000-2001

### **ABS Module May Short Circuit**

**NHTSA Campaign Number:** 20V061000

**Manufacturer** Hyundai Motor America

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 429,686

### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2006-2011 Elantra and 2007-2011 Elantra Touring vehicles. Moisture may enter the Anti-lock Brake (ABS) Module and result in an electrical short.

### **Remedy**

Hyundai will notify owners, and dealers will install a relay in the vehicle's main junction box to prevent the risk of an ABS short-circuit while the car is turned off, free of charge. The recall is expected to begin April 3, 2020. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 188.

### **Vehicles**

#### **MAKE MODEL YEAR**

HYUNDAI	ELANTRA	2006-2011
HYUNDAI	ELANTRA TOURING	2007-2011

## Lower Control Arm May Separate from Axle

**NHTSA Campaign Number:** 20V042000

**Manufacturer** Chrysler (FCA US LLC)

**Components** SUSPENSION

**Potential Number of Units Affected** 3,005

### **Summary**

Chrysler (FCA US LLC) is recalling certain 2020 Jeep Wrangler vehicles. The left side lower control arm bracket and weld may not be correctly positioned.

### **Remedy**

Chrysler will notify owners, and dealers will inspect the front axles, replacing them as necessary, free of charge. The recall is expected to begin March 14, 2020. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is W01.

### **Vehicle**

MAKE	MODEL	YEAR
------	-------	------

JEEP	WRANGLER	2020
------	----------	------

## Automatic Transmission Wiring Harness May Chafe

**NHTSA Campaign Number:** 20V047000

**Manufacturer** Mercedes-Benz USA, LLC.

**Components** POWER TRAIN, ELECTRICAL SYSTEM

**Potential Number of Units Affected** 28

### **Summary**

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2019 AMG GT63 4MATIC and AMG GT63S 4MATIC vehicles. A wiring harness for the automatic transmission may not be properly secured, allowing it to chafe against the drive shaft and possibly cause an engine stall.

## **Remedy**

MBUSA will notify owners, and dealers will inspect the mounting clips and wiring harness, and repair or replace them, as necessary, free of charge. The recall is expected to begin March 27, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

## **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
MERCEDES BENZ	AMG GT 63 S	2019
MERCEDES-BENZ	AMG GT 63	2019