



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest February 17, 2020

Second Row Seat Fasteners May be Missing

NHTSA Campaign Number: 20V053000

Manufacturer Jaguar Land Rover North America, LLC

Components SEATS

Potential Number of Units Affected 17

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2020 Discovery vehicles. The second row seat frame assembly may be missing fasteners, resulting in a seat frame with insufficient strength.

Remedy

Land Rover will notify owners, and dealers will replace the second row seat frame, tightening the bolts properly, free of charge. The recall is expected to begin March 19, 2020. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N422.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

LAND ROVER	DISCOVERY	2020
------------	-----------	------

Incorrectly Manufactured Air Bag Sensor

NHTSA Campaign Number: 20V057000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 7

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Atlas vehicles. The vehicles may be equipped with an incorrectly manufactured air bag sensor, which can delay or disable air bag deployment when necessary.

Remedy

Volkswagen will notify owners, and dealers will replace the air bag crash sensor, free of charge. The recall is expected to begin March 31, 2020. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 69AL.

Vehicle

MAKE	MODEL YEAR
-------------	-------------------

VOLKSWAGEN	ATLAS 2018
------------	------------

Reduced/Loss of Steering Assist

NHTSA Campaign Number: 20V062000

Manufacturer Tesla, Inc.

Components STEERING

Potential Number of Units Affected 14,113

Summary

Tesla, Inc. (Tesla) is recalling certain 2015-2016 Model X vehicles. The aluminum bolts that attach the power steering gear assist motor to the gear housing may corrode and fracture causing a reduction or complete loss of power steering assist.

Remedy

Tesla will notify owners, and Tesla Service Centers will replace the steering gear mounting bolts with coated steel bolts, and add a corrosion-preventative sealer to the steering gear motor housing and motor connection bolts. If the mounting bolts are found to be broken or break during removal and cannot be removed, a new steering gear will also be installed. All services will be performed free of charge. Tesla has not yet provided a date for when owner notification letters will be mailed. Owners may contact Tesla customer service at 1-877-798-3752.

Vehicle

MAKE MODEL YEAR

TESLA MODEL X 2015-2016

Daytime Running Lights May Fail

NHTSA Campaign Number: 20V063000

Manufacturer Mazda North American Operations

Components EXTERIOR LIGHTING

Potential Number of Units Affected 36,761

Summary

Mazda North American Operations (Mazda) is recalling certain 2016 CX-5 vehicles. The LED Daytime Running Lights (DRL) may fail while driving.

Remedy

Mazda will notify owners, and dealers will inspect the headlights, and replace the sealing gasket or headlight assemblies, as necessary, free of charge. The recall is expected to begin March 6, 2020. Owners may contact Mazda customer service at 1-800-222-5500 Option 4. Mazda's number for this recall is 4320A.

Vehicle

MAKE MODEL YEAR

MAZDA CX-5 2016