



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

March 23, 2020

Rear Seat Belt Assemblies May Not Lock As Intended

NHTSA Campaign Number: 20V145000

Manufacturer Nissan North America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 450

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2020 Infiniti Q60 vehicles equipped with rear seat belt assemblies with a dual-mode locking mechanism. The seat belt webbing sensor locking mechanism may not lock as intended.

Remedy

Nissan will notify owners, and dealers will inspect the rear seat belt assembly production dates, and replace the assemblies, as necessary, free of charge. The recall is expected to begin May 8, 2020. Owners may contact Nissan customer service at 1-800-867-7669.

Vehicle

MAKE MODEL YEAR

INFINITI Q60 2020

Automatic Emergency Braking May Not Engage

NHTSA Campaign Number: 20V144000

Manufacturer Volvo Car USA LLC

Components FORWARD COLLISION AVOIDANCE

Potential Number of Units Affected 121,605

Summary

Volvo Cars USA LLC (Volvo Cars) is recalling certain 2019-2020 S60, V60, V60 Cross Country, S90L, V90, V90 Cross Country, XC40, XC60, and XC90 vehicles. Due to a software/hardware incompatibility, the Automatic Emergency Brake (AEB) system may not detect obstacles and engage as intended.

Remedy

Volvo will notify owners, and dealers will update the Active Safety Domain Master (ASDM) software, free of charge. The recall is expected to begin May 1, 2020. Owners may contact Volvo customer service at 1-800-458-1552. Volvo's number for this recall is R29998.

Vehicles

MAKE MODEL YEAR

VOLVO S60	2019-2020
VOLVO S90	2019-2020
VOLVO V60	2019-2020
VOLVO V60CC	2019-2020
VOLVO V90	2019-2020
VOLVO V90CC	2019-2020
VOLVO XC40	2019-2020
VOLVO XC60	2019-2020
VOLVO XC90	2019-2020

Possible Loss of Steering Control

NHTSA Campaign Number: 20V149000

Manufacturer Volkswagen Group of America, Inc.

Components STEERING

Potential Number of Units Affected 229

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2019 Audi Q8 and 2017-2019 Audi Q7 vehicles. The bolt connecting the steering shaft to the steering gear may loosen, possibly resulting in a loss of steering control.

Remedy

Volkswagen will notify owners, and Audi dealers will inspect and, if necessary, replace the steering shaft bolt, as necessary, free of charge. The recall is expected to begin May 15, 2020. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 36A1.

Vehicles

MAKE MODEL YEAR

AUDI	Q7	2017-2019
AUDI	Q8	2019

Hood May Open Unexpectedly

NHTSA Campaign Number: 20V142000

Manufacturer General Motors LLC

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 1,909

Summary

General Motors LLC (GM) is recalling certain 2020 Chevrolet Silverado 2500 and 3500 and GMC Sierra 2500 and 3500 vehicles. The hood-latch striker wires may not have been heat-treated properly, possibly causing them to fracture.

Remedy

GM will notify owners, and dealers will replace the hood assembly, free of charge. The recall is expected to begin April 26, 2020. Owners may contact Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-888-988-7267. GM's number for this recall is N192284960.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	SILVERADO 2500	2020
CHEVROLET	SILVERADO 3500	2020
GMC	SIERRA 2500	2020
GMC	SIERRA 3500	2020

Brake Lights Flash During Braking/FMVSS 108

NHTSA Campaign Number: 20V146000

Manufacturer BMW of North America, LLC

Components EXTERIOR LIGHTING

Potential Number of Units Affected 4,026

Summary

BMW of North America, LLC (BMW) is recalling certain 2020 F900R, F900XR, S1000RR, F750GS, F850GS, F850GS Adventure, R1250GS, R1250GS Adventure, R1250RS, R1250R, RnineT, RnineT Pure and RnineT Scrambler and 2019-2020 S1000R motorcycles. The brake light may flash instead of remain steady during emergency braking. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

BMW will notify owner, and dealers will reprogram the emergency stop signal function, free of charge. The recall is expected to begin May 4, 2020. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	F 750 GS	2020
BMW	F 850 GS	2020
BMW	F 850 GS ADVENTURE	2020
BMW	F 900 R	2020
BMW	F 900 XR	2020
BMW	R 1250 GS	2020
BMW	R 1250 GS ADVENTURE	2020
BMW	R 1250 R	2020

MAKE	MODEL	YEAR
BMW	R 1250 RS	2020
BMW	R NINE T	2020
BMW	R NINE T PURE	2020
BMW	R NINE T SCRAMBLER	2020
BMW	S1000 R	2019-2020
BMW	S1000 RR	2020

Trailer Lights May not Function

NHTSA Campaign Number: 20V143000

Manufacturer Jaguar Land Rover North America, LLC

Components EXTERIOR LIGHTING, ELECTRICAL SYSTEM

Potential Number of Units Affected 1,553

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2017-2018 Discovery vehicles equipped with low line headlight assemblies. When towing a trailer with the trailer lights connected to the trailer socket and the vehicle's Daytime Running Lights (DRL) are on, the trailer lights may not function.

Remedy

Land Rover will notify owners, and dealers will update the Body Control Module software, free of charge. The recall is expected to begin May 8, 2020. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N428.

Vehicle

MAKE	MODEL	YEAR
LAND ROVER	DISCOVERY	2017-2018