



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

April 6, 2020

Rear Seat Belt Assemblies May Not Lock As Intended

NHTSA Campaign Number: 20V189000

Manufacturer Subaru of America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 4,862

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2019 Crosstrek vehicles with rear seat belt assemblies with a dual-mode locking mechanism. The seat belt webbing sensor locking mechanism may not lock as intended.

Remedy

Subaru will notify owners, and dealers will replace rear seat belt assemblies, free of charge. The recall is expected to begin April 24, 2020. Owners may contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is WRC-20.

Vehicle

MAKE MODEL YEAR

SUBARU CROSSTREK 2019

Driver Frontal Air Bag Inflator May Rupture

NHTSA Campaign Number: 20V188000

Manufacturer Nissan North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 216,678

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2012-2017 NV Cargo and NV Passenger Van, 2013-2015 Titan and Armada and 2011-2012 Infiniti QX56 vehicles. Due to a manufacturing issue, the air bag inflator may not function properly or may rupture during deployment.

Remedy

Nissan will notify owners, and dealers will replace the front driver air bag inflators, free of charge. The recall is expected to begin May 25, 2020. Owners may contact Nissan customer service at 1-800-867-7669 or Infiniti customer service at 1-800-662-6200.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

INFINITI	QX56	2011-2012
NISSAN	ARMADA	2013-2015
NISSAN	NV	2012-2017
NISSAN	TITAN	2013-2015

Wire Harness May Chafe and Damage Circuits

NHTSA Campaign Number: 20V175000

Manufacturer Ford Motor Company

Components SERVICE BRAKES, HYDRAULIC, ELECTRICAL SYSTEM, ELECTRONIC STABILITY CONTROL

Potential Number of Units Affected 2,871

Summary

Ford Motor Company (Ford) is recalling certain 2021 E-350 and E-450 vehicles. A wire harness in the rear of the vehicle may contact the vehicle frame, resulting in damage to the circuits that support the fuel pump and the anti-lock braking system (ABS).

Remedy

Ford will notify owners, and dealers will inspect the wire harness for damage. If no damage is found, dealers will apply anti-abrasion tape over the area and ensure clearance to surrounding components. If damage is found, dealers will splice in new wire and apply anti-abrasion tape over the area and ensure clearance to surrounding components. All services will be performed free of charge. The recall is expected to begin April 13, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S13.

Vehicles

MAKE MODEL YEAR

FORD E-350 2021

FORD E-450 2021