



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

June 1, 2020

[Air Bags May Not Deploy in Rollover](#)

NHTSA Campaign Number: 20V283000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 76

Summary

BMW of North America, LLC (BMW) is recalling certain 2020 X1 xDrive28i, X1 sDrive28i, X2 xDrive28i and X2 sDrive28i, 2020 MINI Clubman Cooper S All4, 2021 MINI Hardtop 2 Door (Cooper, Cooper S, John Cooper Works and Cooper S E) and MINI Hardtop 4 Door (Cooper and Cooper S) vehicles. Due to a problem with the rollover sensor within the air bag control unit, in the event of a rollover crash, the head air bag, seat belt pretensioners and other safety systems, may not activate.

Remedy

BMW will notify owners, and dealers will replace the air bag control unit, free of charge. This recall is expected to begin on July 13, 2020. Owners may contact BMW customer service at 1-800-525-7417 or MINI customer service at 1-866-825-1525.

Vehicles

MAKE	MODEL	YEAR
BMW	X1	2020
BMW	X2	2020
MINI	COOPER	2020-2021
MINI	COOPER S	2020-2021
MINI	COOPER S CLUBMAN	2020
MINI	JOHN COOPER WORKS	2021

Incorrect Replacement Passenger Air Bag Installed

NHTSA Campaign Number: 20V298000

Manufacturer Mercedes-Benz USA, LLC.

Components AIR BAGS

Potential Number of Units Affected 747

Summary

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2012 C250, C250 Coupe, C300, C350, C350 Coupe, C63 AMG, and C63 AMG Coupe vehicles equipped with a front passenger air bag assembly replaced under a prior recall. An incorrect replacement front passenger air bag may have been installed.

Remedy

MBUSA will notify owners, and dealers will replace the passenger air bag module, free of charge. The recall is expected to begin June 26, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	C250	2012
MERCEDES BENZ	C300	2012
MERCEDES BENZ	C350	2012
MERCEDES BENZ	C63 AMG	2012

Front Lower Suspension Arms May Separate

NHTSA Campaign Number: 20V286000

Manufacturer Toyota Motor Engineering & Manufacturing

Components SUSPENSION

Potential Number of Units Affected 9,502

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2019-2020 RAV4 and RAV4 Hybrid vehicles. The front lower suspension arms may have cracks, which may result in the suspension arm separating from the front wheel assembly.

Remedy

Toyota will notify owners, and dealers will replace both front lower suspension arms, free of charge. This recall is expected to begin July 12, 2020. Owners may contact Toyota customer service at 1-888-270-9371. Toyota's interim numbers for this recall are 20TB08 / 20TA08.

Vehicles

MAKE	MODEL	YEAR
TOYOTA	RAV4	2019-2020
TOYOTA	RAV4 HYBRID	2019-2020

Undersized Ground Wire May Cause Engine Stall

NHTSA Campaign Number: 20V281000

Manufacturer Daimler Trucks North America LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 2,987

Summary

Daimler Trucks North America LLC (DTNA) is recalling certain 2019-2021 Western Star 4700 and 5700 vehicles. A particular wire in the ground harness may be undersized, possibly resulting in a melted connector in the ground circuit harness. If the connector becomes damaged, under certain circumstances, the engine may stall without the ability to restart.

Remedy

DTNA will notify owners, and dealers will replace the ground harness, free of charge. This recall is expected to begin July 16, 2020. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-852.

Vehicles

MAKE	MODEL	YEAR
WESTERN STAR	4700	2019-2021
WESTERN STAR	5700	2019-2021

ABS Malfunction Indicator May Not Light/FMVSS 105

NHTSA Campaign Number: 20V285000

Manufacturer Navistar, Inc.

Components SERVICE BRAKES, HYDRAULIC, ELECTRICAL SYSTEM

Potential Number of Units Affected 2,805

Summary

Navistar, Inc. (Navistar) is recalling certain 2019-2020 International CV vehicles. Due to a software error, the Antilock Braking System (ABS) malfunction indicator does not light when there is a loss of communication between the Electronic Brake Control Module (EBCM) and the Body Control Module (BCM). As such, these vehicles fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) number 105, "Hydraulic and Electric Brake Systems."

Remedy

Navistar will notify owners, and dealers will program the BCM software with a new calibration, free of charge. This recall is expected to begin June 19, 2020. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 20505.

Vehicle

MAKE	MODEL	YEAR
INTERNATIONAL	CV	2019-2020