



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

June 29, 2020

[Middle Row Seat Headrest May Be Improperly Welded](#)

NHTSA Campaign Number: 20V366000

Manufacturer Ford Motor Company

Components SEATS

Potential Number of Units Affected 2,620

Summary

Ford Motor Company (Ford) is recalling certain 2020 Ford Expedition and Lincoln Navigator vehicles. The attachment bracket for the driver's side second-row seat headrest may not have been sufficiently welded to the seat frame. As such, these vehicles fail to comply with Federal Motor Vehicle Safety Standard number 202, "Head Restraints."

Remedy

Ford will notify owners, and dealers will inspect the seat structure and replace it as needed, free of charge. This recall is expected to begin July 6, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20C12.

Vehicles

MAKE	MODEL	YEAR
FORD	EXPEDITION	2020
LINCOLN	NAVIGATOR	2020

Brake Caliper Bolts May Loosen

NHTSA Campaign Number: 20V359000

Manufacturer Volkswagen Group of America, Inc.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 1

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling one 2020 Jetta vehicle. The front brake caliper bolts may come loose.

Remedy

Volkswagen will notify the owner, and a dealer will replace all four front brake caliper bolts, free of charge. The recall is expected to begin August 14, 2020. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 47Q2.

Vehicle

MAKE	MODEL YEAR
-------------	-------------------

VOLKSWAGEN JETTA	2020
------------------	------

Steering Gear Tie Rods May Become Damaged

NHTSA Campaign Number: 20V355000

Manufacturer BMW of North America, LLC

Components STEERING

Potential Number of Units Affected 2,779

Summary

BMW of North America, LLC (BMW) is recalling certain 2019 Z4 sDrive30i, 2019-2020 330i xDrive, M340i and M340i xDrive, 2020 X3M and X4M, and Toyota Supra vehicles. In certain driving conditions, such as high temperatures and rough road surfaces, a steering gear tie rod may become damaged, possibly resulting in a fractured tie rod.

Remedy

BMW and Toyota will notify owners, and dealers will replace the steering gear tie rods, free of charge. This recall is expected to begin August 7, 2020. Owners may contact BMW customer service at 1-800-525-7417 or Toyota customer service at 1-888-270-9371.

Vehicles

MAKE MODEL YEAR

BMW	330I	2019-2020
BMW	M340I	2019-2020
BMW	X3	2020
BMW	X4	2020
BMW	Z4	2019
TOYOTA	SUPRA	2020