



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

August 17, 2020

### [Trunk Release May Not Work/FMVSS 401](#)

**NHTSA Campaign Number:** 20V461000

**Manufacturer** General Motors LLC

**Components** LATCHES/LOCKS/LINKAGES, ELECTRICAL SYSTEM

**Potential Number of Units Affected** 5,141

#### **Summary**

General Motors LLC (GM) is recalling certain 2020 Chevrolet Corvette vehicles. The release button located inside the front trunk compartment may not function after the vehicle has been shut off for ten minutes. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 401, "Internal Trunk Release."

#### **Remedy**

GM will notify owners, and dealers will update the software in the vehicle's Body Control Module (BCM) to allow the release switch to always work, free of charge. Owners also may allow the vehicle to be remedied via an Over-The-Air software update. The recall is expected to begin September 21, 2020. Owners may contact GM customer service at 1-866-522-9559. GM's number for this recall is N202309350.

#### **Vehicle**

**MAKE      MODEL      YEAR**

CHEVROLET CORVETTE 2020

## Top View Rear Camera Holder Malfunction/FMVSS 111

**NHTSA Campaign Number:** 20V452000

**Manufacturer** Bentley Motors, Inc.

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 102

### **Summary**

Bentley Motors, Inc. (Bentley) is recalling certain 2020 Flying Spur vehicles. Moisture can enter the Top View rear camera holder and result in a reduction in the clarity of the rear view camera image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rearview Mirrors."

### **Remedy**

Bentley will notify owners, and dealers will modify the top view camera holder to improve the water draining ability, free of charge. The recall is expected to begin August 21, 2020. Owner may contact Bentley customer service at 1-800-777-6923. Bentley's number for this recall is RE 20/21.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

BENTLEY	FLYING SPUR	2020
---------	-------------	------

## Adjustable Brake Pedal Arm May Rotate

**NHTSA Campaign Number:** 20V435000

**Manufacturer** Daimler Trucks North America LLC

**Components** SERVICE BRAKES

**Potential Number of Units Affected** 149

### **Summary**

Daimler Trucks North America, LLC. (DTNA) is recalling certain 2021 Saf-T-Liner C2 School Buses. The adjustable brake pedal arm may rotate from its original location due to an incorrect fit between the pedal adjustment tube and the upper brake arm casting.

### **Remedy**

DTNA will notify owners, and dealers will install a new brake pedal assembly, free of charge. The recall is expected to begin September 25, 2020. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-857.

**Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

THOMAS BUILT BUSES SAF-T-LINER C2		2021
-----------------------------------	--	------

**Windshield May Separate from Vehicle****NHTSA Campaign Number:** 20V464000**Manufacturer** Mercedes-Benz USA, LLC.**Components** VISIBILITY, AIR BAGS**Potential Number of Units Affected** 1**Summary**

Mercedes-Benz USA, LLC. (MBUSA) is recalling one 2020 GLE 450 vehicle. The windshield may not have been bonded correctly to the vehicle, possibly allowing it to separate from the vehicle and affect the full protective function of the passenger's frontal air bag in the event of a crash.

**Remedy**

MBUSA will notify the owner, and a dealer will inspect the windshield bonding and repair it as necessary, free of charge. The recall is expected to begin August 28, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

**Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

MERCEDES-BENZ	GLE450	2020
---------------	--------	------