



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

August 3, 2020

### Potential Loss of Steering Control

**NHTSA Campaign Number:** 20V422000

**Manufacturer** Kia Motors America

**Components** STEERING

**Potential Number of Units Affected** 104

#### **Summary**

Kia Motors America (Kia) is recalling certain 2020 Stinger vehicles equipped with a 2.0L Turbo-GDI engine. A component within the Rack Mounted Motor Driven Power Steering (MDPS) Assembly may have been manufactured incorrectly, possibly resulting in the steering locking or becoming difficult while driving.

#### **Remedy**

Kia will notify owners, and dealers will replace the MDPS Assembly, free of charge. The recall is expected to begin August 28, 2020. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC193.

#### **Vehicle**

**MAKE MODEL YEAR**

KIA STINGER 2020

## Potential Loss of Steering Control

**NHTSA Campaign Number:** 20V447000

**Manufacturer** Hyundai Motor America

**Components** STEERING

**Potential Number of Units Affected** 2

### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2020 Genesis G70 vehicles. A component within the Rack Mounted Motor Driven Power Steering (R-MDPS) Assembly may have been manufactured incorrectly, possibly resulting in the steering locking or becoming difficult while driving.

### **Remedy**

Hyundai dealers have replaced the R-MDPS Assemblies, free of charge, prior to the sale of the vehicles. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 004G.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

HYUNDAI	GENESIS G70	2020
---------	-------------	------

## Driver's Seat Fastener Bolt May Fail

**NHTSA Campaign Number:** 20V430000

**Manufacturer** Mercedes-Benz USA, LLC.

**Components** SEATS

**Potential Number of Units Affected** 1

### **Summary**

Mercedes-Benz USA, LLC. (MBUSA) is recalling one 2020 GLE 350 vehicle. One of four bolts securing the driver's seat may not have been installed correctly and may fail.

### **Remedy**

MBUSA will notify the owner, and a dealer will inspect the driver's seat fastening bolts, tightening them as necessary, free of charge. The recall is expected to begin September 22, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

**Vehicle****MAKE      MODEL YEAR**

MERCEDES-BENZ GLE350 2020

**Power Steering Assist Cylinder Bracket May Break****NHTSA Campaign Number:** 20V429000**Manufacturer** PACCAR Incorporated**Components** STEERING**Potential Number of Units Affected** 239**Summary**

PACCAR Incorporated (PACCAR) is recalling certain 2020 Peterbilt 520 vehicles. Incorrect bolts may have been used to secure the steering assist cylinder bracket, possibly allowing the bolts to loosen.

**Remedy**

PACCAR will notify owners, and dealers will install hardware with thread adhesive and replace any components damaged by the improperly secured steer assist bracket, free of charge. The recall is expected to begin September 22, 2020. Owners may contact PACCAR customer service at 1-425-828-5888. PACCAR's number for this recall is 20PBD.

**Vehicle****MAKE      MODEL YEAR**

PETERBILT 520      2020