



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest October 12, 2020

Seat Belt Retractor May Not Lock

NHTSA Campaign Number: 20V581000

Manufacturer General Motors LLC

Components SEAT BELTS

Potential Number of Units Affected 5

Summary

General Motors LLC (GM) is recalling certain 2020 Chevrolet Corvette vehicles. The driver's seat belt retractor may not lock as intended during a crash.

Remedy

GM will notify owners, and dealers will replace the driver's side seat-belt retractor, free of charge. The recall is expected to begin on November 9, 2020. Owners may contact GM customer service at 1-866-522-9559. GM's number for this recall is N202307690.

Vehicle

MAKE MODEL YEAR

CHEVROLET CORVETTE 2020

Seat Belt Retractor May Not Lock

NHTSA Campaign Number: 20V580000

Manufacturer Chrysler (FCA US LLC)

Components SEAT BELTS

Potential Number of Units Affected 2,114

Summary

Chrysler (FCA US LLC) is recalling certain 2019 Jeep Wrangler and Ram 2500, 2019-2020 Ram 1500 and 2020 Jeep Gladiator vehicles. The front seat belt retractors may not lock as intended during a crash.

Remedy

Chrysler will notify owners, and dealers will replace the front seat belt retractors, free of charge. The recall is expected to begin November 13, 2020. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is W67.

Vehicles

MAKE	MODEL	YEAR
JEEP	GLADIATOR	2020
JEEP	WRANGLER	2019
RAM	1500	2019-2020
RAM	2500	2019

Seat Belt ELR/ALR functional issue/FMVSS 208; 209

NHTSA Campaign Number: 20V578000

Manufacturer Motor Coach Industries

Components SEAT BELTS

Potential Number of Units Affected 56

Summary

Motor Coach Industries (MCI) is recalling certain 2019 D45CRT-LE coaches. The seat belt retractors installed in the last row of the passenger seats may not function properly, preventing them from being used. As such,

these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection" and 209, "Seat Belt Assemblies."

Remedy

MCI will notify owners, and the seat belt manufacturer will modify the seat belt installation for the last row of seats, free of charge. The recall is expected to begin October 23, 2020. Owners may contact MCI customer service at 1-800-241-2947. MCI's number for this recall is SB 490.

Vehicle

MAKE MODEL YEAR

MCI D45 CRT LE 2019

Incorrect Rear Brake ABS Modulator Valve/FMVSS 121

NHTSA Campaign Number: 20V593000

Manufacturer PACCAR Incorporated

Components SERVICE BRAKES, AIR

Potential Number of Units Affected 1,416

Summary

PACCAR Incorporated (PACCAR) is recalling certain 2016-2021 Kenworth T680 trucks equipped with a 2.1m Cab and WABCO 6S/6M ABS brake system with drum brakes. The brake systems were manufactured with a standard rear-brake ABS modulator valve instead of a quick release valve, which may exceed the intended service-brake release timing. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 121, "Air Brake Systems."

Remedy

PACCAR will notify owners, and dealers will replace the standard rear-brake, ABS modulator valve with a quick release valve, free of charge. The recall is expected to begin November 25, 2020. Owners may contact PACCAR customer service at 1-425-828-5888. PACCAR's number for this recall is 20KWD.

Vehicle

MAKE MODEL YEAR

KENWORTH T680 2016-2021