

# NHTSA Recalls of Interest October 26, 2020

# Seat Trim Can Interfere with Air Bag Deployment

NHTSA Campaign Number: 20V633000

Manufacturer Toyota Motor Engineering & Manufacturing

Components AIR BAGS, SEATS

Potential Number of Units Affected 3.121

#### **Summary**

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2020 Highlander and Highlander hybrid vehicles. Incorrect seat trim covers on one or both of the front seats can prevent the seat-mounted side air bag from deploying properly.

#### Remedy

Toyota will notify owners, and dealers will inspect the front seats and replace the seat trim covers as necessary, free of charge. The recall is expected to begin December 13, 2020. Owners may contact Toyota customer service at 1-800-442-8696. Toyota's number for this recall is 20TB14 / 20TA14.

#### **Vehicles**

TOYOTA HIGHLANDER 2020 TOYOTA HIGHLANDER HYBRID 2020

# Window Air Bag May Not Be Mounted Correctly

NHTSA Campaign Number: 20V628000

Manufacturer Mercedes-Benz USA, LLC.

**Components** AIR BAGS

**Potential Number of Units Affected** 7

#### **Summary**

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2020 GLB 250 vehicles. The window air bag in the Apillar area may not be mounted correctly, affecting its performance. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 226, "Ejection Mitigation."

### Remedy

MBUSA will notify owners, and dealers will check the mounting of the window air bag and correct it as necessary, free of charge. The recall is expected to begin December 8, 2020. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2020100010.

#### Vehicle

MAKE MODEL YEAR

MERCEDES BENZ GLB250 2020

# Front Seat Air Bags Fasteners may Be Loose

NHTSA Campaign Number: 20V604000

**Manufacturer** Aston Martin The Americas

**Components** AIR BAGS

**Potential Number of Units Affected 21** 

#### **Summary**

Aston Martin The Americas (Aston Martin) is recalling certain 2017 DB11, 2019 DB11 V8 Volante and DBS Superleggera, 2019-2020 Vantage and 2020 Superleggera Volante vehicles. The front seat air bag fasteners may not have been tightened correctly.

## Remedy

Aston Martin will notify owners, and dealers will examine and, if necessary, secure the front seat air bag fasteners, free of charge. The recall is expected to begin November 5, 2020. Owners may contact Aston Martin customer service at 1-888-923-9988. Aston Martin's number for this recall is RA-01-1418.

#### **Vehicles**

MAKE MODEL YEAR

ASTON MARTIN DB11 2017, 2019 ASTON MARTIN DBS SUPERLEGGERA 2019-2020 ASTON MARTIN VANTAGE 2019-2020

# Center Console May Open in Rear Crash/FMVSS 201

NHTSA Campaign Number: 20V608000

Manufacturer Mercedes-Benz USA, LLC.

Components LATCHES/LOCKS/LINKAGES

**Potential Number of Units Affected** 7

## **Summary**

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2019 C300 vehicles. The center console lock-system might not lock properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 201, "Occupant Protection In Interior Impact."

### Remedy

MBUSA will notify owners, and dealers will check the center console storage compartment, and replace it, if necessary, free of charge. The recall is expected to begin December 1, 2020. Owners may contact MBUSA customer service at 1-800-367-6372. MBUSA's number for this recall is 2020100006.

#### Vehicle

MAKE MODEL YEAR

MERCEDES BENZ C300 2019

# Rearview Camera Image Obscured/FMVSS 111

NHTSA Campaign Number: 20V598000

Manufacturer BMW of North America, LLC

**Components BACK OVER PREVENTION** 

Potential Number of Units Affected 312

#### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2020-2021 X3 sDrive 30i, X3 xDrive 30i, X3M 40i, X3 xDrive 30e, X4 xDrive 30i, X4M 40i, 530i, 540i, 540i xDrive, M550i xDrive, M5, 550e, 550e xDrive, and 550e iPerformance vehicles. A small portion of the rearview image may be slightly obscured. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

## Remedy

BMW will notify owners, and dealers will inspect and, if necessary, program the rearview camera with updated software. The recall is expected to begin November 23, 2020. Owners may contact BMW customer service at 1-800-525-7417.

#### Vehicles

#### MAKE MODEL YEAR

BMW	530I	2020-2021
BMW	540I	2020-2021
BMW	550E	2020-2021
BMW	M5	2020-2021
BMW	M550I	2020-2021
BMW	X3	2020-2021
BMW	X4	2020-2021

# Rear Spoiler May Detach

NHTSA Campaign Number: 20V623000

Manufacturer Jaguar Land Rover North America, LLC

**Components STRUCTURE** 

**Potential Number of Units Affected 21,834** 

## **Summary**

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2010-2011 Range Rover Sport vehicles. The upper cover on the rear spoiler may detach from the vehicle.

## Remedy

Land Rover will notify owners, and dealers will apply a new adhesive to secure the upper spoiler cover, free of charge. The recall is expected to begin November 30, 2020. Owners can contact Land Rover customer service at 1-800-369-1000. Land Rover's number for this recall is N499.

#### Vehicle

MAKE MODEL YEAR

LAND ROVER RANGE ROVER SPORT 2010-2011