



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest November 23, 2020

Fuel Tank Weld May Fail

NHTSA Campaign Number: 20V700000

Manufacturer BMW of North America, LLC

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 49

Summary

BMW of North America, LLC (BMW) is recalling certain 2020-2021 Z4 and 2020-2021 Toyota Supra vehicles. The weld between the fuel tank halves may have been insufficiently welded, causing the weld to fail.

Remedy

BMW will notify owners, and dealers will replace the fuel tank, free of charge. The recall is expected to begin January 4, 2021. Owners may contact BMW customer service at 1-800-525-7417 or Toyota customer service at 1-888-270-9371.

Vehicles

MAKE MODEL YEAR

BMW Z4 2020-2021

TOYOTA SUPRA 2020-2021

Tires may have been Overcured

NHTSA Campaign Number: 20V684000

Manufacturer General Motors LLC

Components TIRES

Potential Number of Units Affected 7,516

Summary

General Motors LLC (GM) is recalling certain 2020 Buick Enclave, Cadillac XT5, GMC Acadia and Chevrolet Traverse vehicles and 2020-2021 Chevrolet Silverado 1500, GMC Sierra 1500 vehicles. The vehicles may have been manufactured with Continental tires that were overcured.

Remedy

GM will notify owners, and dealers will inspect vehicles and replace tires that have DOT number and production mold number combinations identified by Continental, free of charge. The recall is expected to begin December 21, 2020. Owners may contact GMC customer service at 1-888-988-7267, Buick customer service at 1-866-608-8080, Chevrolet customer service at 1-800-222-1020 or Cadillac customer service at 1-800-458-8006. GM's number for this recall is N202319030.

Vehicles

MAKE	MODEL	YEAR
BUICK	ENCLAVE	2020
CADILLAC	XT5	2020
CHEVROLET	SILVERADO 1500	2020-2021
CHEVROLET	TRAVERSE	2020
GMC	ACADIA	2020
GMC	SIERRA 1500	2020-2021

Headlights Can Be Misadjusted/FMVSS 108

NHTSA Campaign Number: 20V698000

Manufacturer Toyota Motor Engineering & Manufacturing

Components EXTERIOR LIGHTING

Potential Number of Units Affected 413

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2021 RAV4 Prime vehicles. The headlight aiming caps may have been improperly closed, allowing for horizontal adjustment of the headlight beam. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Toyota will notify owners, and dealers will close the aiming caps on the headlights, free of charge. The recall is expected to begin January 4, 2021. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's number for this recall is 20TA15.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

TOYOTA	RAV4 PRIME	2021
--------	------------	------

Fuel Injector Installed Without Damping Component

NHTSA Campaign Number: 20V666000

Manufacturer BMW of North America, LLC

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 21

Summary

BMW of North America, LLC (BMW) is recalling certain 2020-2021 M2 Coupe and 2020 M4 Coupe vehicles. Fuel injectors may have been installed without a damping component which is used to reduce vibration. If a damping component is not present, vibration will increase at the connection between the fuel line and the fuel rail, which over time, can result in damage at the connection.

Remedy

BMW will notify owners, and dealers will inspect the fuel injectors and if a damping component is missing, the injectors and the fuel rail will be replaced, free of charge. The recall is expected to begin December 21, 2020. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

BMW	M2	2020-2021
BMW	M4	2020

Loss of Steering Due To Knuckle Failure

NHTSA Campaign Number: 20V712000

Manufacturer Volkswagen Group of America, Inc.

Components STEERING

Potential Number of Units Affected 776

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2021 Atlas and 2020-2021 Atlas Cross Sport vehicles. One or both steering knuckles may have been damaged during production.

Remedy

Volkswagen has notified owners, and dealers will inspect and, as necessary, replace the steering knuckle, free of charge. The recall began November 19, 2020. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 40Q6. Note: Owners are advised to DO NOT DRIVE the vehicle until the vehicle has been inspected and repaired if necessary.

Vehicles

MAKE	MODEL	YEAR
VOLKSWAGEN	ATLAS	2021
VOLKSWAGEN	ATLAS CROSS SPORT	2020-2021