



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

September 14, 2020

[ABS Unit may cause Engine Compartment Fire](#)

NHTSA Campaign Number: 20V543000

Manufacturer Hyundai Motor America

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 180,000

Summary

Hyundai Motor America (Hyundai) is recalling certain 2019-2021 Tucson vehicles. The Anti-lock Brake Hydraulic Electronic Control Unit (HECU) could corrode internally and cause an electrical short, possibly resulting in an engine compartment fire.

Remedy

Hyundai will notify owners, and dealers will replace the HECU, free of charge. Owners are advised to park outside and away from structures as a precaution until the recall repair is complete. The recall is expected to begin October 30, 2020. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 195.

Vehicle

MAKE MODEL YEAR

HYUNDAI TUCSON 2019-2021

ABS Unit may cause Fire

NHTSA Campaign Number: 20V518000

Manufacturer Kia Motors America

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 9,443

Summary

Kia Motors America (Kia) is recalling certain 2019 Stinger vehicles equipped with 3.3L T-GDI engines. While driving, an engine compartment fire may occur in the area where the Anti-lock Brake Hydraulic Electronic Control Unit (HECU) is located.

Remedy

The remedy for this recall is still under development. The recall is expected to begin October 26, 2020. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC196.

Vehicle

MAKE MODEL YEAR

KIA STINGER 2019

Loss of Electric Power Steering Assist

NHTSA Campaign Number: 20V515000

Manufacturer General Motors LLC

Components STEERING

Potential Number of Units Affected 95

Summary

General Motors LLC (GM) is recalling certain 2014-2016 Chevrolet Caprice Police Pursuit vehicles (PPV), that did not get a replacement steering gear under recalls 17V-265 or 16V-160. The connector between the electric power steering module and the torque sensor may fail, possibly resulting in a loss of electric power steering assist.

Remedy

GM will notify owners, and dealers will inspect the steering gear assembly, replacing any that are not of the approved part numbers, free of charge. The recall is expected to begin October 12, 2020. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N202306620.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

CHEVROLET CAPRICE POLICE PURSUIT 2014-2016

Stealth Mode Disables Camera Display/FMVSS 111

NHTSA Campaign Number: 20V512000

Manufacturer Chrysler (FCA US LLC)

Components BACK OVER PREVENTION

Potential Number of Units Affected 26,361

Summary

Chrysler (FCA US LLC) is recalling certain 2018-2020 Dodge Charger Pursuit vehicles equipped with a "stealth mode." When stealth mode is selected, the backup camera rearview image will not display when the vehicle is in reverse. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rearview Mirrors."

Remedy

Chrysler will notify owners, and dealers will update body control module software to disable stealth mode when the vehicle is shifted into "Reverse", free of charge. The recall is expected to begin October 16, 2020. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is W62.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

DODGE CHARGER 2018-2020