



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest March 22, 2021

### Internal Damage to ABS Module

**NHTSA Campaign Number:** 21V147000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** SERVICE BRAKES, HYDRAULIC, ELECTRICAL SYSTEM

**Potential Number of Units Affected** 4

#### **Summary**

Chrysler (FCA US, LLC) is recalling certain 2020-2021 Ram ProMaster City vehicles. The Anti-Lock Brake System (ABS) module may have internal damage, which could result in a loss of braking performance or autonomous braking functions.

#### **Remedy**

FCA US, LLC will notify owners, and dealers will replace the ABS module, free of charge. The recall is expected to begin April 28, 2021. Owners may contact FCA US, LLC customer service at 1-800-853-1403.

#### **Vehicle**

MAKE	MODEL	YEAR
------	-------	------

RAM	PROMASTER CITY	2020-2021
-----	----------------	-----------

## Anti-Lock Brake System Module May Short Circuit

**NHTSA Campaign Number:** 21V160000

**Manufacturer** Hyundai Motor America

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 94,646

### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2015-2016 Genesis and 2017-2020 Genesis G80 vehicles. The Anti-Lock Brake System (ABS) module could malfunction and short circuit.

### **Remedy**

Hyundai will notify owners, and dealers will replace the ABS module fuse, free of charge. Owners are advised to park outside and away from structures until the remedy is complete. The recall is expected to begin May 7, 2021. Owners can contact Hyundai customer service at 1-855-371-9460. Hyundai's numbers for this recall are 201 and 006G.

### **Vehicles**

MAKE	MODEL	YEAR
------	-------	------

GENESIS	G80	2017-2020
---------	-----	-----------

HYUNDAI	GENESIS	2015-2016
---------	---------	-----------

## ABS and DSC Systems May Become Disabled

**NHTSA Campaign Number:** 21V167000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** SERVICE BRAKES, HYDRAULIC, ELECTRONIC STABILITY CONTROL

**Potential Number of Units Affected** 2,089

### **Summary**

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2020 Jaguar F-Type vehicles. The diagnostic check for the Anti-Lock Brake System (ABS) that runs at vehicle startup may not complete in the time required, which could disable the ABS and the Dynamic Stability Control (DSC) system during that drive cycle.

## Remedy

Jaguar will notify owners, and dealers will update the vehicle software, free of charge. The recall is expected to begin May 7, 2021. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H335.

## Vehicle

**MAKE MODEL YEAR**

JAGUAR F-TYPE 2020

## Occupant Detection System Malfunction/FMVSS 208

**NHTSA Campaign Number:** 21V164000

**Manufacturer** Kia Motors America

**Components** AIR BAGS

**Potential Number of Units Affected** 142

## Summary

Kia Motors America (Kia) is recalling certain 2021 Telluride, K5, and Forte vehicles. The Occupant Classification and Detection System (OCS/ODS) unit may not detect the presence of a child restraint system in the front passenger seat. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

## Remedy

Kia will notify owners, and dealers will replace the OCS/ODS unit, free of charge. The recall is expected to begin in March 2021. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC207.

## Vehicles

**MAKE MODEL YEAR**

KIA	FORTE	2021
KIA	K5	2021
KIA	TELLURIDE	2021

## Head Restraints Incorrect

**NHTSA Campaign Number:** 21V156000

**Manufacturer** BMW of North America, LLC

**Components** SEATS

**Potential Number of Units Affected** 258

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2021 X5 sDrive40i, X5 xDrive50i, X5 M50i, X5 xDrive45e, 2021 X7 xDrive40i, X7 M50i, and XB7 vehicles. The head restraints on the second-row outer seats may be the incorrect type for the vehicle.

### **Remedy**

BMW will notify owners, and dealers will inspect the head restraints, and replace them as necessary, free of charge. The recall is expected to begin May 3, 2021. Owners may contact BMW customer service at 1-800-525-7417.

### **Vehicles**

MAKE	MODEL	YEAR
------	-------	------

BMW	X5	2021
-----	----	------

BMW	X5 HYBRID	2021
-----	-----------	------

BMW	X7	2021
-----	----	------

BMW	XB7	2021
-----	-----	------

## Passenger Air Bag May Deploy Incorrectly

**NHTSA Campaign Number:** 21V159000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 3,388

### **Summary**

Volkswagen Group of America, Inc. (Audi) is recalling certain 2021 Audi RS6 Avant, RS7, 2020-2021 A6 Allroad, S6 Sedan, S7, 2019-2021 A6 Sedan, and A7 vehicles. The score line on the passenger air bag may not have been manufactured correctly.

## Remedy

Audi will notify owners, and dealers will inspect the passenger air bag score line, and repair it as necessary, free of charge. The recall is expected to begin May 7, 2021. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 70i2.

## Vehicles

MAKE	MODEL	YEAR
AUDI	A6	2019-2021
AUDI	A6 ALLROAD	2020-2021
AUDI	A7	2019-2021
AUDI	RS6	2021
AUDI	RS7	2021
AUDI	S6	2020-2021
AUDI	S7	2020-2021

## Lower Knee Air Bag Cushion Cover May Come Loose

**NHTSA Campaign Number:** 21V168000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 250

## Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2020 Range Rover Evoque vehicles. The cushion cover on the left-side lower knee air bag may come loose, which could result in the cushion unfolding from the air bag module housing.

## Remedy

Land Rover will notify owners, and dealers will replace the left-side lower knee air bag module, free of charge. The recall is expected to begin May 7, 2021. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N566.

## Vehicle

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER EVOQUE	2020

## Driver's Air Bag Inflator May Explode

**NHTSA Campaign Number:** 21V158000

**Manufacturer** Ford Motor Company

**Components** AIR BAGS

**Potential Number of Units Affected** 2,602,668

### **Summary**

Ford Motor Company (Ford) is recalling certain 2007-2011 Ranger, 2006-2012 Fusion, Lincoln Zephyr, Lincoln MKZ, 2006-2011 Mercury Milan, 2007-2010 Ford Edge, and Lincoln MKX vehicles. The driver's side air bag inflator may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling.

### **Remedy**

Ford will notify owners, and dealers will replace the driver-side airbag inflator or module with an alternate one, free of charge. The recall is expected to begin April 1, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S12.

### **Vehicles**

MAKE	MODEL	YEAR
FORD	EDGE	2007-2010
FORD	FUSION	2006-2012
FORD	RANGER	2007-2011
LINCOLN	MKX	2007-2010
LINCOLN	MKZ	2006-2012
LINCOLN	ZEPHYR	2006-2012
MERCURY	MILAN	2006-2011

## Driver's Air Bag Inflator May Explode

**NHTSA Campaign Number:** 21V162000

**Manufacturer** Mazda North American Operations

**Components** AIR BAGS

**Potential Number of Units Affected** 5,844

## Summary

Mazda North American Operations (Mazda) is recalling certain 2007-2009 B-Series pickup trucks. The driver's side air bag inflator may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, high temperatures, and high temperature cycling.

## Remedy

Mazda will notify owners, and dealers will replace the driver-side air bag inflator with an alternate one, free of charge. The recall is expected to begin May 9, 2021. Owners may contact Mazda customer service at 1-800-222-5500 option 4. Mazda's number for this recall is 4821C.

## Vehicle

MAKE	MODEL	YEAR
------	-------	------

MAZDA	B-SERIES TRUCK	2007-2009
-------	----------------	-----------

## Tire Failure may Cause Sudden Air Loss

**NHTSA Campaign Number:** 21V155000

**Manufacturer** Ford Motor Company

**Components** TIRES

**Potential Number of Units Affected** 15,769

## Summary

Ford Motor Company (Ford) is recalling certain 2018 F-150, 2018-2020 F-250, F-350, and 2019 Escape vehicles equipped with Continental tires. On the affected vehicles, it is possible that one or more tires were cured for too long during tire production.

## Remedy

Ford will notify owners, and dealers will inspect the tires, and replace them as necessary, free of charge. The recall is expected to begin March 29, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S10.

## Vehicles

MAKE	MODEL	YEAR
------	-------	------

FORD	ESCAPE	2019
------	--------	------

FORD	F-150	2018
------	-------	------

FORD	F-250 SD	2018-2020
------	----------	-----------

**MAKE MODEL YEAR**

FORD F-350 SD 2018-2020

**Tire Failure may Cause Sudden Air Loss**

**NHTSA Campaign Number:** 21V165000

**Manufacturer** Honda (American Honda Motor Co.)

**Components** TIRES

**Potential Number of Units Affected** 1,093

**Summary**

Honda (American Honda Motor Co.) is recalling certain 2019-2020 Passport and Pilot vehicles equipped with Continental tires. On the affected vehicles, it is possible that one or more tires were cured for too long during tire production.

**Remedy**

Honda will notify owners, and dealers will inspect all four tires and replace them as necessary, free of charge. The recall is expected to begin April 19, 2021. Owners may contact American Honda Motor Co. customer service at 1-888-234-2138. Honda's number for this recall is UA2.

**Vehicles****MAKE MODEL YEAR**

HONDA PASSPORT 2019-2020

HONDA PILOT 2019-2020

**Tire Failure may Cause Sudden Air Loss**

**NHTSA Campaign Number:** 21V169000

**Manufacturer** Nissan North America, Inc.

**Components** TIRES

**Potential Number of Units Affected** 126,809

## Summary

Nissan North America, Inc. (Nissan) is recalling certain 2019-2020 Altima and 2018-2021 Titan vehicles equipped with Continental tires. On the affected vehicles, it is possible that one or more tires were cured for too long during tire production.

## Remedy

Nissan will notify owners, and dealers will inspect the tires, and replace them as necessary, free of charge. The recall is expected to begin April 28, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PC798.

## Vehicles

MAKE	MODEL	YEAR
------	-------	------

NISSAN	ALTIMA	2019-2020
--------	--------	-----------

NISSAN	TITAN	2018-2021
--------	-------	-----------

## Transverse Link May Separate From Ball Joint

**NHTSA Campaign Number:** 21V170000

**Manufacturer** Nissan North America, Inc.

**Components** STEERING

**Potential Number of Units Affected** 15,223

## Summary

Nissan North America, Inc. (Nissan) is recalling certain 2020 Nissan Murano vehicles. The left and/or right-hand transverse link may not have been manufactured correctly, which could result in it separating from the ball joint.

## Remedy

Nissan will notify owners, and dealers will inspect the transverse link's lot codes, and if necessary, replace them and perform a vehicle alignment, free of charge. The recall is expected to begin April 21, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PC797.

## Vehicle

MAKE	MODEL	YEAR
------	-------	------

NISSAN	MURANO	2020
--------	--------	------

