



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest April 26, 2021

Steering Arm and Tie Rod Bolts May Fracture

NHTSA Campaign Number: 21V255000

Manufacturer Daimler Trucks North America, LLC

Components STEERING

Potential Number of Units Affected 1,738

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2021-2022 Thomas Built Buses Saf-T-Liner C2, Saf-T-Liner EFX, and Saf-T-Liner HDX school buses. The steering arm and tie rod bolts may have a defective seam that can fracture.

Remedy

DTNA will notify owners, and dealers will replace the tie rod arm bolts and steering arm, free of charge. The recall is expected to begin June 10, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-884.

Vehicles

MAKE	MODEL	YEAR
THOMAS BUILT BUSES	SAF-T-LINER C2	2021-2022
THOMAS BUILT BUSES	SAF-T-LINER EFX	2021-2022
THOMAS BUILT BUSES	SAF-T-LINER HDX	2021-2022

Steering Arm and Tie Rod Bolts May Fracture

NHTSA Campaign Number: 21V256000

Manufacturer Daimler Trucks North America, LLC

Components STEERING

Potential Number of Units Affected 17,822

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2021-2022 Freightliner Cascadia, Business Class M2, 114SD, 108SD, 122SD, Custom Chass S2 Chassis, Custom Chass XB Chassis, Custom Chass XC Chassis, and Custom Chass MT Chassis Western Star 4700, 4900, 5700 vehicles . The steering arm and tie rod bolts may have a defective seam that can fracture.

Remedy

DTNA will notify owners, and dealers will replace the tie rod arm and steering arm bolts, free of charge. The recall is expected to begin June 10, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-884.

Vehicles

MAKE	MODEL	YEAR
FCCC	MT45	2021-2022
FCCC	MT55	2021-2022
FCCC	S2	2022
FCCC	XB	2022
FCCC	XC CHASSIS	2021-2022
FREIGHTLINER	108SD	2021-2022
FREIGHTLINER	114SD	2021-2022
FREIGHTLINER	122SD	2021-2022
FREIGHTLINER	BUSINESS CLASS M2	2021-2022
FREIGHTLINER	CASCADIA	2021-2022
FREIGHTLINER	CUSTOM CHASS S2	2021
FREIGHTLINER	CUSTOM CHASS XB	2021
WESTERN STAR	4700	2021-2022
WESTERN STAR	4900	2021-2022
WESTERN STAR	5700	2021-2022

ECM Software May Cause Stall

NHTSA Campaign Number: 21V264000

Manufacturer Subaru of America, Inc.

Components ENGINE AND ENGINE COOLING, ELECTRICAL SYSTEM

Potential Number of Units Affected 466,205

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2017-2019 Subaru Impreza and 2018-2019 Crosstrek vehicles. The Engine Control Module (ECM) may continue to power the ignition coil after the engine is shut off, causing a short circuit.

Remedy

Subaru will notify owners, and dealers will update the ECM software, replace the ignition coils and, if necessary, the front exhaust pipe, free of charge. The recall is expected to begin May 28, 2021. Owners can contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is WRE-21. Note: This recall includes all vehicles previously repaired under Recall 19V743.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

SUBARU	CROSSTREK	2018-2019
--------	-----------	-----------

SUBARU	IMPREZA	2017-2019
--------	---------	-----------