



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

### Seat Back Recliners Improperly Welded

**NHTSA Campaign Number:** 21V302000

**Manufacturer** Hyundai Motor America

**Components** SEATS

**Potential Number of Units Affected** 1,464

#### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2021 Elantra vehicles. The driver and front passenger seat back recliners may have been improperly welded.

#### **Remedy**

Dealers will inspect and if necessary, replace the seat back frame assembly, free of charge. Owner notification letters are expected to be mailed June 25, 2021. Owners may contact Hyundai customer service at 1-888-371-9460. Hyundai's number for this recall is 204.

#### **Vehicle**

**MAKE MODEL YEAR**

HYUNDAI ELANTRA 2021

### Anti-Lock Brake System Module May Short

**NHTSA Campaign Number:** 21V303000

**Manufacturer** Hyundai Motor America

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 151,205

### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2013-2015 Santa Fe Sport vehicles. Brake fluid may leak inside the Anti-lock Brake System (ABS) module, possibly resulting in an electrical short.

### **Remedy**

Dealers will replace the ABS multi-fuse, and inspect and replace the ABS module, as necessary, free of charge. Owners are advised to park outside and away from structures as a precaution until the recall repair is complete. Owners notification letters are expected to be mailed June 25, 2021. Note: This recall includes all vehicles previously recalled under NHTSA recall number 20V-520. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 205.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

HYUNDAI	SANTA FE SPORT	2013-2015
---------	----------------	-----------

## **Roof Rail Covers May Detach**

**NHTSA Campaign Number:** 21V316000

**Manufacturer** Ford Motor Company

**Components** STRUCTURE

**Potential Number of Units Affected** 616,967

### **Summary**

Ford Motor Company (Ford) is recalling certain 2016-2019 Explorer vehicles. The retention pins could loosen and allow the roof rail covers to detach from the vehicle.

### **Remedy**

Dealers will install push-pins and replace any damaged rail clips and roof rail covers, as necessary, free of charge. Owner notification letters are expected to be mailed June 28, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21S22.

## Vehicle

**MAKE MODEL YEAR**

FORD EXPLORER 2016-2019

## Front Seat Belt Buckle Assembly Malfunction

**NHTSA Campaign Number:** 21V298000

**Manufacturer** BMW of North America, LLC

**Components** SEAT BELTS

**Potential Number of Units Affected** 12

### Summary

BMW of North America, LLC (BMW) is recalling certain 2021 330i, 330i xDrive, M340i, M3, and 330e xDrive vehicles. The bolt securing the seat belt assembly to the frame was not tightened to specification.

### Remedy

BMW will notify owners, and dealers will inspect the front seat belt buckle assembly connection and, if necessary, replace it, free of charge. The recall is expected to begin June 21, 2021. Owners may contact BMW customer service at 1-800-525-7417.

### Vehicles

**MAKE MODEL YEAR**

BMW 330E 2021

BMW 330I 2021

BMW M3 2021

BMW M340I 2021