



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest May 17, 2021

Missing Seat Heater May Prevent Air Bag Deployment

NHTSA Campaign Number: 21V318000

Manufacturer Porsche Cars North America, Inc.

Components SEATS, AIR BAGS

Potential Number of Units Affected 136

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2021 Cayenne GTS, Cayenne GTS Coupe, 2020-2021 Cayenne Coupe, Cayenne S Coupe, Cayenne E-Hybrid Coupe vehicles. The passenger seat back heating element was not installed and may impact the calibration of the Occupant Classification System.

Remedy

Dealers will install a heating element, free of charge. Owner notification letters are expected to be mailed June 27, 2021. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AMB0.

Vehicles

MAKE	MODEL	YEAR
PORSCHE	CAYENNE	2020-2021
PORSCHE	CAYENNE E-HYBRID	2020-2021
PORSCHE	CAYENNE GTS	2021
PORSCHE	CAYENNE S	2020-2021

Air May Reduce Effectiveness of Rear Brakes

NHTSA Campaign Number: 21V315000

Manufacturer Ducati North America

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 5,909

Summary

Ducati North America (Ducati) is recalling certain 2017-2020 Monster 797, Monster 1200, Supersport, 2016-2020 XDiavel, and 2018-2020 Monster 821 motorcycles. Air may permeate the rear brake system.

Remedy

Dealers will install new rear brake hoses, free of charge. Owner notification letters are expected to be mailed June 17, 2021. Owners may contact Ducati customer service at 1-888-391-5446.

Vehicles

MAKE	MODEL	YEAR
DUCATI	MONSTER 1200	2017-2020
DUCATI	MONSTER 797	2017-2020
DUCATI	MONSTER 821	2018-2020
DUCATI	SUPERSPORT	2017-2020
DUCATI	XDIAVEL	2016-2020

Rotor and Shaft May Separate Causing a Loss of ABS

NHTSA Campaign Number: 21V309000

Manufacturer Chrysler (FCA US, LLC)

Components SERVICE BRAKES, HYDRAULIC, SERVICE BRAKES, AIR

Potential Number of Units Affected 9

Summary

Chrysler (FCA US, LLC) is recalling certain 2019-2021 Alfa Romeo Stelvio and 2020-2021 Alfa Romeo Giulia vehicles. Hard braking may cause the Anti-Lock Brake System (ABS) Hydraulic Control Unit (HCU) rotor shaft to separate, a reduction of braking assist, and a loss of ABS.

Remedy

Dealers will replace the ABS HCU, free of charge. Owner notification letters are expected to be mailed June 23, 2021. Owners may contact FCA US LLC customer service at 1-800-853-1403.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

ALFA ROMEO	GIULIA	2020-2021
ALFA ROMEO	STELVIO	2019-2021

Seat Belt Retractors Spool Sleeve May Be Cracked

NHTSA Campaign Number: 21V314000

Manufacturer Arcimoto Inc

Components SEAT BELTS

Potential Number of Units Affected 255

Summary

Arcimoto Inc (Arcimoto) is recalling certain 2019-2021 FUV, 2020 Deliverator, 2021 Rapid Responder motorcycles. The seat belt retractor spool sleeve may be cracked, allowing broken pieces to block the seat belt from retracting.

Remedy

A service technician will replace the seat belt retractor, free of charge. Owner notification letters are expected to be mailed May 31, 2021. Owners may contact Arcimoto customer service at 1-541-683-6293.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

ARCIMOTO	DELIVERATOR	2020
ARCIMOTO	FUV	2019-2021
ARCIMOTO	RAPID RESPONDER	2021