



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest May 3, 2021

### Front Seat Movement May Trap Rear Passenger

The rear passenger may become trapped by the front seat without the ability to cancel the seat's movement, increasing the risk of injury.

**NHTSA Campaign Number:** 21V273000

**Manufacturer** Volvo Car USA, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 162

#### **Summary**

Volvo Car USA, LLC (Volvo Car) is recalling certain 2016-2020 XC90 Excellence vehicles. Liquid or condensation on the rear seat control display may cause the front passenger seat to move back as far as possible.

#### **Remedy**

Volvo Car will notify owners, and dealers will update the rear seat control display software, free of charge. The recall is expected to begin June 18, 2021. Owners may contact Volvo Car customer service at 1-800-458-1552. Volvo Car's number for this recall is R10093.

#### **Vehicle**

**MAKE MODEL YEAR**

VOLVO XC90 2016-2020

## Loose or Missing Side Curtain Air Bag Fastener

**NHTSA Campaign Number:** 21V280000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** AIR BAGS

**Potential Number of Units Affected** 2,721

### **Summary**

Chrysler (FCA US, LLC) is recalling certain 2020-2021 Dodge Durango vehicles. The Side Air Bag Inflatable Curtain (SABIC) fastener may be loose or missing.

### **Remedy**

Dealers will tighten or replace the fastener, free of charge. The recall is expected to begin June 11, 2021. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is Y16.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

DODGE	DURANGO	2020-2021
-------	---------	-----------

## TPMS May Misidentify the Affected Tire/FMVSS 138

**NHTSA Campaign Number:** 21V274000

**Manufacturer** Volkswagen Group of America, Inc.

**Components**

**Potential Number of Units Affected** 149

### **Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2021 Arteon vehicles. The Tire Pressure Monitoring System (TPMS) sensors were incorrectly calibrated and may not detect the position of a wheel sensor after tire rotation. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 138, "Tire Pressure Monitoring Systems."

## Remedy

Volkswagen will notify owners, and dealers will replace the wheel electronics and tire valves, free of charge. Owner notification letters are expected to be mailed June 18, 2021. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 44R2.

## Missing Internal Bushing In Brake Caliper

**NHTSA Campaign Number:** 21V286000

**Manufacturer** Nissan North America, Inc.

### Components

**Potential Number of Units Affected** 14,054

### Summary

Nissan North America, Inc. (Nissan) is recalling certain 2021 Rogue vehicles. The rear left and/or right brake caliper assemblies may be missing an internal bushing, allowing the O-ring seal to move and brake fluid to leak.

## Remedy

Dealers will inspect and replace the left and/or right rear brake calipers, as necessary, free of charge. Owner notification letters are expected to be mailed June 10, 2021. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PC804.

## Water Intrusion from AC Drain Hose May Cause Short

Water intrusion into the driver and passenger side foot wells may cause corrosion and/or short circuits to electrical components, increasing the risk of fire. In addition, the emergency call (eCall) feature may be disabled and the doors may not unlock, increasing the risk of injury. Also, the engine may not start or may enter a limp-home mode, increasing the risk of a crash.

**NHTSA Campaign Number:** 21V288000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** EQUIPMENT

**Potential Number of Units Affected** 6,331

### Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 AMG GLE 53, 2020 GLE350, GLE450, GLE580, GLS450, and GLS580 vehicles. The air conditioner drain hoses may have been incorrectly installed, causing water to drain into the passenger compartment.

## Remedy

Dealers will inspect and correct the air conditioner drain hoses, as necessary, free of charge. Owner notification letters are expected to be mailed on June 22, 2021. Owners may contact MBUSA customer service at 1-800-367-6372.

## Vehicles

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
MERCEDES-BENZ	AMG GLE53	2021
MERCEDES-BENZ	GLE350	2020
MERCEDES-BENZ	GLE450	2020
MERCEDES-BENZ	GLE580	2020
MERCEDES-BENZ	GLS450	2020
MERCEDES-BENZ	GLS580	2020